



PHASE I ENVIRONMENTAL SITE ASSESSMENT 17355 RAUPP ROAD AND 2700, 2704, AND 2750 OAKWOOD BOULEVARD MELVINDALE, MICHIGAN 48122

prepared for

DOWNRIVER AREA BROWNFIELD CONSORTIUM SOUTHGATE, MICHIGAN 48195

AKT PEERLESS PROJECT No. 5635F-1-17 SEPTEMBER 26, 2007



PHASE I ENVIRONMENTAL SITE ASSESSMENT 17355 RAUPP ROAD AND 2700, 2704, AND 2750 OAKWOOD BOULEVARD MELVINDALE, MICHIGAN 48122

prepared for

DOWNRIVER AREA BROWNFIELD CONSORTIUM SOUTHGATE, MICHIGAN 48195

AKT PEERLESS PROJECT No. 5635F-1-17 SEPTEMBER 26, 2007



TABLE OF CONTENTS (continued)

		4.4.1	Local Health Department	12
		4.4.2	Local Fire Department	12
		4.4.3	Water & Sewage Utility Provider	12
		4.4.4	Natural Gas Provider	13
		4.4.5	Previous Environmental Reports	13
	4.5		DRICAL USE INFORMATION	
	· ·	4.5.1	Aerial PhotographsFire Insurance Maps	16
, ×		4.5.2	Fire Insurance Maps	17
		4.5.3	City Directories	
		4.5.4	Assessing Department Records	19
		4.5.5	Building Department Records	19
5.0	INTE	RVIEW	/S	19
	5.1	INTER	RVIEWS WITH SUBJECT PROPERTY OWNERS AND MANAGE	RS .19
	5.2	INTER	RVIEWS WITH OTHERS	20
6.0	SHRI	FCT DI	ROPERTY RECONNAISSANCE	20
0.0	6.1		ODOLOGY AND LIMITING CONDITIONS	
	6.2		RAL SUBJECT PROPERTY SETTING AND OPERATIONS	
	6.3		RVATIONS	
	0.3			
		6.3.1	Hazardous Substances and Petroleum Products	
		6.3.2	Hazardous and Non-Hazardous Waste	
		6.3.3	Storage Tanks.	
		6.3.4	Unidentified Substances/Containers	
		6.3.5	Potential PCB Containing Equipment	
		6.3.6 6.3.7	Interior Staining / Corrosion	
		6.3.8	Drains and Sumps	
		6.3.9		
			Pits, Ponds, and Lagoons	
			Stained Soil, Stressed Vegetation, Stressed/Stained Pavement	
			Well and Septic Systems	
			Other Observations	
	6.4		ASTM SCOPE CONSIDERATIONS	
	o. r	6.4.1	Suspect Asbestos Sources	
		ac rt≎	en defive on many angeles and and see months and many and	~ * * * * * * * * * * * * * * * * * * *
7.0	CONC	CLUSIC	ONS AND RECOMMENDATIONS	23



TABLE OF CONTENTS

1.0	0 INTRODUCTION			
	1.1	PURPOSE	1	
	1.2	SCOPE OF SERVICES]	
	1.3	PROJECT RESOURCES	2	
	1.4	SIGNIFICANT ASSUMPTIONS	2	
X. Y	1.5	LIMITATIONS AND EXCEPTIONS	2	
	1.6	LIMITATIONS AND EXCEPTIONS	3	
	1.7	USER RELIANCE		
2.0	USER	R AND/OR CLIENT PROVIDED INFORMATION	7	
	2.1	TITLE RECORDS		
	2.2	ENVIRONMENTAL LIENS OR ACTIVITY AND USE LIMITATIONS		
	2.3	KNOWLEDGE OF THE USER		
	2.4	VALUATION REDUCTION FOR ENVIRONMENTAL ISSUES		
	2.5	REASON FOR PERFORMING THIS PHASE I ESA		
3.0	SUBJ	ECT PROPERTY DESCRIPTION	4	
	3.1	LOCATION AND LEGAL DESCRIPTION	4	
	3.2	SUBJECT PROPERTY AND VICINITY CHARACTERISTICS	5	
	3.3	DESCRIPTION OF STRUCTURES AND OTHER IMPROVEMENTS	5	
	3.4	CURRENT USE OF THE SUBJECT PROPERTY	6	
	3.5	UTILITIES AND MUNICIPAL SERVICES	7	
	3.6	CURRENT USES OF THE ADJOINING PROPERTIES	7	
4.0	RECO	ORDS REVIEW	Q	
		PHYSICAL SETTING SOURCES		
		4.1.1 Topography and Area Hydrogeology		
		4.1.2 Area Geology and Soils		
	4.2	STANDARD ENVIRONMENTAL RECORD SOURCES		
		4.2.1 Subject Property and Occupant Listings		
		4.2.2 Adjoining and Nearby Sites		
	4.3	ENVIRONMENTAL RECORD SOURCES		
		4.3.1 MDEQ Waste and Hazardous Material Division (WHMD) Records	11	
		4.3.2 MDEQ Remediation and Redevelopment Division (RRD) Records	12	
	4.4	ADDITIONAL ENVIRONMENTAL RECORD SOURCES	12	



TABLE OF CONTENTS (continued)

	7.1	RECOGNIZED ENVIRONMENTAL CONDITIONS	23
	7.2	HISTORICAL RECOGNIZED ENVIRONMENTAL CONDITIONS	24
	7.3	POTENTIAL AREAS OF CONCERN AND SIGNIFICANT DATA GAPS	24
8.0		IATIONS	
9.0	SIGN	NATURES OF ENVIRONMENTAL PROFESSIONALS	25
QUA	LIFIC	ATIONS	
FIGU	RES		
Figure	e 1		ap
Figure	2	Topographic Location M	ap
Figure	3	Parcel M	ap
Figure	e 4		ap
APPE	NDIC	<u>ES</u>	
Apper	ndix A.	General Limitations and Exceptio	ns
Apper	ndix B.	Legal Descripti	on
Apper	ndix C.		hs
Apper	ndix D.	Standard Environmental Record Database Repo	ort
Appen	ndix E .		on
Appen	ndix F	Sanborn Fire Insurance Ma	ps
Appen	ıdix G.		on
Appen	ndix H.	Previous Environmental Repo	rts



PHASE I ENVIRONMENTAL SITE ASSESSMENT

17355 RAUPP ROAD AND 2700, 2704, AND 2750 OAKWOOD BOULEVARD MELVINDALE, MICHIGAN 48122

AKT PEERLESS PROJECT No. 5635F-1-17

1.0 <u>INTRODUCTION</u>

The Downriver Area Brownfield Consortium (the Client and User) retained AKT Peerless Environmental Services (AKT Peerless) to conduct a Phase I Environmental Site Assessment (ESA) of 17355 Raupp Road and 2700, 2704, and 2750 Oakwood Boulevard in the City of Melvindale, Wayne County, Michigan (subject property). This Phase I ESA was conducted in accordance with the guidelines established by the American Society for Testing and Materials (ASTM) in the Standard Practice for Environmental Site Assessments: Phase I Environmental Site Assessment Process / Designation E 1527-05 (ASTM Standard Practice E 1527-05).

1.1 PURPOSE

The purpose of this Phase I ESA was to evaluate the current and historical conditions of the subject property in an effort to identify *recognized environmental conditions* (RECs)¹ and *historical recognized environmental conditions* (HRECs)² in connection with the subject property. Moreover, certain users of this Phase I ESA may be able to satisfy one of the environmental due diligence requirements to qualify for the bona fide prospective purchaser, contiguous landowner, or innocent landowner liability protections available under the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) of 1980, the Superfund Amendments and Reauthorization Act (SARA) of 1986, and the Small Business Liability and Brownfield Revitalization Act (Brownfield Amendments) of 2002. This Phase I ESA is intended to reduce, but not eliminate, uncertainty regarding the potential for RECs and HRECs in connection with the subject property.

1.2 SCOPE OF SERVICES

AKT Peerless' scope-of-services is based on its proposal PF-8255 dated August 20, 2007, and the terms and conditions of that agreement. This Phase I ESA included the following:

¹ ASTM's Standard Practice E 1527-05 defines the term recognized environmental condition (REC) as the presence or likely presence of any hazardous substance or petroleum product on a property under conditions that indicate (1) an existing release, (2) a past release, or (3) a material threat of a release of a hazardous substance or petroleum product into structures on the subject property or into the ground, groundwater, or surface water of the subject property.

² ASTM defines the term historical recognized environmental condition (HREC) as an environmental condition which in the past would have been considered an REC, but which may or may not be considered an REC currently. Neither HRECs nor RECs are intended to include *de minimis* conditions that generally do not present a material risk of harm to public health or the environment and would not be the subject of an enforcement action if brought to the attention of appropriate governmental agencies.



- an inquiry of environmental conditions by an environmental professional.
- a review of specialized knowledge reported by the Client.
- a review of public and historical records, including those maintained by federal, state, tribal, and local government agencies.
- interviews with regulatory officials and personnel associated or knowledgeable with the subject property, including as appropriate past and present owners, or neighbors if the property is abandoned.
- a reconnaissance of the subject property and adjoining properties.

1.3 PROJECT RESOURCES

AKT Peerless referred to the following resources between August 20, 2007 and September 26, 2007 to complete its ESA:

- United States Environmental Protection Agency (USEPA), Region 5
- United States Geological Survey (USGS)
- United States Department of Agriculture (USDA) Soil Conservation Service
- Michigan Department of Environmental Quality (MDEQ)
- Wayne County Environmental Health Department
- City of Melvindale Government Sources (e.g., assessing, building, fire, engineering departments, etc.)
- Environmental Data Resources, Inc. (EDR)
- Bresser's
- Terraserver
- Interviews and Questionnaire Responses

1.4 SIGNIFICANT ASSUMPTIONS

During this Phase I ESA, AKT Peerless made the following significant assumptions:

- AKT Peerless assumed that the information provided by EDR in the regulatory database report is an accurate and complete representative summary of the information contained in the referenced regulatory agency records, except when such information is obviously contradicted by other data.
- AKT Peerless assumed that the information used to prepare this assessment that was obtained from ostensibly knowledgeable individuals, regulatory agency representatives, or other secondary sources was an accurate and complete representative summary of the information possessed by those individuals, representatives, or sources.

1.5 LIMITATIONS AND EXCEPTIONS

A list of general limitations and exceptions typically encountered when completing Phase I ESAs is provided in Appendix A. Along with the inherent limitations set forth in various sections of ASTM Standard Practice E 1527-05, the accuracy and completeness of this report may also be



limited by the following project specific facts or conditions:

- AKT Peerless was not provided access to the subject building located at 2700 Oakwood Boulevard and was only provided partial access to the subject building located at 2704 Oakwood Boulevard.
- Due to data failure, AKT Peerless was unable to obtain specific information about the utilities associated with the subject property.

Subject to the general limitations and exceptions listed in Appendix A and the referenced terms and conditions, AKT Peerless accepts responsibility for the competent performance of its duties in executing this assignment and preparing this report in accordance with the normal standards of the profession, but disclaims any responsibility for consequential damages.

Should additional information become available to the Client that differs significantly from our understanding of conditions presented in this report, AKT Peerless requests that such information be forwarded immediately to our attention so that we may reassess the conclusions provided herein and amend this project's scope of services as necessary and appropriate.

1.6 SPECIAL TERMS AND CONDITIONS

To the best of AKT Peerless' knowledge, no special terms or conditions apply to the preparation of this Phase I ESA.

1.7 USER RELIANCE

AKT Peerless performed this Phase I ESA for the benefit of the Client and Mr. Nick Patel. AKT Peerless acknowledges that these parties may rely on the contents and conclusions presented in this report. Unless stated otherwise in writing, AKT Peerless makes no other warranty, representation, or extension of reliance upon the findings of this report to any other entity or third party.

2.0 USER AND/OR CLIENT PROVIDED INFORMATION

The following subsections summarize the information that Mr. Nick Patel, property owner, provided to AKT Peerless.

2.1 TITLE RECORDS

The Client did not provide recorded land title records to AKT Peerless.

2.2 ENVIRONMENTAL LIENS OR ACTIVITY AND USE LIMITATIONS

The Client did not report any: (1) environmental cleanup liens against the subject property that are filed or recorded under federal, tribal, state, or local law; or (2) activity and use limitations (AULs), such as engineering controls, land use restrictions or institutional controls, that are in place at the subject property and/or have been filed or recorded in a registry under federal, tribal, state, or local law.



2.3 KNOWLEDGE OF THE USER

The Client did not report specialized knowledge or experience, actual knowledge, or commonly known or reasonable ascertainable information that is material to identifying recognized environmental conditions in connection with the subject property. Mr. Nick Patel, property owner of Parcel A, provided AKT Peerless with a copy of the following report, which documents a previous environmental investigation of the 17355 Raupp Road property:

 Transaction Screen Environmental Site Assessment, prepared in August 2004 by Northern Environmental on behalf of The National Republic Bank of Chicago

The contents of the previous environmental report is summarized and discussed in Section 4.4.5. Refer to Appendix H for a copy of the referenced report.

2.4 VALUATION REDUCTION FOR ENVIRONMENTAL ISSUES

The Client did not report knowledge of, or reason to anticipate, a reduction in the value of the subject property for environmental issues.

2.5 REASON FOR PERFORMING THIS PHASE I ESA

According to the Client, this Phase I ESA was conducted as part of environmental due diligence related to financing and redevelopment of the subject property.

3.0 SUBJECT PROPERTY DESCRIPTION

3.1 LOCATION AND LEGAL DESCRIPTION

The subject property is located in Section 59 (T.2S., R.11E.) in Melvindale, Wayne County, Michigan. The subject property is situated west of Raupp Road and north of Oakwood Boulevard. It consists of 11 rectangular shaped parcels that contain approximately 1.3 acres.

Mr. Nick Patel is the current owner and manager of the 17355 Raupp Road property, which is occupied by the Motor City Motel. Mr. Patrick Riley is the current owner of the 2700 and 2704 Oakwood Boulevard properties. 2700 Oakwood Boulevard is currently unoccupied and 2704 Oakwood Boulevard is currently occupied by Jake's Cross Roads Bar & Grill. Mr. Luke Walkuski is the current owner of the 2750 Oakwood Boulevard property, which is currently utilized for home improvement activities and storage. The following table presents additional information regarding the subject property. For ease of reference in this report, AKT Peerless has designated each of the subject property addresses with a letter. These designations have no relevance to legally recorded data about the subject property.

Parcel	Address	Tax Identification Number	Owner of Record	Approximate Acreage
A	17355 Raupp Road	47-006-01-0072-000 (Lots 72-80) 47-006-01-0072-000 (Lots 81-85)	Nick Patel	0.7
В	2700 Oakwood Boulevard	47-006-01-0071-000 (Lot 71)	Patrick Riley	0.05



Parcel	Address	Tax Identification Number	Owner of Record	Approximate Acreage
С	2704 Oakwood Boulevard	47-006-01-00245-000 (Lots 245-246) 47-006-01-00247-000 (Lot 247) 47-006-01-00248-000 (Lot 248) 47-006-01-00249-000 (Lot 249) 47-006-01-00250-000 (Lot 250) 47-006-01-00251-000 (Lot 251) 47-006-01-00252-000 (Lot 252)	Patrick Riley	0.4
D	2750 Oakwood Boulevard	47-006-01-00247-301 (Lots 253-255)	Luke Walkuski	0.13

Refer to Figure 1, Subject Property Location Map; Figure 2, Topographic Location Map; Figure 3, Parcel Map; and Figure 4, Subject Property Map. The legal descriptions of the subject property are presented in Appendix B. Photographs taken during AKT Peerless' subject property reconnaissance are provided in Appendix C.

3.2 SUBJECT PROPERTY AND VICINITY CHARACTERISTICS

Parcel A is currently developed with a 23-unit motel, Parcel B is currently developed with a vacant commercial building, Parcel C is currently developed with a restaurant/bar with a second story apartment unit, and Parcel D is currently developed with a commercial building utilized for storage and home improvement activities. The subject property is located in an area of Melvindale that is characterized by commercial and residential properties, and surface roadways.

3.3 DESCRIPTION OF STRUCTURES AND OTHER IMPROVEMENTS

General information regarding the on-site buildings (the subject buildings) is presented in the following table:

Building 1: 17355 Raupp Road (Parcel A)						
General Construction	Interior Finish:	Square Ft.	Construction and Other Improvement Dates			
1-story; composition roof; wood roof joists and deck; concrete block bearing walls; slab-on-grade concrete foundation; concrete block, brick, and wood exterior; no basement	plaster, resilient floor tiles (RFTs), carpet, ceramic tile, paint, wood, metal, glass, etc.	~ 8,267 SF (total)	constructed in 1952 with a building addition in 1956			

Building 1 consists of a 23 unit motel with two boiler/mechanical rooms and an office area. The exterior of Parcel A is improved with paved and landscaped areas.



Building 2: 2700 Oakwood Boulevard (Parcel B)						
General Construction	Interior Finish:	Square Ft.	Construction and Other Improvement Dates			
1-story; flat roof; wood roof joists and deck; concrete block bearing walls; concrete block and brick exterior; unknown if basement	unknown	~ 800 SF (total)	constructed prior to 1937			

Building 1 consists of a vacant commercial building. AKT Peerless was not provided access to the interior of Building 2. The exterior of Parcel B is improved with paved areas.

Building 3: 2704 Oakwood Boulevard (Parcel C)					
General Construction	Interior Finish:	Square Ft.	Construction and Other Improvement Dates		
2-story; flat roof; wood roof joists and deck; brick bearing walls and exterior; basement	Main Floor - plaster, RFTs, acoustical ceiling tiles (ACTs), paint, wood, metal, glass, etc. Second Floor - AKT Peerless was not provided access	~ 5,080 SF (total)	constructed in 1929		

The main floor of Building 3 consists of a restaurant/bar area and restrooms. AKT Peerless was not provided access to the basement or second floor of Building 3. The exterior of Parcel C is improved with paved areas.

Building 4: 2750 Oakwood Boulevard (Parcel D)					
General Construction	Interior Finish:	Square Ft.	Construction and Other Improvement Dates		
2-story; flat roof; wood roof joists and deck; concrete block bearing walls; concrete block and brick exterior; partial basement	drywall, RFTs, concrete, concrete block, paint, wood, metal, glass, etc	~ 2,518 SF (total)	constructed in 1945		

Building 4 consists of a commercial building utilized for home improvement activities and storage. The main floor consists of a sales area, storage/garage area, and restrooms, the second floor consists of a vacant apartment unit, and the basement is utilized for storage. The exterior of Parcel D is improved with paved areas.

3.4 CURRENT USE OF THE SUBJECT PROPERTY

Parcel A is currently operated as a motel and is occupied by the Motor City Motel. Parcel B is not used for any significant or obvious purpose. Parcel C is currently operated as a restaurant/bar (occupied by Jake's Crossroads Bar & Grill) with a second story residential flat. Parcels D is utilized for home improvement activities and storage. The subject property is zoned General Commercial (C-2) and Multifamily Residential (R-3). Past uses of the subject property



are discussed in Section 4.5. Refer to Appendix C for photographs of the property taken during AKT Peerless' property reconnaissance.

3.5 UTILITIES AND MUNICIPAL SERVICES

AKT Peerless identified the type and supplier of utilities provided to the subject property. These services are described in the following table:

Utility / Service	Туре	Utility Company or Municipality	Comments/Historical Services
heat	natural gas	DTE Energy	natural gas is currently is provided to the subject property / historical services have included hot water and/or steam
municipal waste	general refuse	Waste Management	none identified
potable water	municipal	City of Melvindale	municipal drinking water has been provided since development in 1929
electricity	electric lines	DTE Energy	electricity has been provided since development in 1929
sewage disposal	municipal	City of Melvindale	municipal sewage utilities have been provided since at least 1963 / historical services not identified

Additional information regarding the referenced heat, water, and sewage utilities is presented in Section 4.4.

3.6 CURRENT USES OF THE ADJOINING PROPERTIES

The following table describes the current uses of the adjoining properties, identified occupants, and noteworthy observations of environmental concern, if any, that were noted during AKT Peerless' recent reconnaissance of the adjoining properties.

Direction	Address	Current Use / Occupant	Potential Concerns
north	17301 Raupp Road	residential / Hayvar Senior Apartments	none observed
east	17250 Raupp Road	residential / Rauppdale Apartments	none observed
east	2630 Oakwood Boulevard	commercial / Wendys	none observed
south	2661 Oakwood Boulevard	commercial / Metro Mart	gasoline station
south	17431 Dix Road	commercial / White Castle	none observed
	2760 Oakwood Boulevard	commercial / Buhay Services and Supply Company	none observed
west	Eddon Street	apartments	none observed
	Eddon Street	single-family residential dwellings	none observed

Based on AKT Peerless' visual observations, the current uses of the adjoining properties do not appear to pose a direct environmental threat to the subject property, except for the southern adjoining gasoline station (2661 Oakwood Boulevard). Additional information about the potential environmental threat posed by this use is presented in Section 4.2.2.



4.0 RECORDS REVIEW

The objective of the records review is to evaluate reasonably ascertainable databases, historical records, and physical setting records to help identify recognized environmental conditions at the subject property and, to the extent identifiable, at surrounding properties.

4.1 PHYSICAL SETTING SOURCES

AKT Peerless reviewed geological survey maps for geologic, hydrologic, and topographic conditions that may affect potential contaminant migration to the subject property.

4.1.1 Topography and Area Hydrogeology

According to the USGS' *Topographic Map of the Dearborn Quadrangle*, which was published in 1968 and was photorevised in 1983, the subject property is situated between 590 and 585 feet above the National Geodetic Vertical Datum (NGVD). The subject property's topography appears relatively flat.

AKT Peerless did not obtain or review reports that document actual groundwater conditions at or adjacent to the subject property. Therefore, AKT Peerless was unable to (1) identify the depth to shallow groundwater beneath the subject property, or (2) determine the groundwater flow direction beneath the subject property.

Typically, the water table aquifer flows toward a major drainage feature or in the same direction as the drainage basin. River Rouge, which flows to the southeast before joining the Detroit River, is located approximately ½ mile north of the subject property. Therefore, AKT Peerless infers that groundwater beneath the subject property flows to the southeast, with potential influence from River Rouge.

AKT Peerless' research did not identify any known groundwater recharge area on or near the subject property, or any groundwater supply or monitor wells on the subject property. Groundwater from the area of the subject property does not serve as the primary drinking water source for properties in Melvindale, which obtains its municipal water from the Detroit Water & Sewerage Department (DWSD). Public sources of information do not identify main aquifers below the subject property.

4.1.2 Area Geology and Soils

According to the MDNR Geological Survey Division's *Bedrock Geology of Southern Michigan* (1987), bedrock beneath the subject property is classified as Dundee Limestone of an unassigned group, which is included in the Erian Series within the Devonian System of the Paleozoic Era. The depth to bedrock beneath the subject property was not readily available prior to the completion of this Phase I ESA.

According to the Michigan Geological Survey Division's publication, *Quaternary Geology of Southern Michigan* (1982), soil in the subject property area is defined as lacustrine sand and gravel. This soil is described as pale brown to pale reddish brown, fine to medium sand, commonly including beds or lenses of small gravel. This soil occurs chiefly as former beach and



near-offshore littoral deposits of glacial Great Lakes and may include intercalated lacustrine clay. Soil thickness ranges from 3 to 100 feet. Typically, lacustrine sand and gravel are associated with moderate hydraulic permeability and may allow the movement of contaminants through groundwater.

According to the USDA's *Soil Survey of Wayne County, Michigan* (1977), soil at the subject property is classified as belonging to the Hoytville-Nappanee association, which is described as nearly level and gently sloping, very poorly drained and somewhat poorly drained soils that have a fine textured subsoil.

AKT Peerless did not obtain other information about the subject property's soil during this Phase I ESA.

4.2 STANDARD ENVIRONMENTAL RECORD SOURCES

AKT Peerless retained EDR to provide current environmental database information compiled by a variety of federal and state regulatory agencies. The purpose of obtaining this data was to evaluate potential environmental risks associated with the subject property, adjoining sites, and other sites that are (1) identified on target lists, and (2) within varying distances of up to one mile from the subject property. AKT Peerless reviewed the following federal and state databases for such listings within the indicated search radii.

Туре	Regulatory Agency Database	Approximate Minimum Search Distance
Federal	National Priority List (NPL)	1 mile
Federal	De-listed National Priority List (DNPL)	½ mile
Federal	Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS)	½ mile
Federal	CERCLIS No Further Remediation Action Planned (NFRAP) Site List	½ mile
Federal	Resource Conservation and Recovery Act (RCRA) Corrective Action Report (CORRACTS) Facilities List	1 mile
Federal	RCRA non-CORRACTS Treatment, Storage or Disposal (TSD) Facilities List	½ mile
Federal	RCRA Generators List	subject property and adjoining properties
Federal	Institutional Control / Engineering Control Registries*	subject property
Federal	Environmental Response and Notification System (ERNS)	subject property
State & Tribal	Hazardous Waste Sites (HWS) (equivalents to NPL and CERCLIS)	1 mile
State & Tribal	Solid Waste Facilities/Landfill Sites (SWLF)	½ mile
State & Tribal	Historical Landfill Site (HIST LF)	½ mile
State & Tribal	Leaking Underground Storage Tank (LUST) List	½ mile



Туре	Regulatory Agency Database	Approximate Minimum Search Distance
State & Tribal	Registered Underground Storage Tank (UST) List	subject property and adjoining properties
State & Tribal	Institutional Control / Engineering Control Registries*	subject property
State & Tribal	Brownfield Sites	½ mile
State	Baseline Environmental Assessment (BEA) Sites	½ mile
Either	Unmappable Database Listings (a.k.a. Orphan Sites)	database-dependent

^{*} Neither the US EPA nor Michigan Tribal Governments nor the State of Michigan maintains registries of sites with Institutional Controls / Engineering Controls in the subject property area.

4.2.1 Subject Property and Occupant Listings

The EDR Report (Appendix D) does not identify the subject property or its known occupants on the referenced databases, except for the following:

• D and K Starter and Alternator, at 2750 Oakwood Boulevard (former property occupant), was identified on the federal RCRA-SQG database. This database includes facilities that generate (or have generated) between 100 and 1,000 kilograms of hazardous waste per calendar month. According to the EDR Report, this occupant had not reported treatment, storage, or disposal (TSD) activities, and had no reported RCRA violations. This former occupant was also identified on the federal Facility Index System (FINDS) database. This database identifies facilities that are contained on one or more other federal databases (RCRA-SQG).

Additional information about the presence of this former occupant on the referenced databases is presented in Section 4.3.1.

4.2.2 Adjoining and Nearby Sites

AKT Peerless' review of the referenced databases (including those on the orphan list) also considered the potential or likelihood of contamination from adjoining and nearby sites. To evaluate which of the adjoining and nearby sites identified in the EDR Report present an environmental risk to the subject property, AKT Peerless considered the following criteria:

- the type of database on which the site is identified.
- the topographic position of the identified site relative to the subject property.
- the direction and distance of the identified site from the subject property.
- local soil conditions in the subject property area.
- the known or inferred groundwater flow direction in the subject property area.
- the status of the respective regulatory agency-required investigation(s) of the identified site, if any.



 surface and subsurface obstructions and diversions (e.g., buildings, roads, sewer systems, utility service lines, rivers, lakes, and ditches) located between the identified site and the subject property.

Only those sites that are judged to present a potential environmental risk to the subject property are further evaluated by reviewing MDEQ file information. Using the referenced criteria, and based upon a review of readily available information contained within the EDR Report, AKT Peerless did not identify adjoining (i.e., bordering) or nearby sites (e.g., properties within a ¼-mile radius) listed in the EDR Report that were judged to present a potential environmental risk to the subject property, except for the following:

Database(s):	UST	Distance:	adjoining
Name:	Petron Inc	Direction:	south
Address:	2661 Oakwood Boulevard	Elevation:	587 feet
Section References:	none	Known/Inferred Groundwater Flow Direction:	southeast

Petron Inc is identified as the owner of three gasoline USTs, one diesel fuel UST, and one kerosene UST that were installed in 1991 and are currently in use. Specific data about these USTs is presented in the EDR Report. In AKT Peerless' opinion, this southern adjoining property, beyond Oakwood Boulevard, does not present an environmental concern to the subject property based on (1) a release from the USTs has not been reported, (2) no obvious improper waste generation or storage was observed on this adjoining property during AKT Peerless' property reconnaissance, (3) the distance of the site across Oakwood Boulevard (~100 feet), and (4) the apparent groundwater flow direction in a southeasterly direction and away from the subject property.

4.3 ENVIRONMENTAL RECORD SOURCES

4.3.1 MDEQ Waste and Hazardous Material Division (WHMD) Records

Subject Property

AKT Peerless contacted the MDEQ WHMD to review available records regarding waste management activities, permits, inspections, violations, and registered USTs associated with the subject property. According to the WHMD, records were not available for the subject property.

AKT Peerless referenced the WHMD Waste Data System (WDS) for information regarding the subject property. The WDS tracks activities at facilities regulated by the Solid Waste, Scrap Tire, Hazardous Waste, and Liquid Industrial Waste programs. According to the WDS, 2750 Oakwood Boulevard (Parcel D) is identified as D and K Starter and Alternator (former occupant). According to the WDS, the business is no longer generating. No further information was provided by the WDS. Refer to Appendix G for a copy of the WDS information.

2760 Oakwood Boulevard

AKT Peerless contacted the MDEQ WHMD to review available records regarding waste management activities, permits, inspections, violations, and registered USTs associated with this western adjoining property. According to the WHMD, records were not available for this property. AKT Peerless also referenced the WDS for information regarding this western adjoining property. This adjoining site was not identified in the WDS database. Refer to Section



4.5 for further information pertaining to this site.

4.3.2 MDEQ Remediation and Redevelopment Division (RRD) Records

Subject Property

AKT Peerless reviewed the RRD's Perfected Lien List to determine if environmental cleanup liens had been filed against the subject property. According to the most recent list that was published on July 17, 2007, the MDEQ does not have record of environmental cleanup liens filed against the subject property.

The RRD denied AKT Peerless' recent request for RRD records pertaining to the subject property indicating that no records exist under the name given or another name reasonably known to the public body.

2760 Oakwood Boulevard

The RRD denied AKT Peerless' recent request for RRD records pertaining to this western adjoining property indicating that no records exist under the name given or another name reasonably known to the public body. Refer to Section 4.5 for further information pertaining to this site.

4.4 ADDITIONAL ENVIRONMENTAL RECORD SOURCES

4.4.1 Local Health Department

Subject Property

The Wayne County Health Department indicated that they do not have records pertaining to the subject property.

2760 Oakwood Boulevard

The Wayne County Health Department indicated that they do not have records pertaining to this western adjoining property. Refer to Section 4.5 for further information pertaining to this site.

4.4.2 Local Fire Department

Subject Property

According to Fire Chief Scott Wellman of the Melvindale Fire Department, available records did not indicate the presence of storage tanks, incident reports, or other issues of potential environmental concern associated with the subject property.

2760 Oakwood Boulevard

According to Fire Chief Scott Wellman of the Melvindale Fire Department, available records did not indicate the presence of storage tanks, incident reports, or other issues of potential environmental concern associated with this western adjoining property. Refer to Section 4.5 for further information pertaining to this site.

4.4.3 Water & Sewage Utility Provider

The Melvindale Public Works Department has provided municipal drinking water services to the subject property since development in 1929 and municipal sewerage services since at least 1963



(oldest available sewer permit). The Melvindale Public Works Department's sanitary waste is ultimately received for processing by the City of Detroit Water & Sewerage Department (DWSD).

Information regarding sewage services was limited for the subject property. This gap in historical information is considered *data failure* as provided in Section 7.3.2.3 of the ASTM Standard Practice For ESAs (E 1527). Therefore, a potential exists for abandoned septic systems to be present at the subject property.

4.4.4 Natural Gas Provider

DTE Energy currently provides natural gas to the subject property; however, connection dates are unknown. Historical heating services have included hot water and/or steam. Information regarding historical heating systems was limited for the subject property. This gap in historical information is considered *data failure* as provided in Section 7.3.2.3 of the ASTM Standard Practice For ESAs (E 1527). Therefore, a potential exists for abandoned heating oil tanks to be present at the subject property.

4.4.5 Previous Environmental Reports

Mr. Nick Patel, property owner, provided AKT Peerless with a copy of the following report, which documents a previous environmental investigation of Parcel A (Appendix H):

• <u>Transaction Screen Environmental Site Assessment</u>, prepared in August 2004 by Northern Environmental on behalf of The National Republic Bank of Chicago

At the time of Northern Environmental's assessment, the subject property consisted of a motel. Northern Environmental did not identify environmental concerns associated with the subject property, with the exception of an unknown pipe located just west of the subject building. Northern Environmental recommend that further environmental investigation be conducted to evaluate the presence of the unknown pipe.

During AKT Peerless' property reconnaissance activities on September 4, 2007, AKT Peerless observed this pipe and determined that it was a sewer cleanout line. Therefore, further investigation of this pipe is not warranted.

AKT Peerless was not provided with copies of other reports that document previous investigations or assessments of the subject property, nor did AKT Peerless identify the existence of such documents during this assessment.

4.5 HISTORICAL USE INFORMATION

The objective of reviewing historical sources is to: (1) develop a history of previous uses or specific occupancies of the subject property, (2) identify those uses or specific occupancies that are likely to have led to potential environmental concerns at the subject property, and to the extent identifiable, at adjoining properties, and (3) identify obvious uses of the subject property from the present, back to the property's *obvious* first developed use, or back to 1940, whichever is earlier.



Historical Summary - Subject Property

The following table summarizes the general development and use of the subject property, as identified by AKT Peerless.

Time Period	Improvements	Use	Owner / Occupant	Data Source(s)
c. 1929 – c. 1945	Parcel A – none Parcel B – building and garage Parcel C – building, garage, and parking areas Parcel D - none	Parcel A – none apparent Parcel B – commercial Parcel C – commercial and residential Parcel D - none	Parcels A, B, C, D – unknown	municipal records aerial photographs Sanborn Fire Insurance Maps interviews
c. 1945 – c. 1952	Parcel A – none Parcel B – building Parcel C – building, garage, and parking areas Parcel D – building and parking areas	Parcel A – none apparent Parcel B – commercial Parcel C – commercial and residential Parcel D - commercial	Parcel A – unknown Parcel B – unknown Parcel C – unknown Parcel D – unknown	municipal records aerial photographs Sanborn Fire Insurance Maps interviews
c. 1952 – c. 1956	Parcel A – building and parking areas Parcel B – building Parcel C – building, garage, and parking areas Parcel D – building and parking areas	Parcel A – motel Parcel B – commercial Parcel C – commercial and residential Parcel D - commercial	Parcel A – Motor City Motel Parcel B – unknown Parcel C – unknown Parcel D – unknown	municipal records aerial photographs Sanborn Fire Insurance Maps interviews
c. 1956 – c. 1991	Parcel A – building with addition and parking areas Parcel B – building with addition Parcel C – building, garage, and parking areas Parcel D – building and parking areas	Parcel A – motel Parcel B – commercial Parcel C – commercial and residential Parcel D - commercial	Parcel A – Motor City Motel (1952-present) Parcel B – CM Bollinger (c. 1958-c. 1965); Hamrich Amusements (c. 1970 – c. 1975); Primary Service (c. 1980 – c. 1985); Just My Type (c. 1990) Parcel C – Hollywood Café (c. 1958 – c. 1965); Enchanted Hairstylists (c. 1964 – c. 1980); Crossroads Bar and Grill (c. 1970 – present); Teddy's Hair Loft (c. 1985 – c. 1995) Parcel D – M&L Janitor Supply (c. 1960 – c. 1965); T&B Service Station Maintenance (c. 1964 –	municipal records aerial photographs Sanborn Fire Insurance Maps city directories topographic map interviews



Time Period	Improvements	Use	Owner / Occupant	Data Source(s)
			c. 1965); American Generator Remfg. Co. (c. 1970 – c. 1980); B&B Starter and Alternator (c. 1985); National Generator (c. 1990)	
c. 1991 – present	Parcel A – building and parking areas Parcel B – building Parcel C – building and parking areas Parcel D – building and parking areas	Parcel A – motel Parcel B – commercial Parcel C – commercial and residential Parcel D - commercial	Parcel A – Motor City Motel (1952-present) Parcel B – Paper and Ink Printing (c. 1995); currently vacant Parcel C – Crossroads Bar and Grill (c. 1970 – present) Parcel D – Bruce's Auto Supply and D&K Starter and Alternator (c. 1995); Luke Walkuski (present)	municipal records aerial photographs Sanborn Fire Insurance Maps city directories topographic map soil survey interviews reconnaissance

Historical Summary - Adjoining Properties

<u>North</u>

The northern adjoining property (17301 Raupp Avenue) consisted of unimproved land from at least 1937 until between 1961 and 1966, when a residential apartment complex was constructed. Hayvar Senior Apartments currently occupies the northern adjoining property.

East (from north to south)

The eastern adjoining property, beyond Raupp Road (17250 Raupp Avenue), consisted of unimproved land from at least 1937 until between 1964 and 1966, when a residential apartment complex was constructed. Rauppdale Apartments currently occupies this eastern adjoining property

The eastern adjoining property, beyond Raupp Road (2630 Oakwood Boulevard), consisted of unimproved land from at least 1937 until approximately 1962, when a restaurant was constructed. In approximately the late 1990s/early 2000s a new restaurant was constructed. Wendy's currently occupies this eastern adjoining property

South (from west to east)

The southern adjoining property, beyond Oakwood Boulevard (17431 Dix Road), consisted of unimproved land from at least 1937 until prior to 1941, when a commercial building/restaurant. White castle currently occupies this southern adjoining property.

The southern adjoining property, beyond Oakwood Boulevard (2661 Oakwood Boulevard) has consisted of a gasoline fueling station since at least 1937. Metro Mart currently occupies this southern adjoining property.



West (from north to south)

The western adjoining properties along Eddon Street have consisted of single-family residential dwellings and an apartment building since at least 1937.

The western adjoining property (2760 Oakwood Boulevard) consisted of gasoline fueling/service station from at least 1937 until the 1980s/1990s, when it was utilized for various commercial uses. Occupants of this adjoining property have included Joe's Service, Monaco Collision, S. Gambino Signs, American Auto Access, and Gambino Pin Striping. Buhay Service and Supply currently occupies this adjoining property.

4.5.1 Aerial Photographs

AKT Peerless obtained aerial photographs for the subject property from EDR and Terraserver. AKT Peerless' observations noted during the review of these photographs are summarized in the following table. Photocopies of select aerial photographs are presented as Appendix E.

Photo Dates	Observations (Subject Property)	Potential Environmental Concerns
1937	Parcel A consists of unimproved land. Parcel B consists of an apparent commercial building. Parcel C consists of an apparent commercial/residential structure with a detached garage and parking areas. Parcel D consists of unimproved land.	none observed
1949	Appears similar to the 1937 aerial photograph; however, an apparent commercial building and paved parking areas have been constructed on Parcel D.	none observed
1957 1964 1972 1985 1993 2000 2002	Appears similar to the 1949 aerial photograph; however, an apparent motel building and paved parking areas have been constructed on Parcel A.	none observed

AKT Peerless' review of historical aerial photographs of the adjoining properties is summarized in the following table.

Photo Dates	Potential Environmental Concerns (Adjoining Properties)
1937	
1949	No obvious evidence or indications of recognized environmental conditions or other potential
1957	environmental concerns were noted with respect to the adjoining properties during AKT Peerless'
1964	review of the referenced aerial photographs, aside from the fact that the western and a southern
1972	adjoining property appear to be developed with gasoline fueling stations.
1985	
1993 2000 2002	No obvious evidence or indications of recognized environmental conditions or other potential environmental concerns were noted with respect to the adjoining properties during AKT Peerless' review of the referenced aerial photographs, aside from the fact that a southern adjoining property appears to be developed with a gasoline fueling station.



As discussed in Section 4.2.2, the southern adjoining gasoline fueling station (2661 Oakwood Boulevard) does not appear to present an environmental concern to the subject property; however, as discussed in Section in Section 4.5.3, the western adjoining former gasoline fueling station (2760 Oakwood Boulevard) appears to present a potential environmental concern to the subject property.

4.5.2 Fire Insurance Maps

AKT Peerless obtained fire insurance maps for the subject property from EDR. AKT Peerless' observations noted during the review of these maps are summarized in the following table. Photocopies of the referenced maps are presented in Appendix F.

Map Dates	Observations (Subject Property)	Potential Environmental Concerns
1941	Parcel A consists of unimproved land. Parcel B consists of a commercial building. Parcel C consists of an apparent commercial/residential structure with a detached garage. Parcel D consists of unimproved land.	none observed
1950 1952	Appears similar to the 1941 Sanborn map; however, a commercial building has been constructed on Parcel D.	none observed
1957 1961 1966	Parcel A consists of a 24 unit motel building. An addition has been made to the commercial building located on Parcel B. Parcels C and D appear similar to previous Sanborn maps.	none observed

AKT Peerless' review of historical fire insurance maps of the adjoining properties is summarized in the following table.

Map Dates	Potential Environmental Concerns (Adjoining Properties)
1941	
1950	No obvious evidence or indications of recognized environmental conditions or other potential
1952	environmental concerns were noted with respect to the adjoining properties during AKT Peerless'
1957	review of the referenced aerial photographs, aside from the fact that the western and a southern
1961	adjoining property are developed with gasoline fueling stations.
1966	

As discussed in Section 4.2.2, the southern adjoining gasoline fueling station (2661 Oakwood Boulevard) does not appear to present an environmental concern to the subject property; however, as discussed in Section in Section 4.5.3, the western adjoining former gasoline fueling station (2760 Oakwood Boulevard) appears to present a potential environmental concern to the subject property.

4.5.3 <u>City Directories</u>

City Directories from various years between 1958-2007 were reviewed at the Bresser's Cross-Reference Directory archival library. The purpose of this review was to determine the past occupancy of the subject property. Information obtained from the reviewed directories is summarized in the following table:



Dates	Subject Property Occupants (17355 Raupp Road – Parcel A)
1958-2007	Motor City Motel

Dates	Subject Property Occupants (2700 Oakwood Boulevard – Parcel B)
1958-1965	CM Bollinger
1970-1976	Hamrich Amusements
1980-1985	Primary Service
1990	Just My Type
1995	Paper & Ink Printing
2000-2007	address not listed

Dates	Subject Property Occupants (2704 Oakwood Boulevard – Parcel C)
1958-1961	Hollywood Café, residential
1964-1965	Hollywood Café, Enchanted Hairstylists, residential
1970-1980	Crossroads Bar, Enchanted Hairstylists, residential
1985-1995	Crossroads Bar, Teddies Hair Loft, residential
1995-2007	residential

Dates	Subject Property Occupants (2750 Oakwood Boulevard – Parcel D)	
1958-1959	address not listed	
1960-1961	M&L Janitor Supply	
1964-1965	T&B Service Station Maintenance	
1970-1980	American Generator Remfg. Co.	
1985	B&B Starter and Alternator	
1990	National Generator	
1995	Bruce's Auto Supply, D&K Starter and Alternator	
2000-2007	address not listed	

An address that is not listed typically indicates that (1) the property was vacant at that time, (2) a potential building was unoccupied at that time, (3) a previously existing address was different than the current address, (4) the building was not represented in the directory because of a "lag time" between building the structure and compiling the list, or (5) occupant information was not available for inclusion into the directory.

AKT Peerless also reviewed city directories for select adjoining properties to determine their past occupancy. No obvious environmental concerns associated with historical occupants of the adjoining properties were noted, except for the following:

- <u>2661 Oakwood Boulevard</u> (southern adjoining property, beyond Oakwood Boulevard) this adjoining property has operated as a gasoline fueling/service station since at least 1958; however, as discussed in Section 4.2.2, this adjoining property does not appear to present an environmental concern to the subject property.
- 2760 Oakwood Boulevard (western adjoining property) this adjoining property operated as



an automotive service garage from at least 1958 until approximately the 1990s. In AKT Peerless' opinion, this adjoining property presents a potential environmental concern to the subject property based on (1) the site adjoins Parcel D directly to the west, (2) the site operated a gasoline fueling/service station from at least 1937 until approximately the 1980s/1990s, (3) information regarding the removal of the USTs and/or environmental investigations were not identified.

4.5.4 Assessing Department Records

AKT Peerless reviewed tax assessment records on the subject property at the Melvindale Assessing Department. The following table summarizes features or items of potential environmental concern, if any, that were noted during the record review.

Environmental Issue	Comments
Storage Tanks	none identified
Asbestos-Containing Materials	none identified
PCB Materials	none identified
On-site Well/Septic System	none identified
Disposal Facilities/Fill Material (e.g., lagoons, pits, landfills, etc.)	none identified

The Assessing Department could not locate a file for Parcel D (2700 Oakwood Boulevard). Copies of information obtained from the Melvindale Assessing Department are included in Appendix G.

4.5.5 Building Department Records

AKT reviewed building records for the subject property at the Melvindale Building Department. AKT Peerless' review did not identify potential environmental concerns associated with the subject property, except for the following:

Parcel D - 2750 Oakwood Boulevard

 August 1989 – Certificate of Occupancy, indicates that D&K Starter Shop (starter and alternator shop) occupied this property.

Parcel B - 2700 Oakwood Boulevard

• June 1983 – Permit, indicates that a print shop occupied this property.

5.0 INTERVIEWS

AKT Peerless provided questionnaires to the subject property owner and key site manager, and as available, conducted interviews.

5.1 INTERVIEWS WITH SUBJECT PROPERTY OWNERS AND MANAGERS

AKT Peerless interviewed Mr. Nick Patel, regarding knowledge of Parcel A and provided an owner questionnaire. Mr. Patel has owned Parcel A for approximately eight years. No



information was reported that would be considered material to identifying recognized environmental conditions in connection with the subject property.

AKT Peerless interviewed Mr. Pat Riley, regarding knowledge of Parcels B and C. Mr. Riley has owned Parcels B and C since 1998. According to Mr. Riley, Parcel B formerly operated as a print shop and Parcel C has operated as a restaurant since development. No additional information was reported that would be considered material to identifying recognized environmental conditions in connection with the subject property.

AKT Peerless interviewed Mr. Luke Walkuski, regarding knowledge of Parcel D. Mr. Walkuski currently utilizes Parcel D for home improvement activities and storage. According to Mr. Walkuski, Parcel D formerly operated as an automotive repair operation. No additional information was reported that would be considered material to identifying recognized environmental conditions in connection with the subject property.

5.2 INTERVIEWS WITH OTHERS

Other interviews were not conducted.

6.0 SUBJECT PROPERTY RECONNAISSANCE

6.1 METHODOLOGY AND LIMITING CONDITIONS

The subject property reconnaissance consisted of visual and physical observations of the subject property. AKT Peerless visually and/or physically observed the periphery of the subject property. In addition, AKT Peerless observed the subject property from all adjacent public thoroughfares.

Ms. Jessica Cory of AKT Peerless conducted the subject property reconnaissance on September 5 and 14, 2007. Mr. Nick Patel, property owner of Parcel A, and Mr. Luke Walkuski, property owner of Parcel D, accompanied Ms. Cory during the reconnaissance activities. AKT Peerless encountered the following project specific facts or conditions that limited our ability to access the subject property:

AKT Peerless was not provided access to the subject building located at 2700 and was only
provided partial access to the subject building located at 2704 Oakwood Boulevard.

6.2 GENERAL SUBJECT PROPERTY SETTING AND OPERATIONS

Parcel A is currently developed with a 23-unit motel, Parcel B is currently developed with a vacant commercial building, Parcel C is currently developed with a restaurant/bar with a second story residential apartment unit, and Parcel D is currently developed with a commercial building utilized for storage and home improvement activities. The exterior of the subject property is improved with paved parking areas, grass, and landscaped areas. In general, the subject property is level with adjoining properties to the north, south and east, but is slightly higher than the adjoining properties to the west.



6.3 OBSERVATIONS

6.3.1 Hazardous Substances and Petroleum Products

AKT Peerless did not observe hazardous substances or petroleum products at the subject property, with the exception of general household cleaners at Parcel A.

6.3.2 Hazardous and Non-Hazardous Waste

AKT Peerless did not observe hazardous or non-hazardous waste at the subject property, with the exception of general refuse at Parcels A and C.

6.3.3 Storage Tanks

AKT Peerless did not observe evidence of current or former UST systems (e.g., vent pipes, fill ports, dispensing pumps, patched pavement, etc.) at the subject property, except for an unknown pipe located along the east-central exterior wall of the building located on Parcel D. The pipe was approximately two to three inches in diameter and three feet high. Refer to Photograph 10 in Appendix C for a photograph of this unknown pipe.

6.3.4 <u>Unidentified Substances/Containers</u>

AKT Peerless did not observe evidence of unidentified substances or other suspect containers on the subject property.

6.3.5 Potential PCB Containing Equipment

AKT Peerless inspected the subject property for the presence of liquid-cooled electrical units such as transformers and large capacitors. Such units are notable since they may be potential sources of PCBs (polychlorinated biphenyls). AKT Peerless did not observe suspect PCB-containing equipment at the subject property, except for the following:

Source Description	Source Location	Responsibility	Observations
fluorescent light fixtures	subject building interiors	subject property owners	no evidence of a release

Fluorescent light ballasts manufactured before 1980 may contain PCBs. These ballasts are considered small capacitors under the Toxic Substances Control Act (TSCA). An inspection of these fluorescent light ballasts for evidence of PCB content was beyond the scope of this assessment. However, no obvious evidence of leaking units was noted. Given the subject buildings' dates of construction, it is AKT Peerless' opinion that these fixtures may contain PCBs.

6.3.6 Interior Staining / Corrosion

AKT Peerless did not observe evidence of interior staining or corrosion.

6.3.7 Drains and Sumps

AKT Peerless did not observe drains or sumps in the subject building, except for the following:



Description	Location	Observed Environmental Concerns
floor drain	bathrooms	none
	basement of 2750 Oakwood Boulevard	none

6.3.8 Discharge Features

Storm water that falls upon the subject property appears to percolate directly into the ground. AKT Peerless did not observe storm water catch basins or drains on the subject property.

6.3.9 Pits, Ponds, and Lagoons

AKT Peerless did not observe evidence of pits, ponds, or lagoons, or evidence thereof, at the subject property.

6.3.10 Solid Waste Dumping / Landfills

AKT Peerless did not observe evidence of solid waste dumping or landfills at the subject property.

6.3.11 Stained Soil, Stressed Vegetation, Stressed/Stained Pavement

AKT Peerless did not observe any evidence of stained soil, stressed vegetation, stressed pavement, or stained pavement at the subject property.

6.3.12 Well and Septic Systems

AKT Peerless did not observe physical evidence or indication of wells or septic systems at the subject property.

6.3.13 Other Observations

AKT Peerless did not observe evidence of other potential environmental concerns at the subject property.

6.4 NON-ASTM SCOPE CONSIDERATIONS

AKT Peerless did not evaluate any other potential environmental conditions (i.e., further areas of possible business/environmental concern and/or liability) that are outside the scope of ASTM Standard Practice E 1527-05. Examples of such potential environmental conditions that were beyond the scope of this Phase I ESA include, cultural and historic resources, ecological resources, endangered species, health and safety, high-voltage power lines, indoor air quality, industrial hygiene, lead-based paints (LBPs), lead in drinking water, moisture intrusion/suspect mold growth, noise pollution, radon, regulatory compliance/non-compliance and/or wetlands.

AKT Peerless advises users of this document who wish to obtain an evaluation of the subject property relative to any of the aforementioned non-ASTM issues to engage the services of a qualified environmental professional.



6.4.1 Suspect Asbestos Sources

Although evaluating asbestos-containing materials (ACMs) was outside the scope of ASTM Standard Practice E 1527-05, AKT Peerless observed building materials that are suspect for asbestos content during the property inspection. In general, these suspect materials were readily accessible and visible during the inspection and did not require the dismantling of permanent structures, such as walls, floors, and ceilings. Suspect ACMs observed during AKT Peerless' property inspection included plaster, textured ceiling/wall material, suspended ceiling tiles, vinyl floor tiles, thermal system insulation, pipe joint compound, and roofing materials.

It is recommended that prior to performing demolition activities that comprehensive building demolition asbestos surveys be conducted to identify the nature and extent of asbestos containing materials at the subject property.

7.0 CONCLUSIONS AND RECOMMENDATIONS

7.1 RECOGNIZED ENVIRONMENTAL CONDITIONS

We have performed a Phase I ESA of the subject property in conformance with the scope and limitations of ASTM Standard Practice E 1527-05. Any exceptions to, or deletions from, this practice are described in Section 8 and Appendix A of this report. This assessment has revealed no evidence of RECs in connection with the subject property, except for the following:

- As discussed throughout this report, Parcel B (2700 Oakwood Boulevard) operated as a print shop in the 1980s/1990s. Specific information regarding the print shop operations was not available during the completion of this assessment (i.e, potential hazardous material use and storage, etc.). In addition, AKT Peerless was not provided access to the interior of this subject building.
- 2. As discussed throughout this report, Parcel D (2750 Oakwood Boulevard) operated as an automotive service garage from the 1960s until approximately the 1990s. Occupants of this property have included T&B Service Station Maintenance, B&B Starter and Alternator, Bruce's Auto Supply, and D&K Starter and Alternator. Specific information regarding the former service garage operations was not available during the completion of this assessment (i.e, potential hazardous material use and storage, USTs/ASTs, hydraulic hoists etc.).
- 3. As discussed in section 6.3.3, AKT Peerless observed an unknown pipe located along the east-central exterior wall of the building located at 2750 Oakwood Boulevard (Parcel D). The source of the pipe is unknown, and could potentially be associated with a UST or former AST.
- 4. As discussed throughout this report, the western adjoining property (2760 Oakwood Boulevard) operated as gasoline fueling/service station from at least 1937 until approximately the 1980s/1990s. In AKT Peerless' opinion, this adjoining property presents a potential environmental concern to the subject property based on (1) the site adjoins Parcel D directly to the west, (2) the site operated a gasoline fueling/service station with at least three gasoline USTs from at least 1937 until approximately the 1980s/1990s, (3) information



regarding the removal of the USTs and/or environmental investigations were not identified.

Because RECs were identified during the performance of the Phase I ESA, further investigation and/or assessment is warranted in order to determine the nature, extent, magnitude, and materiality of the RECs associated with the subject property.

7.2 HISTORICAL RECOGNIZED ENVIRONMENTAL CONDITIONS

AKT Peerless did not identify HRECs in connection with the subject property.

7.3 POTENTIAL AREAS OF CONCERN AND SIGNIFICANT DATA GAPS

AKT Peerless did not identify other areas of potential concern in connection with the subject property during the course of this ESA, except for the following:

- As discussed in Section 6.3.5, based on the age of the subject buildings, fluorescent light ballasts noted during the site inspection may contain PCBs. It is AKT Peerless' opinion these fixtures represent a minimal environmental risk to the subject property. However, upon replacement of the fixtures during future renovations, the ballasts should be evaluated and, if PCB-containing, handled in accordance with applicable regulations.
- As discussed in Section 6.4.1, suspect ACMs observed during AKT Peerless' property
 inspection included plaster, textured ceiling/wall material, suspended ceiling tiles, vinyl floor
 tiles, thermal system insulation, pipe joint compound, and roofing materials. It is
 recommended that prior to performing demolition activities that comprehensive building
 demolition asbestos surveys be conducted to identify the nature and extent of asbestos
 containing materials at the subject property.
- Due to data failure, AKT Peerless was unable to determine if the use of the subject property historically entailed the use of septic systems.
- Due to data failure, AKT Peerless was unable to determine what specific heating fuels (e.g., coal, propane, oil, etc.) were used at the subject property prior to the connection to natural gas.

AKT Peerless did not identify evidence of an adverse environmental effect upon the subject property in connection with the areas of potential concern listed above. Nevertheless, it is AKT Peerless' opinion that a potential exists for PCB containing light ballasts, septic systems, and/or heating oil containers to be present at the subject property.

Consequently, AKT Peerless recommends that such items, if identified or encountered during future development activities, be decommissioned, removed, and/or disposed in accordance with applicable federal, state, and local regulations. Additional action beyond that recommended above may be warranted if evidence of actual or historical heating oil USTs is identified at the subject property in the future.

AKT Peerless did not identify or encounter any instances of <u>significant</u> data gaps during the course of this ESA, except for the following:

AKT Peerless was not provided access to the subject building located at 2700 and was only



provided partial access to the subject building located at 2704 Oakwood Boulevard.

8.0 **DEVIATIONS**

AKT Peerless did not deviate from ASTM Standard Practice E 1527-05 when performing this Phase I ESA (i.e., no components of that practice were deleted, and no additions to it were made), except as describes in Section 6.4.

9.0 SIGNATURES OF ENVIRONMENTAL PROFESSIONALS

We declare that, to the best of our knowledge and professional belief, we meet the definition of environmental professional as defined in ASTM E-1527-05 or conducted this inquiry under the supervision or responsible charge of, an environmental professional. We have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. We have developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in ASTM E-1527-05.

Jessica T. Cory

Environmental Consultant

persica T. Cory

AKT PEERLESS ENVIRONMENTAL SERVICES

Farmington, Michigan Office

phone: 248-615-1333 fax: 248-615-1334

Sandra Muszynski


Senior Project Manager

AKT PEERLESS ENVIRONMENTAL SERVICES

Farmington, Michigan Office

andre Massyri

phone: 248-615-1333 fax: 248-615-1334





QUALIFICATIONS



Professional Environmental Services

PROFESSIONAL PROFILE

JESSICA T. CORY

Environmental Consultant
Environmental Compliance and Assessment Services

EDUCATION

Bachelor of Science: Environmental Studies and Applications, 2003 Michigan State University, East Lansing, Michigan

PROFESSIONAL EXPERIENCE

Environmental Consultant
AKT Peerless Environmental Services

Project Scientist Innovative Environmental Solutions, Inc.

AREA OF EXPERTISE

- (1) Evaluating the potential environmental risk at commercial, industrial, and residential property
- Conducting Phase I environmental site assessments (ESAs)
- (3) Conducting Phase II Subsurface Investigations
- (4) Preparing Baseline Environmental Assessments
- (5) Field management and activities coordination
- (6) Coordinating environmental investigations

ADDITIONAL EXPERTISE

- (1) Conducting field operations such as soil, surface water, and groundwater sampling
- (2) Oversight of field operations such as monitoring well installation, contaminant delineation, and soil excavation
- (3) Creating maps, diagrams, and drawings

ADDITIONAL EXPERTISE (continued)

- (4) Assessment of commercial and multi-family residential facilities in support of property condition assessments
- (5) Conducting asbestos, lead, and hazardous material inspections

SUMMARY OF SELECTED PROJECTS

- (1) Performed Phase I ESAs (including site reconnaissance, regulatory and historical records investigations, and report completion) for financial institutions, manufacturing facilities, real estate developers, and property managers. Properties included industrial, commercial, and residential sites located in Michigan and Ohio.
- (2) Performed II subsurface investigations (including soil boring and monitoring well installation, laboratory data interpretation, and report preparation) to:
 - (a) Evaluate the potential presence of contaminants
 - (b) Evaluate the type of contaminants
 - (c) Delineate horizontal and vertical extent

Additional activities included the preparation of Baseline Environmental Assessments to address identified contamination at facilities for submittal to the Michigan Department of Environmental Quality.

- (3) Prepared Property Condition Assessments of commercial and residential apartment properties. Activities included site inspections and report preparation.
- (4) Performed asbestos, lead, and hazardous material inspections of various buildings including commercial and manufacturing buildings and residential structures. Activities performed consisted of visual inspections of suspect materials, review of building records, observations of sampling techniques, and review of laboratory results.

LICENSES

Michigan Asbestos Inspector, Accreditation Number A34295

Michigan Asbestos Management Planner, Accreditation Number A32400

SPECIALIZED TRAINING

OSHA 29 CFR 1910.120 - 40-Hour Hazardous Waste Operations Training

AHERA Asbestos Inspector Course

AHERA Asbestos Management Planner Course



Professional Environmental Services

PROFESSIONAL PROFILE

SANDRA M. MUSZYNSKI, CHMM

Senior Environmental Consultant
Environmental Compliance and Assessment Services

EDUCATION

Master in Science: in Environmental Science, 1990 University of New Haven, West Haven, Connecticut

Bachelor of Science: Zoology, 1988

Michigan State University, East Lansing, Michigan

PROFESSIONAL EXPERIENCE

Senior Environmental Consultant & Compliance Specialist

AKT Peerless Environmental Services

Environmental Consultant

Soil and Materials Engineers

Senior Staff Scientist

Environmental Science and Engineering

Compliance Specialist

Environmental Management Consultants

AREA OF EXPERTISE

- (1) Phase I environmental site assessments (ESAs)
- (2) Environmental compliance audits and reviews
- (3) Environmental management services such as waste characterization, waste minimization assessments, spill prevention plans, stormwater pollution prevention plans, environmental reporting, and environmental permitting
- (4) Project management, oversight, and coordination of Phase I ESAs, Phase II ESAs, and remediation projects

SUPPORTING AREAS OF EXPERTISE

- (1) Working knowledge of state and federal environmental regulations applicable to solid, hazardous, and medical waste management, wastewater discharges, toxic release inventory reporting, hazardous chemical inventory reporting, air emissions permitting, underground and aboveground storage tanks, oil pollution control, PCBs, asbestos, and OSHA hazard communication
- (2) Asbestos building inspections
- (3) Project management and field activities coordination

SUMMARY OF SELECTED PROJECTS

- (1) Performed Phase I ESAs (including project management, site reconnaissance, regulatory and historical records investigations, and report completion) for financial institutions, manufacturing facilities, real estate developers, property managers, and insurance companies. Properties included industrial, commercial, and residential sites as well as health care facilities.
- (2) Conducted environmental compliance audits for:
 - (a) Metal fabricating facilities (including stamping plants and welding operations)
 - (b) Plastics forming facilities
 - (c) Electronic equipment manufacturing facilities
 - (d) Foundries
 - (e) Metal plating operations
 - (f) Hospitals

Audits focused on determining the facilities' degree of compliance with applicable federal, state and local environmental regulations and recommending actions to achieve compliance.

- (3) Provided technical expertise and project management support for Wayne County's USEPA Brownfield Assessment Demonstration Pilot Project. The pilot project was designed to empower communities in the economic redevelopment of Brownfield sites through a \$200,000 USEPA grant. Duties include management, oversight and completion of Phase I ESAs; participation in Technical Advisory Committee meetings; budget tracking; and the identification and utilization of available resources from supporting agencies and communities.
- (4) Provided technical expertise to the Downriver Area Brownfield Consortium's (DABC) USEPA Brownfield Assessment Demonstration Pilot Project. The pilot project was designed to empower communities in the economic redevelopment of Brownfield sites through a \$200,000 USEPA grant. Duties included the management and completion of Phase I ESAs.

- (5) Prepared Spill Prevention Control and Countermeasure/Pollution Incident Prevention (SPCC/PIP) Plans for (1) bulk fuel storage facilities, (2) asphalt paving facilities (3) pharmaceutical supply companies, and (4) various manufacturing facilities.
- (6) Prepared Stormwater Pollution Prevention Plans for foundries and various manufacturing facilities.
- (7) Assembled an Environmental, Health, and Safety Policy Handbook for the aviation department of a large manufacturing company.
- (8) Prepared an annual Toxic Chemical Release Inventory (TRI/Form R) and Hazardous Chemical Inventory (Tier II) reports for:
 - (a) Metal fabricating facilities
 - (b) Heat treating facilities
 - (c) A pharmaceutical supply company
 - (d) Foundries
 - (e) Various manufacturing facilities
- (9) Completed National Pollutant Discharge Elimination System (NPDES) wastewater discharge permit applications for:
 - (a) Manufacturing facilities
 - (b) Groundwater remediation systems
- (10) Completed Critical Materials and Wastewater Reports for various manufacturing facilities.
- (11) Assembled and submitted formal petitions to the MDEQ for the designation of waste foundry sand as "inert for general reuse" and as "low hazard industrial waste," thus avoiding disposal costs. Petitions included information such as waste sand generation schematics, generation rates, raw material data, laboratory analysis data, and statistical analysis.
- (12) Conducted asbestos inspections of various buildings including:
 - (a) Manufacturing plants
 - (b) Commercial buildings
 - (c) Hospitals
 - (d) Residential structures
- (13) Managed Phase II subsurface investigations (including the coordination of soil boring and monitoring well installation, laboratory data interpretation, and report completion) to:
 - (a) Evaluate the potential presence of contaminants
 - (b) Evaluate the type of contaminants
 - (c) Delineate horizontal and vertical extent

CERTIFICATIONS

Certified Hazardous Materials Manager (CHMM) by the Institute of Certified Hazardous Materials Managers, Michigan

ISO 14001 Environmental Management Systems Lead Auditor Training (RAB Certified Course)

Accredited asbestos inspector by the Michigan Department of Labor and Economic Growth

Certified NIOSH Airborne Asbestos Dust Sampling and Evaluating


Health and Safety Training for Hazardous Waste Sites (OSHA-mandated 40-hour training and additional Site Supervisor Workshop)

PUBLICATIONS/PRESENTATIONS

Anthony, T.R. and Ashley, S.E., Do Your Clients' USTs Comply With 1998 Regulations? Michigan Lawyers Weekly, Vol. 11, No. 8, December 1996.


Ashley, S.E., Environmental Compliance Audits. Presented to Michigan Asphalt Paving Association. January 1995.

Voydanoff, S.E., New Year's Day, 1990: Out With the Old and Back With the Recycled. Manufacturers' Mart, September 1990.






FIGURES




DEARBORN QUADRANGLE

MICHIGAN - WAYNE COUNTY
7.5 MINUTE SERIES (TOPOGRAPHIC)



T.2 S. - R.11 E.






FARMINGTON DETROIT SAGINAW LANSING WWW.AKTPEERLESS.COM

TOPOGRAPHIC LOCATION MAP

2700, 2704 & 2750 OAKWOOD AND 17335 RAUPP MELVINDALE, MICHIGAN PROJECT NUMBER: 5635F-1-17 DRAWN BY: KHE DATE: 8-21-07

FIGURE 2







FARMINGTON DETROIT SAGINAW LANSING WWW.AKTPEERLESS.COM

PARCEL MAP

2700, 2704 & 2750 OAKWOOD AND 17335 RAUPP MELVINDALE, MICHIGAN PROJECT NUMBER: 5635F-1-17 DRAWN BY: KHE DATE: 8-21-07

FIGURE 3







APPENDIX A

GENERAL LIMITATIONS AND EXCEPTIONS



General Limitations and Exceptions

Subject to the proposal, scope-of-services, and the related terms and conditions referenced in Section 1.0 of this Phase I ESA, AKT Peerless accepts responsibility for the competent performance of its duties in executing the assignment and preparing reports in accordance with the normal standards of the profession, but disclaims any responsibility for consequential damages.

Although AKT Peerless believes that the findings, opinions, and recommendations contained herein are reliable and appropriate, AKT Peerless cannot warrant or guarantee that the information provided is exhaustive, or that the information obtained from any data sources is complete or accurate.


Along with the inherent limitations set forth in various sections of ASTM Standard Practice E 1527-05, the accuracy and completeness of this report may be limited by the following facts or conditions:

- Due to the poor scale of the historical aerial photographs, the presence or absence of small features (e.g., individual drums, fuel dispensers) could not be discerned reliably.
- AKT Peerless made reasonable efforts to determine if USTs or related equipment (collectively referred to as UST systems) are or have been present at the subject property. AKT Peerless defines reasonable efforts as obtaining and evaluating information from visual observations of unobstructed areas and from the secondary sources cited in this report. AKT Peerless recognizes, and suggests users of this assessment acknowledge, that the accuracy of our conclusions relative to the on-site presence or use of UST systems may be directly affected by the presence of physical obstructions at the time of the reconnaissance, or affected by our receipt and evaluation of incorrect information.
- AKT Peerless' evaluation of soil and groundwater features at and near the subject property was based only on published maps and other readily available information. AKT Peerless used this information to assess soil types and groundwater flow directions to determine if conditions at any nearby sites present an environmental threat to the subject property.
- Unless specifically noted otherwise, invasive investigation of any kind has not been performed during this Phase I ESA, nor has observation under floors, above ceilings, behind walls, within the surface and subsurface soil, within groundwater, within confined spaces, roof tops, or inaccessible areas been performed.
- AKT Peerless did not conduct sampling or analysis of air, soil, groundwater, surface water, or building materials as part of this Phase I ESA, unless specifically noted otherwise.
- This Phase I ESA did not include a physical inspection of the adjoining properties, which AKT Peerless observed from the subject property and from readily accessible public rightsof-way.
- AKT Peerless typically does not review historical or environmental information about nearby sites in detail unless known activities or events at a nearby site appear to present an environmental threat to the subject property.
- AKT Peerless' scope of services did not include conducting a review of property title



documentation. AKT Peerless requested property title documentation and environmental cleanup liens from the Client, but was not provided this information, unless specifically noted otherwise. However, as described in this report, AKT Peerless made reasonable attempts to determine if the State Environmental Agency maintains documentation regarding environmental liens recorded against the subject property.

- This assessment did not include a review or audit of operational environmental compliance issues, or of any environmental management systems, that may be associated with the subject property.
- This Phase I ESA did not include any investigation or evaluation of issues not specifically related to petroleum products or hazardous substances as defined in CERCLA (i.e., other areas of potential business environmental risk such as radon, lead in drinking water, etc.).
- The information and opinions contained in the report are given in light of this assignment. The report must be reviewed and relied upon only in conjunction with the terms and conditions expressly agreed-upon by the parties and as limited therein.
- Although AKT Peerless believes the results contained in herein are reliable, AKT Peerless
 cannot warrant or guarantee that the information provided is exhaustive, or that the
 information provided by the Client, third parties, or the secondary information sources cited
 in this report is complete or accurate.
- AKT Peerless is not in a position to provide an opinion regarding the Fair Market Value of the subject property. Therefore, a comparison of the purchase price of the subject property to other similar real estate transactions was not conducted during this assessment.
- Nothing in this report constitutes a legal opinion or legal advice. For information regarding individual or organizational liability, AKT Peerless recommends consultation with independent legal counsel.
- AKT Peerless relied upon specific or common knowledge of the Client, or information
 provided to the Client, to identify environmental liens, institutional controls, activity use
 limitations, or property valuation issues. As possible within the time frame and cost of this
 project, AKT Peerless looked for any obvious environmental information regarding these
 issues made readily available during the course of this ESA.
- The information and opinions presented in this report are for the exclusive use of the Client. No distribution to or reliance by other parties may occur without the express written permission of AKT Peerless. AKT Peerless will not distribute this report without written consent from the Client, or as required by law or by a Court order.
- Any third parties to whom the right to rely on the contents of this report have been granted by AKT Peerless, which is explicitly required prior to any third-party release, expressly agrees to be bound by the original terms and conditions entered into by AKT Peerless and the Client.





APPENDIX B LEGAL DESCRIPTION

[Back to Non-Printer Friendly Version] [Send To Printer]

Parcel: 47 006 01 0072 000 Data Current As

Of: 4:19 AM 9/01/2007

Property Address

[collapse]

17355 RAUPP

MELVINDALE, MI 48122

Owner Information

[collapse]

DAS, NARESH

17355 RAUPP

MELVINDALE, MI 48122

Unit:

47

Taxpayer Information

[collapse]

SEE OWNER INFORMATION

General Information for Tax Year 2008

[collapse]

Property Class:

201

Assessed Value:

\$204,400

School District:

XM143 - 47-

MELVINDALE/NORTHERN Taxable Value:

\$115,865

State Equalized Value:

Al \$204,400

Map #

Temp Code

Date of Last Name Chg:

06/02/2000

Date Filed:

Principal Residence Exemption

(2007 May 1):

05/01/1994 0.0000 %

Principal Residence Exemption

(2007 Final): **Principal Residence Exemption** 0.0000 %

(2008 May 1):

0.0000 %

Previous Year Info	MBOR Assessed	Final S.E.V.	Final Taxable
2007	\$204,400	\$204,400	\$115,865
2006	\$190,100	\$190,100	\$111,731

Land Information

[collapse]

Acreage: **Zoning Code: Land Value:**

0.00 R1 1 FA Frontage: Depth:

0.00 Ft. 0.00 Ft.

Land Improvements: Renaissance Zone:

ECF Neighborhood Code:

\$129,200 \$0 NO

Mortgage Code:

Lot Dimensions/Comments:

Legal Information

[collapse]

N72 TO N80 LOTS 72 TO 80 INCL SCHAEFER-DIX SUB PC 51,59 L55 P48 WCR

100

Parcel: 47 006 01 0248 000 Data Current As

Of: 1:55 PM 8/01/2007

[Back to Non-Printer Friendly Version] [Send To Printer]

Property Address

[collapse]

2704 OAKWOOD MELVINDALE, MI 48122

Owner Information

[collapse]

RILEY, PATRICK

Unit:

47

545 SONIA MADISON HGTS, MI 48071

Taxpayer Information

[collapse]

SEE OWNER INFORMATION

General Information for Tax Year 2008

[collapse]

Property Class:

Assessed Value:

\$7,300

School District:

XM143 - 47-MELVINDALE/NORTHERN Taxable Value:

\$4,098

State Equalized Value:

AL \$7,300

Мар#

Temp Code

Date of Last Name Chg:

06/02/2000

Date Filed:

Principal Residence Exemption

(2007 May 1):

0.0000 %

Principal Residence Exemption

0.0000 %

(2007 Final):

Principal Residence Exemption

0.0000 %

12000	in cay	± j.	

Previous Year Info	MBOR Assessed	Final S.E.V.	Final Taxable
2007	\$7,300	\$7,300	\$4,098
2006	\$6,800	\$6,800	\$3,952

Land Information				[collapse]
Acreage:	0.00	Frontage:	0.00 Ft.	
Zoning Code:	R1 1 FA	Depth:	0.00 Ft.	
Land Value:	\$14,400	Mortgage Code:		
Land Improvements:	\$0	Lot Dimensions/Comments:		
Renaissance Zone:	NO			
ECF Neighborhood Code:	100			

Legal Information

[collapse]

N248 LOT 248 SCHAEFER-DIX SUB PC 51,59 L55 P48 WCR

Parcel: 47 006 01 0249 000 Data Current As

Of: 1:55 PM 8/01/2007

[Back to Non-Printer Friendly Version] [Send To Printer]

Property Address

[collapse]

2704 OAKWOOD MELVINDALE, MI 48122

Owner Information

[collapse]

RILEY, PATRICK

545 SONIA

MADISON HGTS, MI 48071

Unit:

47

Taxpayer Information

[collapse]

SEE OWNER INFORMATION

General Information for Tax Year 2008

[collapse]

Property Class:

201

Assessed Value:

\$7,300

School District:

XM143 - 47-

MELVINDALE/NORTHERN Taxable Value:

\$4,098

AL

State Equalized Value:

Temp Code

\$7,300 0

Date of Last Name Chg:

06/02/2000

Date Filed:

Principal Residence Exemption

(2007 May 1):

0.0000 %

Principal Residence Exemption

(2007 Final):

0.0000 %

Principal Residence Exemption

(2008 May 1):

0.0000 %

Previous Year Info	MBOR Assessed	Final S.E.V.	Final Taxable
2007	\$7,300	\$7,300	\$4,098
2006	\$6,800	\$6,800	\$3,952

Land Information			[collapse]
Acreage:	0.00	Frontage:	0.00 Ft.
Zoning Code:	R1 1 FA	Depth:	0.00 Ft.
Land Value:	\$14,400	Mortgage Code:	
Land Improvements:	\$0	Lot Dimensions/Comme	nts:
Renaissance Zone:	NO	, , , , , , , , , , , , , , , , , , , ,	
ECF Neighborhood Code:	100		

Legal Information

[collapse]

N249 LOT 249 SCHAEFER-DIX SUB PC 51,59 L55 P48 WCR

Parcel: 47 006 01 0250 000 Data Current As

Of: 1:55 PM 8/01/2007

[Back to Non-Printer Friendly Version] [Send To Printer]

Property Address

2704 OAKWOOD

MELVINDALE, MI 48122

Owner Information

[collapse]

[collapse]

RILEY, PATRICK 545 SONIA

MADISON HGTS, MI 48071

Unit:

47

Taxpayer Information

[collapse]

SEE OWNER INFORMATION

General Information for Tax Year 2008

[collapse]

Property Class:

Assessed Value:

\$7,300

School District:

XM143 - 47-

MELVINDALE/NORTHERN Taxable Value:

\$4,098

State Equalized Value:

AL \$7,300

Map #

Temp Code

0

Date of Last Name Chg:

06/02/2000

Date Filed:

Principal Residence Exemption

(2007 May 1):

0.0000 %

Principal Residence Exemption

(2007 Final):

0.0000 %

Principal Residence Exemption

(2008 May 1):

0.0000 %

Previous Year Info	MBOR Assessed	Final S.E.V.	Final Taxable
2007	\$7,300	\$7,300	\$4,098
2006	\$6,800	\$6,800	\$3,952

Land Information

[collapse]

Acreage: Zoning Code: 0.00

Frontage: Depth:

0.00 Ft. 0.00 Ft.

Land Value:

R1 1 FA \$14,400 \$0

Mortgage Code:

Land Improvements: Renaissance Zone: ECF Neighborhood Code:

NO 100 Lot Dimensions/Comments:

Legal Information

[collapse]

N250 LOT 250 SCHAEFER-DIX SUB PC 51,59 L55 P48 WCR

[collapse]

General Property Information

Parcel: 47 006 01 0251 000 Data Current As

Of: 1:55 PM 8/01/2007

[Back to Non-Printer Friendly Version] [Send To Printer]

Property Address

2704 OAKWOOD

MELVINDALE, MI 48122

Owner Information

[collapse]

RILEY, PATRICK

545 SONIA

MADISON HGTS, MI 48071

Unit:

47

Taxpayer Information

[collapse]

SEE OWNER INFORMATION

General Information for Tax Year 2008

[collapse]

Property Class:

201

Assessed Value:

\$7,300

School District:

XM143 - 47-

MELVINDALE/NORTHERN Taxable Value:

\$4,098

State Equalized Value:

AL \$7,300

Map #

Date of Last Name Chg:

06/02/2000

Date Filed:

Temp Code

Principal Residence Exemption

(2007 May 1):

0.0000 %

Principal Residence Exemption

(2007 Final):

0.0000 %

Principal Residence Exemption

(2008 May 1):

0.0000 %

Previous Year Info	MBOR Assessed	Final S.E.V.	Final Taxable
2007	\$7,300	\$7,300	\$4,098
2006	\$6,800	\$6,800	\$3,952

Land Information

[collapse]

Acreage: Zoning Code: Land Value:

0.00 R1 1 FA \$14,400

Frontage: Depth:

0.00 Ft. 0.00 Ft.

Land Improvements: Renaissance Zone:

ECF Neighborhood Code:

\$0 NO 100 Mortgage Code:

Lot Dimensions/Comments:

Legal Information

[collapse]

N251 LOT 251 SCHAEFER-DIX SUB PC 51,59 L55 P48 WCR

Parcel: 47 006 01 0252 000 Data Current As

Of: 1:55 PM 8/01/2007

[Back to Non-Printer Friendly Version] [Send To Printer]

Property Address

2704 OAKWOOD MELVINDALE, MI 48122

Owner Information

[collapse]

[collapse]

RILEY, PATRICK

545 SONIA

MADISON HGTS, MI 48071

Unit:

47

Taxpayer Information

[collapse]

SEE OWNER INFORMATION

General Information for Tax Year 2008

[collapse]

Property Class:

201

Assessed Value:

\$7,300

School District:

XM143 - 47-

MELVINDALE/NORTHERN Taxable Value:

\$4,098

State Equalized Value:

AL \$7,300

0

Map #

Temp Code

Date Filed:

Date of Last Name Chg:

06/02/2000

Principal Residence Exemption

(2007 May 1):

0.0000 %

Principal Residence Exemption

(2007 Final):

0.0000 %

Principal Residence Exemption

(2008 May 1):

0.0000 %

Previous Year Info	MBOR Assessed	Final S.E.V.	Final Taxable
2007	\$7,300	\$7,300	\$4,098
2006	\$6,800	\$6,800	\$3,952

Land Information

[collapse]

Acreage: Zoning Code: 0.00 R1 1 FA Frontage: Depth:

0.00 Ft. 0.00 Ft.

Land Value: Land Improvements: Renaissance Zone:

ECF Neighborhood Code:

\$14,400 \$0 NO

100

Mortgage Code:

Lot Dimensions/Comments:

Legal Information

[collapse]

N252 LOT 252 SCHAEFER-DIX SUB PC 51,59 L55 P48 WCR

[Back to Non-Printer Friendly Version] [Send To Printer]

Parcel: 47 006 01 0253 301 Data Current As

Of: 1:55 PM 8/01/2007

Property Address

[collapse]

2750 OAKWOOD MELVINDALE, MI 48122

Owner Information

[collapse]

WALKUSKI, LUKE

7656 CHARLESWORTH

DEARBORN HEIGHTS, MI 48127

Unit:

47

Taxpayer Information

SEE OWNER INFORMATION

[collapse]

General Information for Tax Year 2008

[collapse]

Property Class:

201

AL

Assessed Value:

\$27,700

School District:

MELVINDALE/NORTHERN Taxable Value:

\$15,928

State Equalized Value:

Temp Code

\$27,700

XM143 - 47-

Map #

Date of Last Name Chg:

06/02/2000

Date Filed:

Principal Residence Exemption

(2007 May 1):

0.0000 %

Principal Residence Exemption

0.0000 %

(2007 Final): **Principal Residence Exemption**

(2008 May 1):

0.0000 %

Previous Year Info	MBOR Assessed	Final S.E.V.	Final Taxable
2007	\$27,700	\$27,700	\$15,928
2006	\$25,800	\$25,800	\$15.360

Land	Info	orm	atio	n
	-			

[collapse]

Acreage: Zoning Code: 0.00

Frontage: Depth:

0.00 Ft. 0.00 Ft.

Land Value:

R1 1 FA \$40,700

Mortgage Code:

Land Improvements: Renaissance Zone:

ECF Neighborhood Code:


\$0 NO 100

Lot Dimensions/Comments:

Legal Information

[collapse]

*N253 TO 255 LOTS 253 TO 255 INCL SCHAEFER-DIX SUB PC 51, 59 L55 P48 WCR--K=0.14--





APPENDIX C

RECONNAISSANCE PHOTOGRAPHS



PHOTOGRAPH 1: SUBJECT PROPERTY
VIEW OF THE MOTOR CITY MOTEL LOCATED ON PARCEL A OF THE SUBJECT PROPERTY



PHOTOGRAPH 2: SUBJECT PROPERTY
GENERAL VIEW OF A MOTEL UNIT LOCATED IN THE SUBJECT BUILDING



17355 RAUPP ROAD AND 2700, 2704, & 2750 OAKWOOD BOULEVARD MELVINDALE, MICHIGAN TAKEN BY: DATE: JTC 09-05/14-07



PHOTOGRAPH 3: SUBJECT PROPERTY
GENERAL VIEW OF A BOILER/LAUNDRY ROOM LOCATED IN THE SUBJECT BUILDING



PHOTOGRAPH 4: SUBJECT PROPERTY VIEW OF THERMAL SYSTEM INSULATION LOCATED IN THE BOILER ROOM OF THE SUBJECT BUILDING



17355 RAUPP ROAD AND 2700, 2704, & 2750 OAKWOOD BOULEVARD MELVINDALE, MICHIGAN TAKEN BY: DATE:

JTC 09-05/14-07



PHOTOGRAPH 5: SUBJECT PROPERTY
VIEW OF THE SOUTHERN PORTIONS OF PARCEL B (VACANT COMMERCIAL BUILDING) AND
PARCEL C (CROSSROADS BAR & GRILL AND RESIDENTIAL APARTMENT UNIT)



PHOTOGRAPH 6: SUBJECT PROPERTY VIEW OF THE NORTHERN PORTION OF THE VACANT COMMERCIAL BUILDING LOCATED ON PARCEL B



17355 RAUPP ROAD AND 2700, 2704, & 2750 OAKWOOD BOULEVARD MELVINDALE, MICHIGAN TAKEN BY: DATE: JTC 09-05/14-07




PHOTOGRAPH 7: SUBJECT PROPERTY VIEW OF THE NORTHERN/WESTERN PORTIONS OF PARCELS A, B, AND C




PHOTOGRAPH 8: SUBJECT PROPERTY VIEW OF THE SOUTHERN PORTION OF COMMERCIAL BUILDING LOCATED ON PARCEL D



17355 RAUPP ROAD AND 2700, 2704, & 2750 OAKWOOD BOULEVARD MELVINDALE, MICHIGAN TAKEN BY: DATE: JTC 09-05/14-07



PHOTOGRAPH 9: SUBJECT PROPERTY VIEW OF THE EASTERN/NORTHERN PORTION OF THE COMMERCIAL BUILDING LOCATED ON PARCEL D



PHOTOGRAPH 10: SUBJECT PROPERTY VIEW OF AN UNKNOWN PIPE LOCATED ALONG THE EAST-CENTRAL PORTION OF THE BUILDING LOCATED ON PARCEL D



RECONNAISSANCE PHOTOGRAPHS

17355 RAUPP ROAD AND 2700, 2704, & 2750 OAKWOOD BOULEVARD MELVINDALE, MICHIGAN TAKEN BY: DATE: JTC 09-05/14-07



PHOTOGRAPH 11: SUBJECT PROPERTY
GENERAL VIEW OF THE MAIN FLOOR OF THE BUILDING LOCATED ON PARCEL D



PHOTOGRAPH 12: SUBJECT PROPERTY VIEW OF THE GARAGE AREA OF THE BUILDING LOCATED ON PARCEL D



17355 RAUPP ROAD AND 2700, 2704, & 2750 OAKWOOD BOULEVARD MELVINDALE, MICHIGAN TAKEN BY: DATE:

JTC 09-05/14-07



PHOTOGRAPH 13: NORTHERN ADJOINING PROPERTY VIEW OF THE HAYVAR SENIOR APARTMENTS (17301 RAUPP ROAD)



PHOTOGRAPH 14: WESTERN ADJOINING PROPERTY VIEW OF THE BUHAY SERVICE AND SUPPLY CO. (2760 OAKWOOD BOULEVARD)



17355 RAUPP ROAD AND 2700, 2704, & 2750 OAKWOOD BOULEVARD MELVINDALE, MICHIGAN TAKEN BY: DATE: JTC 09-05/14-07



PHOTOGRAPH 15: WESTERN ADJOINING PROPERTY VIEW OF AN ALLEY FOLLOWED BY AN APARTMENT COMPLEX



PHOTOGRAPH 16: SOUTHERN ADJOINING PROPERTY VIEW OF WHITE CASTLE (17431 DIX ROAD)



17355 RAUPP ROAD AND 2700, 2704, & 2750 OAKWOOD BOULEVARD MELVINDALE, MICHIGAN TAKEN BY: DATE:

JTC 09-05/14-07



PHOTOGRAPH 17: EASTERN ADJOINING PROPERTY VIEW OF RAUPP ROAD FOLLOWED BY THE RAUPPDALE APARTMENTS (17250 RAUPP ROAD)

)



RECONNAISSANCE PHOTOGRAPHS

17355 RAUPP ROAD AND 2700, 2704, & 2750 OAKWOOD BOULEVARD MELVINDALE, MICHIGAN TAKEN BY: DATE:

JTC 09-05/14-07





APPENDIX D

STANDARD ENVIRONMENTAL RECORD DATABASE REPORT

EDR Radius MapTM Report

Prepared using the EDR FieldCheck® System

5635f-1-17 2700 Oakwood Melvindale, MI 48122

Inquiry Number: 2022413.1s

September 06, 2007



The Standard in Environmental Risk Information

440 Wheelers Farms Road Milford, Connecticut 06461

Nationwide Customer Service

Telephone: 1-800-352-0050 Fax: 1-800-231-6802 Internet: www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map.	2
Detail Map.	. 3
Map Findings Summary	. 4
Map Findings.	_ 6
Orphan Summary	, 51
EPA Waste Codes.	EPA-1
Government Records Searched/Data Currency Tracking.	GR-1
GEOCHECK ADDENDUM	
GeoCheck - Not Requested	

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

The EDR FieldCheck ®System enables EDR's customers to make certain online modifications to the maps and text contained in EDR Radius Map Reports. As a result, the maps and text contained in this Report may have been so modified. EDR has not taken any action to verify any such modifications, and this report and the findings set forth herein must be read in light of this fact. The EDR FieldCheck System accesses user-modified records from previously submitted reports. Any user-modified record from a previous report that is plotted outside the search radius of this report may not be included in this report.

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT. Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2007 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

A search of the environmental records was conducted by Environmental Data Resources, Inc. (EDR). AKT ENVIRONMENTAL CONSULTANTS used the EDR FieldCheck System to review and/or revise the results of this search, based on independent data verification by AKT ENVIRONMENTAL CONSULTANTS. The report was designed to assist parties seeking to meet the search requirements of EPA's Standards and Practices for All Appropriate Inquiries (40 CFR Part 312), the ASTM Standard Practice for Environmental Site Assessments (E 1527-05) or custom requirements developed for the evaluation of environmental risk associated with a parcel of real estate.

TARGET PROPERTY INFORMATION

ADDRESS

2700 OAKWOOD MELVINDALE, MI 48122

COORDINATES

Latitude (North):

42,284200 - 42° 17' 3.1"

Longitude (West):

83.169500 - 83° 10' 10.2"

Universal Tranverse Mercator: Zone 17 UTM X (Meters): UTM Y (Meters):

321119.8 4683396.5

Elevation:

587 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH TARGET PROPERTY

Target Property Map:

42083-C2 DEARBORN, MI

Most Recent Revision:

1983

TARGET PROPERTY SEARCH RESULTS

The target property was identified in the following records. For more information on this property see page 6.

Site	Database(s)	EPA ID
D AND K STARTER AND ALTERNATOR 2750 OAKWOOD	RCRA-SQG FINDS	MID985607043
MELVINDALE, MI 48122	4	

DATABASES WITH NO MAPPED SITES

No sites were identified in following databases.

FEDERAL RECORDS

..... National Priority List Proposed NPL...... Proposed National Priority List Sites Delisted NPL...... National Priority List Deletions NPL LIENS..... Federal Superfund Liens

RCRA-TSDF...... Resource Conservation and Recovery Act Information

ERNS..... Emergency Response Notification System

HMIRS Hazardous Materials Information Reporting System

US ENG CONTROLS..... Engineering Controls Sites List US INST CONTROL...... Sites with Institutional Controls DOD...... Department of Defense Sites Formerly Used Defense Sites US BROWNFIELDS..... A Listing of Brownfields Sites

CONSENT...... Superfund (CERCLA) Consent Decrees

UMTRA..... Uranium Mill Tailings Sites ODI..... Open Dump Inventory

LUCIS......Land Use Control Information System

DOT OPS..... Incident and Accident Data

ICIS_____Integrated Compliance Information System

HIST FTTS_____FIFRA/TSCA Tracking System Administrative Case Listing

US CDL...... Clandestine Drug Labs RADINFO...... Radiation Information Database LIENS 2 CERCLA Lien Information

MLTS Material Licensing Tracking System

MINES..... Mines Master Index File

RAATS_____RCRA Administrative Action Tracking System

STATE AND LOCAL RECORDS

DEL SHWS..... Delisted List of Contaminated Sites SWF/LF...... Solid Waste Facilities Database HIST LF..... Inactive Solid Waste Facilities

LIENS....Lien List

AST..... Aboveground Tanks

PEAS...... Pollution Emergency Alerting System AUL Engineering and Institutional Controls

DRYCLEANERS Drycleaning Establishments

BROWNFIELDS...... Brownfields and USTfield Site Database

CDL...... Clandestine Drug Lab Listing NPDES List of Active NPDES Permits

AIRS_____ Permit and Emissions Inventory Data

TRIBAL RECORDS

INDIAN RESERV..... Indian Reservations

INDIAN LUST..... Leaking Underground Storage Tanks on Indian Land

INDIAN UST...... Underground Storage Tanks on Indian Land

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified in the following databases.

Elevations have been determined from the USGS Digital Elevation Model and should be evaluated on a relative (not an absolute) basis. Relative elevation information between sites of close proximity should be field verified. Sites with an elevation equal to or higher than the target property have been differentiated below from sites with an elevation lower than the target property.

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in bold italics are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

FEDERAL RECORDS

CERCLIS: The Comprehensive Environmental Response, Compensation and Liability Information System contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

An online review and analysis by AKT ENVIRONMENTAL CONSULTANTS of the CERCLIS list, as provided by EDR, and dated 04/23/2007 has revealed that there is 1 CERCLIS site within approximately 0.5 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
RIVER ROUGE FILL AREA	SCHAEFER RD E GREENFIEL	1/4 - 1/2NNE	17	26

CERCLIS-NFRAP: Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

An online review and analysis by AKT ENVIRONMENTAL CONSULTANTS of the CERC-NFRAP list, as provided by EDR, and dated 06/21/2007 has revealed that there are 2 CERC-NFRAP sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Dist / Dir N	lap ID	Page
RIVER ROUGE MELVINDALE CITY OF DPW	SCHAEFER HWY BRIDGE 3315 GREENFIELD	1/4 - 1/2 NNE 1 1/4 - 1/2 NNW 2		30 37

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

An online review and analysis by AKT ENVIRONMENTAL CONSULTANTS of the CORRACTS list, as provided by EDR, and dated 06/26/2007 has revealed that there is 1 CORRACTS site within approximately 1 mile of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
LEVY EDW C CO PLT 6	13950 MELON RD	1/2 - 1 NE	26	38

RCRAInfo: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRAInfo replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System(RCRIS). The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month. Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month Large quantity generators generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month. Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

An online review and analysis by AKT ENVIRONMENTAL CONSULTANTS of the RCRA-LQG list, as provided by EDR, and dated 06/13/2006 has revealed that there is 1 RCRA-LQG site within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
REILLY PLATING CO	17760 CLARANN	1/8 - 1/4 S	C10	12

RCRAInfo: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRAInfo replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System(RCRIS). The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month. Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month Large quantity generators generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month. Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

An online review and analysis by AKT ENVIRONMENTAL CONSULTANTS of the RCRA-SQG list, as provided by EDR, and dated 06/13/2006 has revealed that there are 6 RCRA-SQG sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
EXPRESS AUTO B AND K COLLISION INC KAIER SCHOOL M-LOK INC	17420 DIX 2521 OAKWOOD BLVD 17525 DORA ST 17760 CLARANN	0 - 1/8 SSE 0 - 1/8 ESE 0 - 1/8 SSE 1/8 - 1/4 S	4	8 8 9 11
Lower Elevation	Address	Dist / Dir	Map ID	Page
R D CHERRY INC VALVE RECONDITIONING	2429 OAKWOOD BLVD 17180 FRANCIS	1/8 - 1/4 E 1/8 - 1/4 ESE	6 B7	10 10

STATE AND LOCAL RECORDS

SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data come from the Department of Environmental Quality's' Contaminated Sites List on Diskette With Address.

An online review and analysis by AKT ENVIRONMENTAL CONSULTANTS of the SHWS list, as provided by EDR, and dated 08/17/2007 has revealed that there are 2 SHWS sites within approximately 1 mile of the target property.

Lower Elevation	Address	Dist / D	Dir	Map ID	Page
DETROIT STRIP CYCLOPS STEEL Facility Status: Inactive - no actions taken to ad	971 SOUTH OAKWOOD dress contamination	1/2 - 1	ENE	27	42
MARATHON PIPELINE CRYSTAL MINE Facility Status: Interim Response conducted - N	1300 SOUTH FORT STREET No further activities anticipated	1/2 - 1	ESE	29	43

LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the Department of Environmental Quality's Leaking Underground Storage Tank (LUST) Database.

An online review and analysis by AKT ENVIRONMENTAL CONSULTANTS of the LUST list, as provided by EDR, and dated 06/11/2007 has revealed that there are 11 LUST sites within approximately 0.5 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
NORFOLK SOUTHERN CORP FORB POO Facility Status: Closed	17801 DIX RD	1/8 - 1/4 SSW	12	14
J & J BUILDING CO Facility Status: Open	17730 DORA ST	1/8 - 1/4 S	13	15
EBONEX CORP Facility Status: Closed	2380 S WABASH ST	1/4 - 1/2S	22	36
Lower Elevation	Address	Dist / Dir	Map ID	Page
DETROIT BUMPER MART Facility Status: Closed	17162 FRANCIS ST	1/8 - 1/4 ESE	B8	10
SALEM MACHINE COSAC PROPERTI Facility Status: Closed	17100 FRANCIS ST	1/8 - 1/4 ESE	11	14
SCHAEFER SERVICE STATION Facility Status: Open Facility Status: Open	2625 SCHAEFER RD	1/4 - 1/2NE	14	17
WORLD CLASS AUTO WASH Facility Status: Closed	2311 S SCHAFER	1/4 - 1/2 E	15	21
FUEL MART OF AMERICA INC Facility Status: Closed	335 S SCHAEFER HWY	1/4 - 1/2NE	16	22
CAPITOL INVESTMENT PROPERTIES Facility Status: Closed	17065 HESS ST	1/4 - 1/2ESE	18	28
REFINERS TRANSPORT & TERMINAL Facility Status: Closed	3335 GREENFIELD RD	1/4 - 1/2 NNW	20	30

Lower Elevation	Address	Dist / Dir	Map ID	Page
JDS CERTIFIED TRUCK REPAIR INC	3345 GREENFIELD	1/4 - 1/2 NNW	21	34
Facility Status: Closed				

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Quality's Michigan UST database.

An online review and analysis by AKT ENVIRONMENTAL CONSULTANTS of the UST list, as provided by EDR, and dated 06/11/2007 has revealed that there are 4 UST sites within approximately 0.25 miles of the target property.

Equal/Higher Elevation	Address	Dist / Dir	Map ID	Page
PETRON INC NORFOLK SOUTHERN CORP FORB POO J & J BUILDING CO	2661 OAKWOOD BLVD 17801 DIX RD 17730 DORA ST	0 - 1/8 SE 1/8 - 1/4SSW 1/8 - 1/4S	A2 12 13	6 14 15
Lower Elevation	Address	Dist / Dir	Map ID	Page
DETROIT BUMPER MART	17162 FRANCIS ST	1/8 - 1/4 ESE	B8	10

BEA: Baseline Environmental Assessment.

An online review and analysis by AKT ENVIRONMENTAL CONSULTANTS of the BEA list, as provided by EDR, and dated 06/13/2007 has revealed that there are 2 BEA sites within approximately 0.5 miles of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
Not reported	1155 OAKWOOD	1/4 - 1/2E	24	38
MILL STEEL, THE	18030 RIALTO STREET	1/4 - 1/2S	25	38

EDR PROPRIETARY RECORDS

EDR Manufactured Gas Plants: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

An online review and analysis by AKT ENVIRONMENTAL CONSULTANTS of the Manufactured Gas Plants list, as provided by EDR, has revealed that there is 1 Manufactured Gas Plants site within approximately 1 mile of the target property.

Lower Elevation	Address	Dist / Dir	Map ID	Page
MICHIGAN CONSOLIDATED GAS CO-	GREENFIELD ROAD	1/2 - 1 NW	28	43

Due to poor or inadequate address information, the following sites were not mapped:

Site Name


MARATHON REFINERY WEATHERING PIT

ROUGE RIVER
NORFOLK AND WESTERN RAILROAD
NORFOLK WESTERN RR
MICHIGAN SITE NETWORK
AL'S TRUCK STOP BP
NORFOLK SOUTHERN CORP
NONFOLK SOUTHERN CORP
MELVINDALE TANK FARM
MI DEPT/TRANSPORTATION BRIDGE S04-82194
FOUR WAY COLLISION INC
ARTS BODY SHOP INC
STERLING GROUP
FORD MOTOR LAND DEVELOPMENT CORP.

Database(s)

SHWS, DEL SHWS, BROWNFIELDS SHWS, BROWNFIELDS SHWS CERC-NFRAP BROWNFIELDS AUL LUST, UST UST AST RCRA-SQG RCRA-SQG, FINDS RCRA-SQG, FINDS BEA BEA

OVERVIEW MAP - 2022413.1s



SITE NAME: 5635f-1-17 ADDRESS: 2700 Oakwood Melvindale MI 48122 LAT/LONG: 42.2842 / 83.1695


CLIENT: **AKT Environmental Consultants**

CONTACT: INQUIRY#: Kate Bowman

2022413.1s

September 06, 2007 12:13 pm DATE:

DETAIL MAP - 2022413.1s



SITE NAME: 5635f-1-17 ADDRESS: 2700 Oakwood Melvindale MI 48122 LAT/LONG: 42.2842 / 83.1695 CLIENT: AKT Environmental Consultants

CONTACT: Kate Bowman

INQUIRY#: 2022413.1s

DATE: September 06, 2007 12:13 pm

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	>1	Total Plotted
FEDERAL RECORDS								
NPL Proposed NPL Delisted NPL NPL LIENS CERCLIS CERC-NFRAP CORRACTS RCRA TSD RCRA Lg. Quan. Gen. RCRA Sm. Quan. Gen. ERNS HMIRS US ENG CONTROLS US INST CONTROL DOD FUDS US BROWNFIELDS CONSENT ROD UMTRA ODI TRIS TSCA FTTS SSTS LUCIS DOT OPS ICIS HIST FTTS CDL RADINFO LIENS 2 PADS MLTS MINES FINDS RAATS	X	1.000 1.000 1.000 1.000 TP 0.500 0.500 1.000 0.250 0.250 TP TP 0.500 1.000 1.000 1.000 0.500 1.000 1.000 0.500 TP	000R00003RR000000000RRRRORRRRRRRRRRRRRR	000800001388000000000088880888888888888	000812008888000000000088880888888888888	0000KKK1KKKKKKKO0K00KKKKKKKKKKKKKKKKKKK	アン・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・	0 0 0 0 1 1 1 6 0 0 0 0 0 0 0 0 0 0 0 0
STATE AND LOCAL RECOR	DS							
State Haz. Waste DEL SHWS State Landfill HIST LF LUST UST LIENS AST		1.000 1.000 0.500 0.500 0.500 0.250 TP 0.250	0 0 0 0 1 NR 0	0 0 0 0 4 3 NR 0	0 0 0 7 NR NR NR	2 NR NR NR NR NR	NR NR NR NR NR NR	2 0 0 0 11 4 0

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
PEAS AUL DRYCLEANERS BROWNFIELDS CDL NPDES AIRS BEA		TP 0.500 0.250 0.500 TP TP TP TP 0.500	NR 0 0 0 NR NR NR 0	NR 0 0 0 NR NR NR 0	NR 0 NR 0 NR NR NR	NR NR NR NR NR NR NR	NR NR NR NR NR NR	0 0 0 0 0 0 0
TRIBAL RECORDS								
INDIAN RESERV INDIAN LUST INDIAN UST		1.000 0.500 0.250	0 0 0	0 0 0	0 0 NR	0 NR NR	NR NR NR	0 0 0
EDR PROPRIETARY RECOR	RDS							
Manufactured Gas Plants		1.000	0	0	0	1	NR	1

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

Map ID MAP FINDINGS

Direction Distance Distance (ft.)

Elevation

Database(s)

EDR ID Number **EPA ID Number**

D AND K STARTER AND ALTERNATOR

2750 OAKWOOD **Target Property** MELVINDALE, MI 48122 RCRA-SQG **FINDS** 1000465978 MID985607043

U003325671

N/A

RCRAInfo:

Actual: 586 ft.

Owner: EPA ID: GRASZAK DANIEL MID985607043

Contact:

DANIEL GRASZAK

(313) 388-4112

Classification:

Small Quantity Generator

TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

A2

SE < 1/8 PETRON INC 2661 OAKWOOD BLVD MELVINDALE, MI 48122

78 ft.

Site 1 of 2 in cluster A

Relative: Higher

UST:

Owner Name:

Petron Inc

Actual: 587 ft.

Owner Address: Owner City, St, Zip: 2661 Oakwood Blvd Melvindale, MI 48122-1350

Owner Country: Owner Contact: USA Not reported

Owner Phone: Facility ID:

(313) 386-2100 00035570 Abrar Ahmad (313) 386-2100

Contact: Contact Phone: Tank ID:

Tank Status:

Currently In Use

Capacity: Install Date: Product:

6000 Oct 1 1991 Gasoline

Remove Date:

Not reported

Tank Release Detection: Automatic Tank Gauging, Inventory Control

Piping Material:

Pipe Realease Detection: Automatic Line Leak Detectors Fiberglass reinforced plastic

Piping Type:

Constr Material:

Pressure Cathodically Protected Steel

Impressed Device:

Owner Name:

Petron Inc

Owner Address:

2661 Oakwood Blvd

Owner City, St, Zip:

Melvindale, MI 48122-1350

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number **EPA ID Number**

U003325671

PETRON INC (Continued)

Owner Country:

USA

Owner Contact: Owner Phone:

Not reported (313) 386-2100

Facility ID: Contact:

00035570 Abrar Ahmad (313) 386-2100

Contact Phone: Tank ID:

Tank Status: Capacity:

Currently In Use 6000

Install Date: Product:

Oct 1 1991 Gasoline

Remove Date:

Not reported

Tank Release Detection: Automatic Tank Gauging, Inventory Control Pipe Realease Detection: Automatic Line Leak Detectors

Piping Material:

Fiberglass reinforced plastic

Piping Type:

Pressure

Constr Material:

Cathodically Protected Steel

Impressed Device:

Owner Name:

Petron Inc

Owner Address: Owner City, St, Zip: 2661 Oakwood Blvd Melvindale, MI 48122-1350

Owner Country:

USA

Owner Contact: Owner Phone:

Not reported (313) 386-2100 00035570

Facility ID: Contact:

Abrar Ahmad (313) 386-2100

Contact Phone: Tank ID:

Tank Status:

Remove Date:

Currently In Use

Capacity: Install Date: Product:

10000 Oct 1 1991 Gasoline Not reported

Tank Release Detection: Automatic Tank Gauging, Inventory Control Pipe Realease Detection: Automatic Line Leak Detectors

Piping Material:

Piping Type:

Fiberglass reinforced plastic

Pressure

Constr Material:

Cathodically Protected Steel

Impressed Device:

Owner Name:

Petron Inc

Owner Address: Owner City, St, Zip: 2661 Oakwood Blvd Melvindale, MI 48122-1350

Owner Country:

USA

Owner Contact: Owner Phone:

Not reported (313) 386-2100 00035570

Facility ID: Contact:

Abrar Ahmad

Contact Phone: Tank ID:

(313) 386-2100

Tank Status:

Currently In Use

Capacity:

10000

Install Date: Product:

Oct 1 1991 Diesel

Remove Date:

Not reported

Tank Release Detection: Automatic Tank Gauging, Inventory Control

Map ID Direction Distance Distance (ft.) Elevation Site

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

U003325671

PETRON INC (Continued)

Pipe Realease Detection: Automatic Line Leak Detectors

Piping Material:

Fiberglass reinforced plastic

Piping Type:

Pressure

Constr Material:

Cathodically Protected Steel

Impressed Device:

Owner Name:

Petron Inc

Owner Address: Owner City, St, Zip: 2661 Oakwood Blvd Melvindale, MI 48122-1350

Owner Country: Owner Contact: USA Not reported

Owner Phone: Facility ID:

(313) 386-2100 00035570

Contact: Contact Phone: Abrar Ahmad (313) 386-2100

Tank ID:

Tank Status:

Currently In Use 6000

Capacity: Install Date:

Oct 1 1991 Kerosene

Product: Remove Date: Not reported

Pipe Realease Detection: Automatic Line Leak Detectors

Tank Release Detection: Automatic Tank Gauging, Inventory Control

Piping Material:

Fiberglass reinforced plastic

Piping Type:

Pressure

Constr Material:

Cathodically Protected Steel

Impressed Device:

A3 SSE **EXPRESS AUTO**

17420 DIX

MELVINDALE, MI 48122

< 1/8 118 ft.

Relative:

Site 2 of 2 in cluster A

Higher

RCRAInfo:

Owner:

EXPRESS AUTO

Actual: 587 ft.

EPA ID: MIK666324868

Contact:

AHMAD MANSOUR (313) 388-9995

Classification:

Small Quantity Generator

TSDF Activities: Not reported

Violation Status: No violations found

4 ESE B AND K COLLISION INC 2521 OAKWOOD BLVD MELVINDALE, MI 48122

< 1/8

557 ft.

Relative: Higher

Actual: 587 ft.

RCRA-SQG 1000309445 **FINDS**

RCRA-SQG

MID052038395

1007099423

MIK666324868

Map ID Direction Distance Distance (ft.) Elevation Site MAP FINDINGS

Database(s)

RCRA-SQG

FINDS

1000979950

MI0000996884

EDR ID Number **EPA ID Number**

1000309445

B AND K COLLISION INC (Continued)

RCRAInfo:

Owner:

MICHAEL BRENNAN

EPA ID: Contact: MID052038395

MICHAEL BRENNAN (313) 386-2580

Classification:

Small Quantity Generator

TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

SSE

KAIER SCHOOL

< 1/8

17525 DORA ST MELVINDALE, MI 48122

653 ft.

RCRAInfo: Relative:

Higher

Owner:

ECONOMIC DEVEL CORP

Actual:

EPA ID: Contact: MI0000996884 MIKE INGELS

(313) 455-9070

587 ft.

Classification: Small Quantity Generator TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

TC2022413.1s Page 9

Map ID Direction Distance Distance (ft.)

Elevation Site Database(s)

EDR ID Number **EPA ID Number**

East

R D CHERRY INC 2429 OAKWOOD BLVD

MELVINDALE, MI 48122

RCRA-SQG

RCRA-SQG

FINDS

LUST

UST

1007990181 MIK825926694

1000866441

MID985665983

1/8-1/4 908 ft.

> Relative: Lower

RCRAInfo:

Owner:

RICHARD D CHERRY

EPA ID:

MIK825926694

Actual: 586 ft.

Contact:

RICHARD CHERRY

(313) 388-7622

Classification:

Conditionally Exempt Small Quantity Generator

TSDF Activities: Not reported

Violation Status: No violations found

B7 ESE **VALVE RECONDITIONING** 17180 FRANCIS

1/8-1/4

MELVINDALE, MI 48122

1106 ft.

Site 1 of 2 in cluster B

Relative: Lower

RCRAInfo:

VALVE RECONDITIONING SVC

Actual: 586 ft.

Owner: EPA ID:

MID985665983

Contact:

MICHAEL CARBONARD

(313) 928-5980

Classification:

Small Quantity Generator

TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

B8

DETROIT BUMPER MART

ESE 1/8-1/4 17162 FRANCIS ST **MELVINDALE, MI 48122**

1108 ft.

Site 2 of 2 in cluster B

Relative: Lower

LUST:

Facility Status:

Closed

Actual: 586 ft.

00019991 Facility ID:

Owner Name:

Supreme Bumpers Inc

Owner Address: Owner City, St, Zip: 420 S 15th St Toledo, OH 43602-1206

Country:

USA

U000267356

N/A

Map ID Direction Distance

MAP FINDINGS

Database(s)

RCRA-SQG

TRIS

1000333017

48122MLKNC17

EDR ID Number **EPA ID Number**

U000267356

DETROIT BUMPER MART (Continued)

Owner Contact:

Not reported

Owner Phone:

(419) 241-5261

District:

SE Michigan District Office

Leak Number: Release Date: C-0572-96 Sep 5 1996

Site Name:

Detroit Bumper Mart Gasoline, Unknown

Closed Date:

Substance Released:

Jan 14 1997

UST:

Distance (ft.)

Site

Elevation

Owner Name:

Supreme Bumpers Inc

Owner Address:

420 S 15th St

Owner City, St, Zip:

Toledo, OH 43602-1206

Owner Country:

USA

Owner Contact:

Not reported

Owner Phone: Facility ID:

(419) 241-5261 00019991

Contact:

ROBERT J MURRAY

Contact Phone:

(248) 546-9910

Tank ID:

Tank Status:

Removed from Ground

Capacity:

2000

Install Date:

Jun 20 1978 Gasoline

Product: Remove Date:

Aug 8 1996

Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material:

Unknown

Piping Type:

Not reported

Constr Material:

Fiberglass Reinforced plastic, Lined Interier

Impressed Device:

No

C9

M-LOK INC

South 1/8-1/4 17760 CLARANN MELVINDALE, MI 48122

1144 ft.

Site 1 of 2 in cluster C

Relative: Higher

RCRAInfo:

Owner: EPA ID: M-LOK INC

Actual: 589 ft.

MID074246679

Contact:

GEORGE SALEH (313) 928-6800

Small Quantity Generator

Classification:

TSDF Activities: Not reported

Violation Status: No violations found

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s)

RCRA-LQG

FINDS

TRIS

EDR ID Number EPA ID Number

1000289727

48122RLLYP17

C10 South REILLY PLATING CO 17760 CLARANN

1/8-1/4

MELVINDALE, MI 48122

1144 ft.

Site 2 of 2 in cluster C

Relative: Higher

FINDS:

Other Pertinent Environmental Activity Identified at Site

Actual: 589 ft.

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and its Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

The NEI (National Emissions Inventory) database contains information on stationary and mobile sources that emit criteria air pollutants and their precursors, as well as hazardous air pollutants (HAPs).

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number **EPA ID Number**

REILLY PLATING CO (Continued)

1000289727

RCRAInfo:

Owner: EPA ID: GEORGE G SALEH MID047179437

Contact:

ROBERT DIEHL

(313) 928-6800

Classification:

Large Quantity Generator

TSDF Activities: Not reported

BIENNIAL REPORTS:

Last Biennial Reporting Year: 2005

Waste F006

Quantity (Lbs) 1535535.75

Violation Status: Violations exist

Regulation Violated:

Area of Violation:

GENERATOR-RECORDKEEPING REQUIREMENTS

Date Violation Determined:

04/22/2004 09/02/2004

Not reported

Actual Date Achieved Compliance:

WRITTEN INFORMAL

Enforcement Action:

04/29/2004

Enforcement Action Date: Penalty Type:

Not reported

Regulation Violated:

Not reported

Area of Violation:

GENERATOR-PRE-TRANSPORT REQUIREMENTS

Date Violation Determined:

04/22/2004

Actual Date Achieved Compliance:

09/02/2004

Enforcement Action:

WRITTEN INFORMAL 04/29/2004

Enforcement Action Date: Penalty Type:

Not reported

Regulation Violated:

Not reported

Area of Violation:

GENERATOR-CONTAINER

Date Violation Determined:

10/23/1995 01/08/1996

Actual Date Achieved Compliance:

WRITTEN INFORMAL

Enforcement Action:

10/23/1995

Enforcement Action Date:

Penalty Type:

Not reported

Regulation Violated:

Area of Violation:

Not reported

GENERATOR-LAND BAN REQUIREMENTS

Date Violation Determined:

09/10/1993

Actual Date Achieved Compliance:

10/05/1993

Enforcement Action:

WRITTEN INFORMAL

Enforcement Action Date:

09/10/1993

Penalty Type:

Not reported

Regulation Violated:

Not reported

Area of Violation:

GENERATOR-MANIFEST REQUIREMENTS

Date Violation Determined: Actual Date Achieved Compliance: 09/10/1993 10/05/1993

Enforcement Action:

WRITTEN INFORMAL

Enforcement Action Date:

09/10/1993

Penalty Type:

Not reported

Regulation Violated:

Not reported

Area of Violation:

GENERATOR-OTHER REQUIREMENTS

Map ID Direction Distance Distance (ft.)

Elevation

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

REILLY PLATING CO (Continued)

1000289727

Date Violation Determined:

Actual Date Achieved Compliance:

09/10/1993 10/05/1993

Enforcement Action:

WRITTEN INFORMAL

Enforcement Action Date:

09/10/1993

Penalty Type:

Not reported

There are 6 violation record(s) reported at this site:

Area of Violation Compliance Evaluation Inspection

Date of Compliance

GENERATOR-PRE-TRANSPORT REQUIREMENTS GENERATOR-RECORDKEEPING REQUIREMENTS 20040902 20040902

Other Evaluation Compliance Evaluation Inspection **GENERATOR-CONTAINER** GENERATOR-LAND BAN REQUIREMENTS 19960108 19931005 19931005

GENERATOR-OTHER REQUIREMENTS GENERATOR-MANIFEST REQUIREMENTS

19931005

11 ESE SALEM MACHINE CO.-SAC PROPERTIES

LUST S102852212 N/A

1/8-1/4

17100 FRANCIS ST MELVINDALE, MI 48122

1168 ft.

Relative: Lower

LUST:

Facility Status:

Closed

Facility ID:

50000938

Actual: Owner Name: Owner Address: Nrt Owner Unknown

586 ft.

Unknown, MI 99999

Owner City, St, Zip: Country:

USA

Owner Contact:

Not reported

Owner Phone:

Not reported

District:

SE Michigan District Office

Leak Number:

C-2001-91

Release Date: Site Name:

Oct 1 1991 S. A. C. Properties

Substance Released:

Unknown

Closed Date:

Nov 12 1991

12 ssw NORFOLK SOUTHERN CORP FORB POOL 17801 DIX RD

U000267404 LUST UST N/A

1/8-1/4

MELVINDALE, MI 48122

1202 ft.

LUST:

Facility Status:

Closed

Relative: Higher

Facility ID: Owner Name: 00011817

Actual: 591 ft.

Owner Address:

Norfolk Southern Corp 8 N JEFFERSON

Owner City, St, Zip:

MELVINDALE, MI 48122

Country:

USA

Owner Contact:

Not reported

Owner Phone:

(734) 246-1995

District:

SE Michigan District Office

Leak Number:

C-0368-91

Release Date:

Mar 1 1991

Site Name:

Norfolk Southern Corp.

Substance Released: Not reported

Closed Date:

Oct 25 1996

MAP FINDINGS Map ID

Direction Distance Distance (ft.)

Elevation Site

Database(s)

EDR ID Number **EPA ID Number**

NORFOLK SOUTHERN CORP FORB POOL (Continued)

U000267404

UST:

Owner Name: Owner Address: Norfolk Southern Corp 8 N JEFFERSON MELVINDALE, MI 48122

Owner City, St, Zip: Owner Country: Owner Contact:

USA Not reported (734) 246-1995

Owner Phone: Facility ID: Contact: Contact Phone:

00011817 R.M. DIXON (313) 928-6950

Tank ID:

Tank Status: Capacity:

Removed from Ground 5000

Install Date: Product:

May 8 1951 Gasoline Aug 1 1990

Remove Date: Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Unknown

Piping Type:

Not reported Unknown

Constr Material: Impressed Device:

No

Owner Name: Owner Address:

Norfolk Southern Corp 8 N JEFFERSON MELVINDALE, MI 48122

Owner City, St, Zip: Owner Country: Owner Contact:

USA Not reported (734) 246-1995

Owner Phone: Facility ID: Contact: Contact Phone:

R.M. DIXON (313) 928-6950

00011817

Tank ID:

Tank Status:

Removed from Ground

Capacity: Install Date: Product: Remove Date:

8000 May 8 1951 Kerosene Oct 1 1990 Tank Release Detection: Not reported Pipe Realease Detection: Not reported

Piping Material: Piping Type: Constr Material: Unknown Not reported Unknown

Impressed Device:

No

13 South J & J BUILDING CO 17730 DORA ST

1/8-1/4 1232 ft.

MELVINDALE, MI 48122

Relative:

LUST:

Higher

Facility Status:

Facility ID:

Open 00035624 J & J Bldg Co

Actual: 587 ft.

Owner Name: Owner Address:

17730 Dora St

Owner City, St, Zip:

Melvindale, MI 48122-1330

Country:

USA

U003325692

N/A

LUST

UST

Map ID Direction Distance Distance (ft.) Elevation

Database(s)

EDR ID Number **EPA ID Number**

U003325692

J & J BUILDING CO (Continued)

Owner Contact:

Not reported

C-0678-99

Owner Phone:

(734) 782-1111

District:

SE Michigan District Office

Leak Number: Release Date:

Jul 13 1999

Site Name:

J & J Building Co

Substance Released:

Unknown

Closed Date:

Not reported

UST:

Owner Name:

J & J Bldg Co 17730 Dora St

Owner Address:

Melvindale, MI 48122-1330

Owner City, St, Zip: Owner Country:

USA

Owner Contact:

Not reported

Owner Phone:

(734) 782-1111 00035624

Facility ID: Contact:

JOE PUTZ

Contact Phone: Tank ID:

(734) 782-1111

Tank Status:

Removed from Ground

Capacity:

Install Date:

Not reported

Product:

WATER Oct 25 1996

Remove Date: Tank Release Detection: Not reported

Pipe Realease Detection: Not reported Piping Material:

Bare Steel

Piping Type:

Not reported

Constr Material:

Asphalt Coated or Bare Steel

Impressed Device:

No

Owner Name:

Owner Address:

J & J Bldg Co 17730 Dora St

Owner City, St, Zip:

Melvindale, MI 48122-1330

Owner Country:

USA

Owner Contact: Owner Phone:

Not reported (734) 782-1111

Facility ID:

00035624

Contact:

JOE PUTZ

Contact Phone:

(734) 782-1111

Tank ID:

Removed from Ground

Tank Status: Capacity:

Not reported

Install Date:

WATER

Product: Remove Date:

Oct 25 1996

Tank Release Detection: Not reported

Pipe Realease Detection: Not reported

Piping Material:

Bare Steel

Piping Type:

Not reported

Constr Material:

Asphalt Coated or Bare Steel

Impressed Device:

Owner Name: Owner Address: J & J Bldg Co 17730 Dora St

Owner City, St, Zip:

Melvindale, MI 48122-1330

Owner Country:

USA

Map ID Direction Distance Distance (ft.) Elevation

Database(s)

LUST

UST

U000267935

N/A

EDR ID Number **EPA ID Number**

U003325692

J & J BUILDING CO (Continued)

Owner Contact:

Not reported

Owner Phone:

(734) 782-1111 00035624

Facility ID:

JOE PUTZ

Contact: Contact Phone:

(734) 782-1111

Tank ID:

Tank Status:

Removed from Ground

Capacity:

500

Install Date: Product:

Not reported WATER

Remove Date:

Oct 25 1996

Tank Release Detection: Not reported

Pipe Realease Detection: Not reported Piping Material:

Bare Steel

Piping Type:

Not reported

Constr Material:

Asphalt Coated or Bare Steel

Impressed Device:

No

14 NE SCHAEFER SERVICE STATION

1/4-1/2

2625 SCHAEFER RD MELVINDALE, MI 48122

1347 ft.

Relative: Lower

LUST:

Facility Status:

Open

Facility ID:

00034155

Actual: 585 ft.

Schaefer Service Station

Owner Name: Owner Address:

2625 Schaefer Rd

Owner City, St, Zip:

Melvindale, MI 48122-1369

Country:

USA

Owner Contact:

Not reported (313) 382-2044

Owner Phone: District:

SE Michigan District Office

Leak Number:

C-0610-95

Release Date:

Aug 1 1995

Site Name:

Schaefer Service

Substance Released:

Unknown, Unknown

Closed Date:

Not reported

Facility Status:

Open

Facility ID:

Owner Name:

00034155 Schaefer Service Station

Owner Address:

2625 Schaefer Rd

Owner City, St, Zip: Country:

Melvindale, MI 48122-1369 USA

Owner Contact:

Not reported

Owner Phone:

(313) 382-2044

District:

SE Michigan District Office

Leak Number:

C-0869-99

Release Date:

Aug 20 1999

Site Name:

Schaefer Service

Substance Released: Unknown Closed Date:

Not reported

UST:

Owner Name:

Schaefer Service Station 2625 Schaefer Rd

Owner Address: Owner City,St,Zip:

Melvindale, MI 48122-1369

Owner Country:

USA

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number **EPA ID Number**

U000267935

SCHAEFER SERVICE STATION (Continued)

Owner Contact:

Not reported

Owner Phone:

(313) 382-2044 00034155

Facility ID: Contact:

Mustapha Akblar

Contact Phone:

(313) 382-2044

Tank ID:

Tank Status:

Removed from Ground

Capacity:

6000

Install Date: Product:

Jan 1 1989 Gasoline

Remove Date:

Aug 1 1999

Tank Release Detection: Groundwater Monitoring

Pipe Realease Detection: Not reported

Piping Material:

Galvanized Steel

Piping Type:

Not reported

Constr Material:

Asphalt Coated or Bare Steel

Impressed Device:

No

Owner Name:

Schaefer Service Station

Owner Address:

2625 Schaefer Rd

Owner City, St, Zip:

Melvindale, MI 48122-1369

Owner Country:

USA

Owner Contact:

Not reported

Owner Phone:

(313) 382-2044

Facility ID:

00034155

Contact:

Mustapha Akblar (313) 382-2044

Contact Phone: Tank ID:

Currently In Use

Tank Status: Capacity:

8000

Sep 1 1999

Install Date:

Product:

Gasoline

Remove Date:

Not reported

Tank Release Detection: Automatic Tank Gauging, Inventory Control

Pipe Realease Detection: Automatic Line Leak Detectors

Piping Material:

Double Walled, Fiberglass reinforced plastic

Piping Type:

Pressure

Constr Material:

Composite(Steel w/Fiberglass), Double Walled

Impressed Device:

Owner Name:

Schaefer Service Station

Owner Address:

2625 Schaefer Rd

Owner City,St,Zip: Owner Country:

Melvindale, MI 48122-1369 USA

Owner Contact:

Not reported

Owner Phone:

(313) 382-2044

Facility ID: Contact:

00034155 Mustapha Akblar

Contact Phone:

(313) 382-2044

Tank ID:

Tank Status:

Removed from Ground

Capacity:

6000

Install Date:

Not reported

Product:

Gasoline

Remove Date:

Aug 1 1999

Tank Release Detection: Groundwater Monitoring

Pipe Realease Detection: Not reported

Map ID Direction Distance Distance (ft.) Elevation

Database(s)

EDR ID Number **EPA ID Number**

U000267935

SCHAEFER SERVICE STATION (Continued)

Piping Material:

Galvanized Steel

Piping Type:

Not reported

Constr Material:

Asphalt Coated or Bare Steel

Impressed Device:

Owner Name: Owner Address: Schaefer Service Station 2625 Schaefer Rd

Owner City, St, Zip:

Melvindale, MI 48122-1369

Owner Country:

USA

Owner Contact: Owner Phone:

Not reported (313) 382-2044

Facility ID: Contact:

00034155 Mustapha Akblar (313) 382-2044

Contact Phone: Tank ID:

Tank Status:

Removed from Ground

Capacity:

12000 Jan 1 1986

Install Date: Product:

Diesel

Remove Date:

Aug 1 1999

Tank Release Detection: Groundwater Monitoring

Piping Material:

Pipe Realease Detection: Not reported Galvanized Steel

Piping Type:

Not reported

Constr Material:

Asphalt Coated or Bare Steel

Impressed Device:

Owner Name:

Schaefer Service Station

Owner Address: Owner City, St, Zip: 2625 Schaefer Rd Melvindale, MI 48122-1369

Owner Country:

USA

Owner Contact: Owner Phone:

Not reported (313) 382-2044 00034155

Facility ID: Contact: Contact Phone:

Mustapha Akblar (313) 382-2044

Tank ID:

Tank Status:

Removed from Ground

Capacity: Install Date:

Not reported

8000

Product:

Gasoline Aug 1 1999

Remove Date: Tank Release Detection: Groundwater Monitoring

Pipe Realease Detection: Not reported

Piping Material:

Galvanized Steel Not reported

Piping Type:

Constr Material:

Asphalt Coated or Bare Steel

Impressed Device:

Owner Name: Owner Address: Schaefer Service Station 2625 Schaefer Rd

Owner City, St, Zip: Owner Country:

Melvindale, MI 48122-1369 USA

Owner Contact: Owner Phone:

Not reported (313) 382-2044

Facility ID: Contact:

00034155 Mustapha Akblar Map ID Direction Distance Distance (ft.)

Site

Elevation

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

U000267935

SCHAEFER SERVICE STATION (Continued)

Contact Phone:

(313) 382-2044

Tank ID:

Tank Status:

Currently In Use

Capacity:

12000 Sep 1 1999

Install Date: Product:

Gasoline

Remove Date:

Not reported

Pipe Realease Detection: Automatic Line Leak Detectors

Tank Release Detection: Automatic Tank Gauging, Inventory Control

Piping Material:

Double Walled, Fiberglass reinforced plastic

Piping Type:

Pressure

Constr Material:

Composite(Steel w/Fiberglass), Double Walled

Impressed Device:

Owner Name: Owner Address: Schaefer Service Station 2625 Schaefer Rd

Owner City,St,Zip:

Melvindale, MI 48122-1369

Owner Country:

USA

Owner Contact:

Not reported

Owner Phone: Facility ID:

(313) 382-2044 00034155

Contact:

Mustapha Akblar (313) 382-2044

Contact Phone: Tank ID:

Tank Status:

Removed from Ground

Capacity:

4000

Install Date: Product:

Not reported Kerosene

Remove Date:

Aug 1 1999

Tank Release Detection: Groundwater Monitoring

Pipe Realease Detection: Not reported

Piping Material:

Galvanized Steel Not reported

Piping Type: Constr Material:

Asphalt Coated or Bare Steel

Impressed Device:

Owner Name:

Schaefer Service Station

Owner Address:

2625 Schaefer Rd

Owner City, St, Zip: Owner Country:

Melvindale, MI 48122-1369

Owner Contact:

USA

Not reported (313) 382-2044

Owner Phone:

00034155

Facility ID:

Mustapha Akblar

Contact:

(313) 382-2044

Contact Phone: Tank ID:

Tank Status:

Currently In Use

Capacity:

8000 Sep 1 1999

Install Date:

Diesel

Product: Remove Date:

Not reported

Tank Release Detection: Automatic Tank Gauging, Inventory Control

Pipe Realease Detection: Automatic Line Leak Detectors

Piping Material:

Double Walled, Fiberglass reinforced plastic

Piping Type:

Composite(Steel w/Fiberglass), Double Walled

Constr Material: Impressed Device:

No

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number **EPA ID Number**

U000267935

SCHAEFER SERVICE STATION (Continued)

Owner Name:

Schaefer Service Station

Owner Address:

2625 Schaefer Rd

Owner City,St,Zip:

Melvindale, MI 48122-1369

Owner Country:

USA

Owner Contact: Owner Phone:

Not reported (313) 382-2044

Facility ID:

00034155

Contact:

Mustapha Akblar

Contact Phone: Tank ID:

(313) 382-2044

Tank Status:

Currently In Use

Capacity: Install Date: 4000 Sep 1 1999

Product:

Kerosene

Remove Date:

Not reported

Tank Release Detection: Automatic Tank Gauging, Inventory Control

Pipe Realease Detection: Automatic Line Leak Detectors

Piping Material:

Double Walled, Fiberglass reinforced plastic

Piping Type:

Pressure

Constr Material:

Composite(Steel w/Fiberglass), Double Walled

Impressed Device:

15

WORLD CLASS AUTO WASH

RCRA-SQG

1001493328

East 1/4-1/2 2311 S SCHAFER **MELVINDALE, MI 48122** **FINDS** LUST

UST

MIR000041673

1392 ft. Relative:

RCRAInfo:

Owner: EPA ID: WORLD CLASS AUTO WASH MIR000041673

Actual: 585 ft.

Lower

Contact:

KAL RABAN

(619) 660-6144

Classification:

Small Quantity Generator

TSDF Activities: Not reported

Violation Status: No violations found

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

corrective action activities required under RCRA.

LUST:

Facility Status:

Closed

Facility ID:

00040074

Owner Name: Owner Address: World Class Autowash

Owner City, St, Zip:

2311 Schaefer Rd Melvindale, MI 48122-1355

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

1001493328

WORLD CLASS AUTO WASH (Continued)

Country:

USA

Owner Contact:

Not reported

Owner Phone: District:

(313) 386-4730

Leak Number:

SE Michigan District Office C-0264-99

Release Date:

Mar 8 1999

Site Name:

World Class Autowash

Substance Released: Unknown

Dec 7 2000 Closed Date:

UST:

Owner Name:

World Class Autowash 2311 Schaefer Rd

Owner Address:

Melvindale, MI 48122-1355

Owner City, St, Zip: Owner Country:

USA

Owner Contact: Owner Phone: Facility ID:

Not reported (313) 386-4730 00040074

Contact: Contact Phone:

KAL RABAN (313) 386-4730

Tank ID:

Tank Status:

Removed from Ground

Capacity:

Install Date: Product:

Not reported Used Oil Mar 17 1999

Remove Date: Tank Release Detection: Not reported Pipe Realease Detection: Not reported

Piping Material: Piping Type:

Unknown

Constr Material:

Not reported

Asphalt Coated or Bare Steel

Impressed Device:

16 NE 1/4-1/2

FUEL MART OF AMERICA INC 335 S SCHAEFER HWY DETROIT, MI 48217

1409 ft.

LUST:

Relative: Lower

Facility Status:

Closed

Facility ID:

00036546

Actual: Owner Name: 585 ft.

Mustapha Akhdar 335 S Schaefer Hwy

Owner Address:

Detroit, MI 48217-1356

Owner City, St, Zip: Country:

USA

Owner Contact:

Not reported

Owner Phone:

(313) 842-8500

District:

SE Michigan District Office

Leak Number:

C-0489-93

Release Date:

Apr 26 1993

Site Name:

Long Dollar Truck Stop

Substance Released: Diesel, Gasoline

Closed Date:

Nov 29 1995

UST:

Owner Name:

Owner Address:

Mustapha Akhdar 335 S Schaefer Hwy Detroit, MI 48217-1356

Owner City,St,Zip: Owner Country:

USA

LUST

UST

U003160812

N/A

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

U003160812

FUEL MART OF AMERICA INC (Continued)

Owner Contact:

Not reported

Owner Phone:

(313) 842-8500

Facility ID: Contact:

00036546 Mustapha Akhdar

Contact Phone:

(313) 842-8500

Tank ID:

Tank Status:

Removed from Ground

3000

Capacity: Install Date:

Not reported

Product: Remove Date:

Gasoline Apr 26 1993 Tank Release Detection: Not reported

Pipe Realease Detection: Not reported Piping Material:

Galvanized Steel

Piping Type:

Suction: No Valve At Tank

Constr Material:

Asphalt Coated or Bare Steel

Impressed Device:

No

Owner Name:

Mustapha Akhdar

Owner Address: Owner City, St, Zip: 335 S Schaefer Hwy Detroit, MI 48217-1356

Owner Country:

USA

Owner Contact:

Not reported

Owner Phone:

(313) 842-8500 00036546

Facility ID: Contact:

Mustapha Akhdar

Contact Phone:

(313) 842-8500

Tank ID:

Currently In Use

Tank Status: Capacity:

12000

Jul 10 1995

Install Date: Product:

Diesel

Remove Date:

Not reported

Tank Release Detection: Inventory Control, Automatic Tank Gauging

Pipe Realease Detection: Automatic Line Leak Detectors, Line Tightness Testing

Piping Material:

Fiberglass Reinforced Plastic

Piping Type:

Pressure

Constr Material:

Double Walled, Polyethylene Tank Jacket

Impressed Device:

No

Owner Name:

Mustapha Akhdar

Owner Address:

335 S Schaefer Hwy

Owner City, St, Zip: Owner Country:

Detroit, MI 48217-1356

Owner Contact:

USA Not reported

Owner Phone:

(313) 842-8500 00036546

Facility ID: Contact:

Mustapha Akhdar (313) 842-8500

Contact Phone: Tank ID:

Tank Status:

Removed from Ground

Capacity:

10000

Install Date:

Jan 1 1960

Product:

Gasoline

Remove Date: Tank Release Detection: Not reported

Apr 26 1993

Pipe Realease Detection: Not reported

Map ID Direction Distance Distance (ft.) Elevation

Database(s)

EDR ID Number **EPA ID Number**

U003160812

FUEL MART OF AMERICA INC (Continued)

Piping Material:

Galvanized Steel

No

Piping Type:

Suction: No Valve At Tank, Suction: Valve at Tank

Constr Material:

Asphalt Coated or Bare Steel

Impressed Device:

Owner Name: Owner Address: Mustapha Akhdar 335 S Schaefer Hwy Detroit, MI 48217-1356

Owner City,St,Zip: Owner Country:

USA Owner Contact: Not reported (313) 842-8500 Owner Phone: Facility ID: 00036546 Contact: Mustapha Akhdar (313) 842-8500 Contact Phone:

Tank ID:

Tank Status:

Removed from Ground

Capacity:

4000

Install Date:

Not reported

Gasoline Product: Apr 26 1993 Remove Date: Tank Release Detection: Not reported Pipe Realease Detection: Not reported

Piping Material: Piping Type:

Galvanized Steel Suction: No Valve At Tank

Constr Material:

Asphalt Coated or Bare Steel

Impressed Device:

No

Owner Name: Owner Address: Mustapha Akhdar 335 S Schaefer Hwy Detroit, MI 48217-1356

Owner City, St, Zip: Owner Country: Owner Contact:

USA Not reported

Owner Phone: Facility ID: Contact:

Contact Phone:

00036546 Mustapha Akhdar (313) 842-8500

(313) 842-8500

Tank ID:

Tank Status:

Currently In Use 12000

Capacity: Install Date: Product:

Jul 10 1995 Gasoline Not reported

Remove Date:

Tank Release Detection: Inventory Control, Automatic Tank Gauging

Pipe Realease Detection: Automatic Line Leak Detectors, Line Tightness Testing

Piping Material:

Double Walled, Flexible Piping

Piping Type:

Constr Material:

Double Walled, Polyethylene Tank Jacket

Impressed Device:

No

Owner Name: Owner Address: Owner City, St, Zip: Mustapha Akhdar 335 S Schaefer Hwy Detroit, MI 48217-1356

Owner Country: Owner Contact: USA

Owner Phone: Facility ID:

Not reported (313) 842-8500 00036546

Contact:

Mustapha Akhdar

Map ID Direction Distance Distance (ft.) Elevation

Database(s)

EDR ID Number EPA ID Number

U003160812

FUEL MART OF AMERICA INC (Continued)

Contact Phone:

(313) 842-8500

Tank ID:

10

Tank Status:

Currently In Use

Capacity:

8000 Jul 10 1995

Install Date: Product:

Diesel

Remove Date:

Not reported

Tank Release Detection: Inventory Control, Automatic Tank Gauging

Pipe Realease Detection: Automatic Line Leak Detectors, Line Tightness Testing

Piping Material:

Fiberglass Reinforced Plastic

Piping Type:

Pressure

Constr Material:

Double Walled, Polyethylene Tank Jacket

Impressed Device:

Owner Name: Owner Address: Mustapha Akhdar 335 S Schaefer Hwy

Owner City, St, Zip: Owner Country:

Owner Contact:

Detroit, MI 48217-1356 USA

Owner Phone:

Not reported (313) 842-8500

Facility ID:

00036546 Mustapha Akhdar

Contact: Contact Phone:

(313) 842-8500

Tank ID:

Tank Status:

Removed from Ground

Capacity: Install Date:

10000 Jan 1 1960

Product: Diesel Remove Date: Apr 26 1993 Tank Release Detection: Not reported

Pipe Realease Detection: Not reported Piping Material:

Galvanized Steel Suction: Valve at Tank

Piping Type: Constr Material:

Asphalt Coated or Bare Steel

Impressed Device:

No

Owner Name: Owner Address: Mustapha Akhdar 335 S Schaefer Hwy Detroit, MI 48217-1356

Owner City, St, Zip: Owner Country:

USA Not reported

Owner Contact: Owner Phone: Facility ID:

(313) 842-8500 00036546 Mustapha Akhdar

Contact: Contact Phone:

(313) 842-8500

Tank ID: Tank Status:

Currently In Use

Capacity: Install Date:

10000 Jul 10 1995

Product: Remove Date: Gasoline Not reported

Tank Release Detection: Inventory Control, Automatic Tank Gauging

Pipe Realease Detection: Automatic Line Leak Detectors, Line Tightness Testing

Piping Material:

Double Walled, Flexible Piping

Piping Type:

Pressure

Constr Material:

Double Walled, Polyethylene Tank Jacket

Impressed Device:

Map ID Direction Distance Distance (ft.) Elevation

Database(s)

EDR ID Number EPA ID Number

U003160812

FUEL MART OF AMERICA INC (Continued)

Owner Name:

Mustapha Akhdar

Owner Address: Owner City,St,Zip: 335 S Schaefer Hwy Detroit, MI 48217-1356

Owner Country:

USA

Owner Contact: Owner Phone:

Not reported (313) 842-8500

Facility ID: Contact:

00036546

Contact Phone:

Mustapha Akhdar (313) 842-8500

Tank ID:

Tank Status: Capacity:

Currently In Use 12000

Install Date: Product:

Jul 10 1995 Diesel

Remove Date:

Not reported

Tank Release Detection: Inventory Control, Automatic Tank Gauging

Pipe Realease Detection: Automatic Line Leak Detectors, Line Tightness Testing

Piping Material:

Fiberglass Reinforced Plastic

Piping Type:

Pressure

Constr Material:

Double Walled, Polyethylene Tank Jacket

Impressed Device:

No

Owner Name:

Mustapha Akhdar 335 S Schaefer Hwy

Owner Address: Owner City, St, Zip:

Detroit, MI 48217-1356

Owner Country:

USA

Owner Contact: Owner Phone:

Not reported (313) 842-8500

Facility ID:

00036546 Mustapha Akhdar

Contact: Contact Phone:

(313) 842-8500

Tank ID:

Tank Status:

Currently In Use 8000

Capacity: Install Date:

Jul 10 1995

Product:

Gasoline

Remove Date:

Not reported

Tank Release Detection: Inventory Control, Automatic Tank Gauging Pipe Realease Detection: Automatic Line Leak Detectors, Line Tightness Testing

Piping Material:

Double Walled, Flexible Piping

Piping Type:

Pressure

Constr Material:

Double Walled, Polyethylene Tank Jacket

Impressed Device:

SCHAEFER RD E GREENFIELD RD WS N BUTLER

17 NNE RIVER ROUGE FILL AREA

CERCLIS 1000211215 FINDS MID985569144

1/4-1/2 MELVINDALE, MI 48122

1502 ft.

CERCLIS: Relative:

Lower

Site ID:

0506152

Actual:

Federal Facility: NPL Status:

Not a Federal Facility Not on the NPL

Non NPL Status:

582 ft.

Other Cleanup Activity: State-Lead Cleanup

CERCLIS Site Alias Name(s):

Alias Name:

RIVER ROUGE FILL AREA

Map ID Direction Distance Distance (ft.) Elevation Site MAP FINDINGS

Database(s)

EDR ID Number **EPA ID Number**

1000211215

RIVER ROUGE FILL AREA (Continued)

Alias Address:

Not reported

WAYNE, MI

Site Description: Not reported

CERCLIS Assessment History:

Action:

DISCOVERY Not reported

Date Started: Date Completed:

08/17/1988

Priority Level:

Not reported

Action: Date Started: UNILATERAL ADMIN ORDER Not reported

Date Completed:

05/03/1990

Priority Level:

Not reported

Action:

ADMINISTRATIVE ORDER ON CONSENT

Date Started:

Not reported 06/06/1990

Date Completed: Priority Level:

Not reported

Action:

POTENTIALLY RESPONSIC admin.cpad log.error_number%TYPE;BLE PARTY

REMOVAL

Date Started:

05/03/1990

Date Completed:

06/08/1990

Priority Level:

Stabilized

Action:

PRELIMINARY ASSESSMENT

Date Started: Date Completed: Not reported 08/05/1991

Priority Level:

High

Action:

SITE INSPECTION

Date Started: Date Completed: Not reported 09/30/1992

Priority Level:

Low

FINDS:

Other Pertinent Environmental Activity Identified at Site

CERCLIS (Comprehensive Environmental Response, Compensation, and Liability Information System) is the Superfund database that is used to support management in all phases of the Superfund program. The system contains information on all aspects of hazardous waste sites, including an inventory of sites, planned and actual site activities, and financial information.

Map ID Direction Distance Distance (ft.) Elevation

Database(s)

LUST

UST

EDR ID Number EPA ID Number

U003325696

N/A

18

CAPITOL INVESTMENT PROPERTIES

ESE 17065 HESS ST 1/4-1/2

MELVINDALE, MI 48122

1683 ft.

Relative:

LUST:

Lower

Facility Status: Closed Facility ID: 00035653 Capitol Investment Prop

Actual: Owner Name: 585 ft. Owner Address:

17065 Hess St Melvindale, MI 48122-1342

Owner City, St, Zip: Country: Owner Contact:

USA Not reported (313) 928-4000

Owner Phone: District:

SE Michigan District Office

Leak Number: Release Date: C-0939-98

Oct 9 1998 Site Name: Capitol Investment Properties

Substance Released:

Unknown, Unknown

Closed Date:

Jan 5 1999

UST:

Owner Name:

Capitol Investment Prop

Owner Address:

17065 Hess St

Owner City,St,Zip:

Melvindale, MI 48122-1342 USA

Owner Country: Owner Contact: Owner Phone:

Not reported (313) 928-4000 00035653

Facility ID: Contact:

MICHAEL A MARTORANO

Contact Phone:

(248) 926-1199

Tank ID:

Tank Status: Removed from Ground

Capacity: 10000 Not reported Install Date: Used Oil Product:

Remove Date: Dec 18 1992 Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Bare Steel

Piping Type:

Suction: No Valve At Tank

Constr Material:

Unknown

Impressed Device:

Owner Name:

Capitol Investment Prop 17065 Hess St

Owner Address: Owner City, St, Zip:

Melvindale, MI 48122-1342

Owner Country:

USA Not reported

Owner Contact: Owner Phone: Facility ID:

(313) 928-4000 00035653

Contact:

MICHAEL A MARTORANO

Contact Phone:

(248) 926-1199

Tank ID:

Tank Status:

Removed from Ground

Capacity: Install Date: Product:

10000 Not reported Diesel

Remove Date:

Sep 30 1998

Tank Release Detection: Not reported

Map ID Direction Distance Distance (ft.) Elevation

Database(s)

EDR ID Number EPA ID Number

U003325696

CAPITOL INVESTMENT PROPERTIES (Continued)

Pipe Realease Detection: Not reported

Piping Material:

Bare Steel

Piping Type:

Suction: No Valve At Tank Asphalt Coated or Bare Steel

Constr Material: Impressed Device:

Owner Name:

Capitol Investment Prop

Owner Address:

17065 Hess St

Owner City,St,Zip: Owner Country:

Melvindale, MI 48122-1342 USA

Owner Contact:

Not reported

Owner Phone:

(313) 928-4000 00035653

Facility ID: Contact:

MICHAEL A MARTORANO

Contact Phone:

(248) 926-1199

Tank ID:

Tank Status:

Removed from Ground

Capacity:

10000

Install Date: Product:

Not reported Gasoline Sep 30 1998

Remove Date: Tank Release Detection: Not reported Pipe Realease Detection: Not reported

Piping Material:

Bare Steel

Piping Type: Constr Material: Suction: No Valve At Tank Asphalt Coated or Bare Steel

Impressed Device:

Owner Name:

Capitol Investment Prop

Owner Address:

17065 Hess St

Owner City, St, Zip:

Melvindale, MI 48122-1342

Owner Country:

USA

Owner Contact: Owner Phone:

Not reported (313) 928-4000 00035653

Facility ID: Contact:

MICHAEL A MARTORANO

Contact Phone:

(248) 926-1199

Tank ID:

Tank Status: Capacity:

Removed from Ground 10000

Install Date: Product:

Not reported Diesel Sep 30 1998

Remove Date: Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Bare Steel

Piping Type:

Suction: No Valve At Tank

Constr Material:

Asphalt Coated or Bare Steel

Impressed Device:

MAP FINDINGS Map ID

Direction Distance Distance (ft.)

Elevation Site Database(s)

EDR ID Number EPA ID Number

19 **RIVER ROUGE**

NNE 1/4-1/2 1978 ft. SCHAEFER HWY BRIDGE MELVINDALE, MI 48122

CERC-NFRAP

1000211214 MID981532955

Relative:

Lower

CERC-NFRAP: Site ID:

Federal Facility:

0503612

NPL Status:

Not a Federal Facility Not on the NPL

Actual: 579 ft.

Non NPL Status:

NFRAP

CERCLIS-NFRAP Site Contact Name(s):

Contact Name:

LORETTA KROETSCH

Contact Tel:

Not reported

Contact Title:

On-Scene Coordinator (OSC)

Site Description: Not reported

CERCLIS-NFRAP Assessment History:

Action:

DISCOVERY Not reported

Date Started: Date Completed:

10/28/1985

Priority Level:

Not reported

Action:

PRELIMINARY ASSESSMENT Not reported

Date Started: Date Completed:

01/07/1986

Priority Level:

High

Action: Date Started: PRELIMINARY ASSESSMENT

Date Completed:

Not reported 03/27/1990

Priority Level:

NFRAP (No Futher Remedial Action Planned

Action: Date Started:

Not reported 07/06/2001

ARCHIVE SITE

Date Completed:

Priority Level: Not reported

20

REFINERS TRANSPORT & TERMINAL CORP

RCRA-SQG

WNN 1/4-1/2 2015 ft.

3335 GREENFIELD RD **MELVINDALE, MI 48122**

MID017236803 **FINDS** LUST UST

1000256539

Relative: Lower

RCRAInfo:

Contact:

MICHAEL TOWER

(313) 382-8500

Actual: 584 ft.

Classification:

Small Quantity Generator TSDF Activities: Not reported

Violation Status: Violations exist

Regulation Violated:

Not reported

Area of Violation:

TRANSPORTER-OTHER REQUIREMENTS

Date Violation Determined: Actual Date Achieved Compliance: 06/21/1995 03/03/1997

Enforcement Action:

WRITTEN INFORMAL

Enforcement Action Date:

06/21/1995

Penalty Type:

Not reported

Map ID Direction Distance Distance (ft.) Elevation Site MAP FINDINGS

Database(s)

EDR ID Number **EPA ID Number**

REFINERS TRANSPORT & TERMINAL CORP (Continued)

1000256539

Regulation Violated:

Not reported

Area of Violation:

TRANSPORTER-ALL REQUIREMENTS (OVERSIGHT)

Date Violation Determined:

07/19/1993

Actual Date Achieved Compliance:

03/03/1997

Enforcement Action:

WRITTEN INFORMAL

Enforcement Action Date:

07/21/1993

Penalty Type:

Not reported

Regulation Violated:

Not reported

Area of Violation:

TRANSPORTER-OTHER REQUIREMENTS

Date Violation Determined: Actual Date Achieved Compliance:

06/11/1992 07/23/1992

Enforcement Action:

WRITTEN INFORMAL

Enforcement Action Date:

06/11/1992

Penalty Type:

Not reported

Regulation Violated:

Not reported

Area of Violation:

Date Violation Determined:

GENERATOR-ALL REQUIREMENTS (OVERSIGHT)

Actual Date Achieved Compliance:

07/10/1990

Enforcement Action:

11/08/1990

Enforcement Action Date:

WRITTEN INFORMAL 07/11/1990

Penalty Type:

Not reported

There are 4 violation record(s) reported at this site:

a second second a second secon		Date of
Evaluation	Area of Violation	Compliance
Compliance Evaluation Inspection	TRANSPORTER-OTHER REQUIREMENTS	19970303
Compliance Evaluation Inspection	TRANSPORTER-OTHER REQUIREMENTS	19970303
Compliance Evaluation Inspection	TRANSPORTER-ALL REQUIREMENTS (OVERSIGHT)	19970303
Compliance Evaluation Inspection	TRANSPORTER-OTHER REQUIREMENTS	19920723
Compliance Evaluation Inspection	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	19901108

FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste, RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

LUST:

Facility Status:

Closed

Facility ID:

00015693

Owner Name: Owner Address: Armada Oil & Gas Co Inc 13530 Michigan Ave Suite #400

Owner City, St, Zip:

Dearborn, MI 48126-3575

Country:

USA

Owner Contact:

Allie Berry

Owner Phone:

(313) 582-1777

District:

SE Michigan District Office

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number **EPA ID Number**

1000256539

REFINERS TRANSPORT & TERMINAL CORP (Continued)

Leak Number:

C-0604-98 Jul 13 1998

Release Date: Site Name:

Armada Oil & Gas

Substance Released: Closed Date:

Unknown Apr 20 1999

UST:

Owner Name:

Armada Oil & Gas Co Inc

Owner Address: Owner City, St, Zip: 13530 Michigan Ave Suite #400 Dearborn, MI 48126-3575

Owner Country:

USA

Owner Contact:

Allie Berry

Owner Phone: Facility ID:

(313) 582-1777 00015693

Contact:

ALLIC BERRY

Contact Phone:

Tank ID:

(313) 582-1777

Tank Status:

Removed from Ground

Capacity:

10000

Install Date:

Apr 10 1980

Product:

Diesel

Remove Date: Tank Release Detection: Not reported

Jul 1 1998

Pipe Realease Detection: Not reported

Piping Material: Piping Type:

Bare Steel Suction: Valve at Tank

Constr Material:

Asphalt Coated or Bare Steel

Impressed Device:

Owner Name:

Armada Oil & Gas Co Inc.

Owner Address: Owner City, St, Zip: 13530 Michigan Ave Suite #400 Dearborn, MI 48126-3575

Owner Country:

USA

Owner Contact:

Allie Berry (313) 582-1777

Owner Phone: Facility ID:

00015693

Contact:

ALLIC BERRY

Contact Phone:

Tank ID:

(313) 582-1777

Tank Status:

Removed from Ground

Capacity: 12000

Install Date:

Apr 10 1962

Product:

Diesel

Remove Date:

Jul 1 1998

Tank Release Detection: Not reported

Pipe Realease Detection: Not reported

Piping Material:

Bare Steel

Piping Type:

Suction: Valve at Tank Asphalt Coated or Bare Steel

Constr Material: Impressed Device:

Owner Name:

Armada Oil & Gas Co Inc

Owner Address:

13530 Michigan Ave Suite #400

Owner City, St, Zip:

Dearborn, MI 48126-3575

Owner Country:

USA

Owner Contact: Owner Phone:

Allie Berry (313) 582-1777

Facility ID:

00015693

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

Database(s)

EDR ID Number EPA ID Number

1000256539

REFINERS TRANSPORT & TERMINAL CORP (Continued)

ALLIC BERRY

Contact Phone: (313

(313) 582-1777

Tank ID:

Tank Status: Removed from Ground

Capacity: 5000 Install Date: Apr 10 1962 Product: Used Oil Remove Date: Jul 1 1998

Tank Release Detection: Not reported Pipe Realease Detection: Not reported Piping Material: Bare Steel

Piping Type: Suction: Valve at Tank
Constr Material: Asphalt Coated or Bare Steel

Impressed Device:

Owner Name: Armada Oil & Gas Co Inc
Owner Address: 13530 Michigan Ave Suite #400
Owner City,St,Zip: Dearborn, MI 48126-3575

Owner Country: USA
Owner Contact: Allie Berry

Owner Phone: (313) 582-1777
Facility ID: 00015693
Contact: ALLIC BERRY
Contact Phone: (313) 582-1777

Tank ID:

Tank Status: Removed from Ground

Capacity: 3400
Install Date: Apr 10 1984
Product: Used Oil
Remove Date: Jul 1 1998
Tank Release Detection: Not reported

Pipe Realease Detection: Not reported Piping Material: Bare Steel

Piping Type: Suction: Valve at Tank
Constr Material: Asphalt Coated or Bare Steel

Impressed Device:

Owner Name: Armada Oil & Gas Co Inc
Owner Address: 13530 Michigan Ave Suite #400
Owner City,St,Zip: Dearborn, MI 48126-3575

Owner Country: USA
Owner Contact: Allie Berry
Owner Phone: (313) 582-1777
Facility ID: 00015693
Contact: ALLIC BERRY

Contact Phone: (313) 582-1777
Tank ID: 5

Tank Status: Removed from Ground
Capacity: 2000

Capacity: 2000
Install Date: Apr 10 1962
Product: Used Oil
Remove Date: Jul 1 1998
Tank Release Detection: Not reported

Pipe Realease Detection: Not reported
Piping Material:
Piping Type:
Suction: Valve

Piping Type: Suction: Valve at Tank
Constr Material: Asphalt Coated or Bare Steel

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

RCRA-SQG

1000241524

MID985567817

EDR ID Number EPA ID Number

1000256539

REFINERS TRANSPORT & TERMINAL CORP (Continued)

Impressed Device:

Owner Name: Owner Address: Armada Oil & Gas Co Inc 13530 Michigan Ave Suite #400

Owner City, St, Zip:

Dearborn, MI 48126-3575 USA

Owner Country: Owner Contact:

Allie Berry (313) 582-1777 Owner Phone:

Facility ID: Contact: Contact Phone: 00015693 ALLIC BERRY (313) 582-1777

Tank ID:

Tank Status:

Removed from Ground

Capacity: Install Date: Product:

Remove Date:

2000 Not reported Used Oil Jul 1 1998

Tank Release Detection: Inventory Control Pipe Realease Detection: Not reported Piping Material:

Bare Steel

Piping Type: Constr Material: Suction: Valve at Tank Asphalt Coated or Bare Steel

Impressed Device: No

21 NNW 1/4-1/2 JDS CERTIFIED TRUCK REPAIR INC

3345 GREENFIELD **MELVINDALE, MI 48122** **FINDS** LUST UST

Relative:

Lower

2123 ft.

RCRAInfo:

Owner: EPA ID: GERALDINE RAYLE MID985567817

Actual: 583 ft.

Contact:

GERALDINE RAYLE (313) 383-4100

Conditionally Exempt Small Quantity Generator Classification:

TSDF Activities: Not reported Violation Status: Violations exist

Regulation Violated:

Not reported

Area of Violation: Date Violation Determined: GENERATOR-LAND BAN REQUIREMENTS

Actual Date Achieved Compliance:

12/18/1992 06/30/1993

Enforcement Action:

WRITTEN INFORMAL

Enforcement Action Date: Penalty Type:

12/18/1992 Not reported

Regulation Violated:

Not reported

Area of Violation:

GENERATOR-OTHER REQUIREMENTS

Date Violation Determined: Actual Date Achieved Compliance: 12/18/1992 06/30/1993

Enforcement Action:

Enforcement Action Date:

WRITTEN INFORMAL 12/18/1992

Penalty Type:

Not reported

There are 2 violation record(s) reported at this site:

Evaluation

Area of Violation

Date of Compliance Map ID MAP FINDINGS

Direction Distance Distance (ft.)

Elevation Site Database(s)

EDR ID Number EPA ID Number

JDS CERTIFIED TRUCK REPAIR INC (Continued)

1000241524

Compliance Evaluation Inspection

GENERATOR-LAND BAN REQUIREMENTS GENERATOR-OTHER REQUIREMENTS

19930630 19930630

FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

LUST:

Facility Status:

Closed

Facility ID:

00036879

Owner Name:

Vasilios C Madias Nave Inc

Owner Address:

3345 Greenfield Rd

Owner City, St, Zip:

Melvindale, MI 48122-1241

Country:

USA

Owner Contact:

Not reported (313) 382-9701

Owner Phone:

SE Michigan District Office

District: Leak Number:

C-0931-96

Release Date:

Nov 12 1996

Site Name: Substance Released: Hyman Freighting

Closed Date:

Diesel

Jun 30 1997

UST:

Owner Name: Owner Address: Vasilios C Madias Nave Inc

Owner City, St, Zip:

3345 Greenfield Rd

Owner Country:

Melvindale, MI 48122-1241 USA

Owner Contact: Owner Phone:

Not reported (313) 382-9701

Facility ID: Contact:

00036879 **GARY BERNDT**

Contact Phone:

(313) 582-2219

Tank ID:

Tank Status:

Removed from Ground

Capacity: Install Date: 8000

Product:

Not reported Diesel

Remove Date:

Nov 12 1996

Pipe Realease Detection: Not reported

Tank Release Detection: Inter Monitoring Double Walled Tank

Piping Material:

Galvanized Steel

Piping Type:

Pressure

Constr Material:

Composite(Steel w/Fiberglass)

Impressed Device:

Owner Name:

Vasilios C Madias Nave Inc

Owner Address:

3345 Greenfield Rd

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

LUST

UST

1000314507

N/A

EDR ID Number **EPA ID Number**

1000241524

JDS CERTIFIED TRUCK REPAIR INC (Continued)

Owner City,St,Zip:

Melvindale, MI 48122-1241

Owner Country:

USA

Owner Contact: Owner Phone:

Not reported (313) 382-9701

Facility ID: Contact:

00036879 **GARY BERNDT**

Contact Phone: Tank ID:

(313) 582-2219

Tank Status:

Removed from Ground

Capacity: Install Date:

10000 Not reported

Product: Remove Date:

Diesel Nov 12 1996 Tank Release Detection: Not reported Pipe Realease Detection: Not reported

Piping Material:

Galvanized Steel

Piping Type:

Pressure

Constr Material:

Composite(Steel w/Fiberglass)

Impressed Device:

No

22 South **EBONEX CORP**

2380 S WABASH ST MELVINDALE, MI 48122

1/4-1/2 2314 ft.

Relative: Higher

LUST:

Facility Status: Facility ID:

Closed 00035097

Actual: 588 ft.

Owner Name:

Michael F. Szczepanik 9934 Sterling Ave

Owner Address: Owner City, St, Zip: Country:

Allen Park, MI 48101-1331 USA

Owner Contact: Owner Phone:

Not reported (313) 381-5977

District: Leak Number: SE Michigan District Office

Release Date: Site Name:

C-1002-91 May 23 1991 **Ebonex Corp**

Substance Released: Closed Date:

Not reported Nov 6 1991

UST:

Owner Name:

Michael F. Szczepanik 9934 Sterling Ave

Owner Address: Owner City, St, Zip:

Allen Park, MI 48101-1331 USA

Owner Country: Owner Contact:

Not reported (313) 381-5977 Owner Phone: Facility ID: 00035097

Contact:

MICHAEL F. SZCZEPANIK

Contact Phone:

(313) 388-0060

Tank ID:

Tank Status:

Removed from Ground

Capacity: Install Date:

2000 Apr 11 1991 Gasoline Product: Remove Date: Jul 18 1991 Tank Release Detection: Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

EBONEX CORP (Continued)

1000314507

Pipe Realease Detection: Not reported

Piping Material:

Galvanized Steel, Unknown Suction: No Valve At Tank

Piping Type: Constr Material:

Impressed Device:

Unknown No

23 NNW MELVINDALE CITY OF DPW

RCRA-SQG **FINDS**

CERC-NFRAP

1000908878 MID981189996

1/4-1/2 2349 ft. 3315 GREENFIELD

MELVINDALE, MI 48122

Relative: Lower

RCRAInfo:

Owner:

MELVINDALE CITY OF

EPA ID:

MID981189996

Actual: 580 ft.

Contact:

ERIC WITTE

(313) 389-1129

Classification:

Conditionally Exempt Small Quantity Generator

TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CERC-NFRAP:

Site ID:

0503539

Federal Facility:

Not a Federal Facility

NPL Status: Non NPL Status: Not on the NPL **NFRAP**

Site Description: Not reported

CERCLIS-NFRAP Assessment History:

Action:

DISCOVERY

Date Started:

Not reported 12/31/1985

Date Completed:

Priority Level:

Not reported

Action: Date Started: ARCHIVE SITE Not reported

Date Completed:

12/11/1987

Priority Level:

Not reported

Action:

PRELIMINARY ASSESSMENT

Date Started:

Not reported

Date Completed: Priority Level:

12/11/1987 NFRAP (No Futher Remedial Action Planned Map ID MAP FINDINGS

Direction Distance Distance (ft.)

EDR ID Number **EPA ID Number** Elevation Site Database(s)

24 BEA S105768266 East 1155 OAKWOOD N/A

1/4-1/2 DETROIT, MI

2367 ft.

BEA: Relative:

Secondary Address: Not reported Lower BEA Number: 1747

Southeast MI Actual: District:

584 ft. Date Received: 2002-07-12 00:59:00

Submitter Name: Marathon Ashland Petroleum LLC Petition Determination: No Request

Petition Disclosure:

No Hazardous Substance(s) Category:

Determination 20107A: No Request Reviewer: thorntop

Division Assigned: **Environmental Response Division**

25 MILL STEEL, THE S105542124 N/A

18030 RIALTO STREET South 1/4-1/2 **MELVINDALE CITY, MI 48122**

2439 ft.

Actual:

579 ft.

BEA: Relative:

Secondary Address: Not reported Lower

BEA Number: 1781 Actual: District: Southeast MI

586 ft. Date Received: 2002-08-16 00:59:00 Mill Steel Company Submitter Name:

Affirmed Petition Determination:

Petition Disclosure:

Same Hazardous Substance(s) Category:

Determination 20107A: No Request Reviewer: owensp

Division Assigned: **Environmental Response Division**

26 LEVY EDW C CO PLT 6 RCRA-SQG 1000439958 NE **13950 MELON RD FINDS** MID094549425

1/2-1 DETROIT, MI 48217 **RCRA-TSDF** 3240 ft. CORRACTS

RCRAInfo Corrective Action Summary: Relative:

Event: Current Human Exposures under Control, Yes, Current Human Exposures Under Lower

Control has been verified. Based on a review of information contained in the El determination, current human exposures are expected to be under control at the facility under current and reasonably expected conditions. This

determination will be re-evaluated when the Agency/State becomes aware of

significant changes at the facility.

Event Date: 11/04/1999

Igration of Contaminated Groundwater under Control, Yes, Migration of Event:

Contaminated Groundwater Under Control has been verified. Based on a review of information contained in the El determination, it has been determined that migration of contaminated groundwater is under control at the facility.

Specifically, this determination indicates that the migration of

contaminated groundwater is under control, and that monitoring will be conducted to confirm that contaminated groundwater remains within the existing area of contaminated groundwater. This determination will be re-evaluated when the Agency becomes aware of significant changes at the

facility.

MAP FINDINGS Map ID Direction

Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number **EPA ID Number**

1000439958

LEVY EDW C CO PLT 6 (Continued)

Event Date:

11/04/1999

Event:

CA Prioritization, Facility or area was assigned a low corrective action

priority.

Event Date:

09/27/1991

Event:

RFA Completed 04/06/1988

Event Date:

Event:

RFA Determination Of Need For An RFI, RFI is Not Necessary;

Event Date:

04/06/1988

RCRAInfo:

Owner:

EDWARD C LEVY COMPANY

EPA ID:

MID094549425

Contact:

FRANK RIORDAN

(313) 843-7200

TSDF Classification: TSDF Activities: Not reported Violation Status: Violations exist

Regulation Violated:

Not reported

Area of Violation:

TSD-PERMIT CONDITION

Date Violation Determined:

12/18/2001 02/19/2002

Actual Date Achieved Compliance:

WRITTEN INFORMAL

Enforcement Action Date:

Enforcement Action:

12/18/2001

Penalty Type:

Not reported

Regulation Violated:

40 cfr262.12,268.7

Area of Violation:

GENRATOR-SQG REQUIREMENTS 08/23/1999

Date Violation Determined: Actual Date Achieved Compliance:

12/12/2005

Enforcement Action:

WRITTEN INFORMAL

Enforcement Action Date:

03/31/1989

Penalty Type:

Not reported

Regulation Violated:

Not reported

Area of Violation:

TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS

Date Violation Determined: Actual Date Achieved Compliance: 09/25/1989 09/28/1989

Enforcement Action:

WRITTEN INFORMAL

Enforcement Action Date:

09/25/1989

Penalty Type:

Not reported

Regulation Violated:

Area of Violation:

Not reported

TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS 08/09/1988

Date Violation Determined: Actual Date Achieved Compliance:

09/29/1989

Enforcement Action:

WRITTEN INFORMAL

Enforcement Action Date:

03/31/1989

Penalty Type:

Not reported

Regulation Violated:

Area of Violation:

Not reported

Date Violation Determined:

TSD-OTHER REQUIREMENTS

Actual Date Achieved Compliance:

06/24/1986 10/27/1987

Map ID Direction Distance Distance (ft.) Elevation Site

MAP FINDINGS

Database(s)

EDR ID Number **EPA ID Number**

1000439958

LEVY EDW C CO PLT 6 (Continued) Enforcement Action:

VERBAL INFORMAL

Enforcement Action Date:

11/30/1983

Penalty Type:

Proposed Monetary Penalty

Enforcement Action:

INITIAL 3008(A) COMPLIANCE ORDER

Enforcement Action Date:

10/24/1986

Penalty Type:

Proposed Monetary Penalty

Enforcement Action:

FINAL 3008(A) COMPLIANCE ORDER

Enforcement Action Date: Penalty Type:

07/13/1987

Enforcement Action:

Proposed Monetary Penalty WRITTEN INFORMAL

Enforcement Action Date:

07/10/1986

Penalty Type:

Proposed Monetary Penalty

Regulation Violated:

Area of Violation:

Not reported

Date Violation Determined:

TSD-GOUNDWATER MONITORING REQUIREMENTS

06/24/1986 10/27/1987

Actual Date Achieved Compliance: Enforcement Action:

VERBAL INFORMAL

Enforcement Action Date:

11/30/1983

Penalty Type:

Enforcement Action:

Proposed Monetary Penalty

INITIAL 3008(A) COMPLIANCE ORDER

Enforcement Action Date:

10/24/1986

Penalty Type:

Proposed Monetary Penalty

Enforcement Action:

FINAL 3008(A) COMPLIANCE ORDER 07/13/1987

Enforcement Action Date:

Proposed Monetary Penalty

Penalty Type:

WRITTEN INFORMAL

Enforcement Action: Enforcement Action Date:

07/10/1986

Penalty Type:

Proposed Monetary Penalty

Regulation Violated:

Not reported

Area of Violation:

TSD-CLOSURE/POST-CLOSURE REQUIREMENTS 06/24/1986

Date Violation Determined: Actual Date Achieved Compliance:

10/27/1987

Enforcement Action:

VERBAL INFORMAL

Enforcement Action Date:

Penalty Type:

11/30/1983

Enforcement Action:

Proposed Monetary Penalty

Enforcement Action Date:

INITIAL 3008(A) COMPLIANCE ORDER

Penalty Type:

10/24/1986

Proposed Monetary Penalty

Enforcement Action:

FINAL 3008(A) COMPLIANCE ORDER

Enforcement Action Date:

07/13/1987

Penalty Type:

Proposed Monetary Penalty

Enforcement Action:

WRITTEN INFORMAL

Enforcement Action Date:

07/10/1986

Penalty Type:

Proposed Monetary Penalty

WRITTEN INFORMAL

Enforcement Action: Enforcement Action Date:

09/23/1986

Penalty Type:

Proposed Monetary Penalty

Regulation Violated:

Not reported

Area of Violation:

TSD-OTHER REQUIREMENTS

Date Violation Determined:

08/19/1985

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

1000439958

LEVY EDW C CO PLT 6 (Continued)

Actual Date Achieved Compliance:

11/07/1985

Enforcement Action:

WRITTEN INFORMAL 08/27/1985

Enforcement Action Date:

00/2//1905

Penalty Type:

Not reported

Enforcement Action:

WRITTEN INFORMAL

Enforcement Action Date: Penalty Type: 10/03/1985

Regulation Violated:

Not reported

Area of Violation:

Not reported

Area of Violation:
Date Violation Determined:

TSD-GOUNDWATER MONITORING REQUIREMENTS

Actual Date Achieved Compliance:

11/20/1983 05/14/1984

Enforcement Action:

WRITTEN INFORMAL

Enforcement Action Date:

11/04/1983

Penalty Type:

Not reported

r cridity Typo.

.

Regulation Violated:

Not reported TSD-GOUNDWATER MONITORING REQUIREMENTS

Area of Violation:

09/22/1983

Date Violation Determined: Actual Date Achieved Compliance:

05/14/1985

Enforcement Action:

WRITTEN INFORMAL

Enforcement Action Date: Penalty Type:

11/04/1983 Not reported

There are 10 violation record(s) reported at this site:

Evaluation	Area of Violation	Date of Compliance
Non-Financial Record Review	TSD-PERMIT CONDITION	20020219
Detailed Multimedia Inspection	GENRATOR-SQG REQUIREMENTS	20051212
Financial Record Review	TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS	19890928
Financial Record Review	TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS	19890929
Compliance Evaluation Inspection	TSD-CLOSURE/POST-CLOSURE REQUIREMENTS	19871027
	TSD-GOUNDWATER MONITORING REQUIREMENTS	19871027
	TSD-OTHER REQUIREMENTS	19871027
Compliance Evaluation Inspection	TSD-OTHER REQUIREMENTS	19851107
Compliance GW Monitoring Evaluation	TSD-GOUNDWATER MONITORING REQUIREMENTS	19840514
Compliance Evaluation Inspection	TSD-GOUNDWATER MONITORING REQUIREMENTS	19850514

FINDS:

Other Pertinent Environmental Activity Identified at Site

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

CORRACTS:

EPA ID:

MID094549425

EPA Region:

05

Map ID Direction Distance Distance (ft.)

Site

Elevation

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

1000439958

LEVY EDW C CO PLT 6 (Continued)

Area Name:

ENTIRE FACILITY

Actual Date:

04/06/1988

Action:

CA050 - RFA Completed

NAICS Code(s):

56221

Waste Treatment and Disposal

EPA ID:

MID094549425

EPA Region: Area Name:

05

Actual Date:

ENTIRE FACILITY 04/06/1988

Action:

CA070NO - RFA Determination Of Need For An RFI, RFI is Not Necessary

NAICS Code(s):

Waste Treatment and Disposal

EPA ID:

MID094549425

EPA Region:

05

Area Name:

ENTIRE FACILITY

Actual Date:

09/27/1991

Action:

CA075LO - CA Prioritization, Facility or area was assigned a low

corrective action priority

NAICS Code(s):

56221

Waste Treatment and Disposal

EPA ID:

MID094549425

EPA Region:

05

Area Name:

ENTIRE FACILITY

Actual Date:

11/04/1999

Action:

CA725YE - Current Human Exposures Under Control, Yes, Current Human

Exposures Under Control has been verified

NAICS Code(s):

56221

Waste Treatment and Disposal

EPA ID:

MID094549425

EPA Region:

05

Area Name:

ENTIRE FACILITY

Actual Date:

11/04/1999

Action:

CA750YE - Migration of Contaminated Groundwater under Control, Yes,

Migration of Contaminated Groundwater Under Control has been verified

NAICS Code(s):

56221

Waste Treatment and Disposal

27

DETROIT STRIP CYCLOPS STEEL

ENE 1/2-1 971 SOUTH OAKWOOD DETROIT, MI 48217

3577 ft.

Relative:

SHWS:

Lower

Facility ID:

Source:

82000173 Metal Processing

Actual:

SAM Score:

20 out of 48

580 ft.

SAM Score Date: 09/05/1990

Township: Range:

025

11E

Section:

30

Quarter: Quarter/Quarter: NW

NW

Facility Status:

Inactive - no actions taken to address contamination

Pollutant(s):

PCB's; Gasoline; Petroleum; Sulfuric acid

S105144810

N/A

SHWS

Map ID Direction Distance Distance (ft.) Elevation

Database(s)

EDR ID Number EPA ID Number

28 NW MICHIGAN CONSOLIDATED GAS CO-RIVER ROUGE STATION

Manufactured Gas Plants

1008408102

1/2-1

GREENFIELD ROAD DETROIT, MI 48122

3824 ft.

N/A

Relative:

Manufactured Gas Plants:

Lower

An MGP operated at the site from approximately 1925 to 1954. The site produced

gas utilizing the carburetted water gas method.

Actual: 585 ft.

29

MARATHON PIPELINE CRYSTAL MINES

SHWS S105144794

ESE 1/2-1 1300 SOUTH FORT STREET DETROIT, MI 48217

PEAS N/A

4757 ft.

584 ft.

Relative: Lower

SHWS:

Facility ID:

82000076

Actual:

Source:

Petroleum Refining

SAM Score:

38 out of 48

SAM Score Date: 12/08/1993 Township: 02S

Range:

11E

Section: Quarter: 33 NW

Quarter/Quarter: NW Facility Status:

Interim Response conducted - No further activities anticipated

Pollutant(s):

CI; Fuel oil

MI PEAS:

Incident Date:

10/18/2000

Date Of PEAS Call:

10/18/2000

Complainant / Company:

Carol Bremer w/Marathon National

Complainant Location:

Detroit, MI 1300 South Fort

Complainant Address:

313-397-6364

Complainant Phone: Company Involved:

Carol Bremer w/Marathon National

Company Involved Address: Township Of Incident:

1300 South Fort Not reported

Name/Volume Of Contaminant:

Sulfur Dioxide/ Unknown

Surface Water Involved ?:

None

Dispatched To District Staff:

P. Samuel George

DEQ Division Involved:

Wayne Co. DOE 10/18/2000

Date Dispatch:

PEAS Number:

843-00

Incident Description:

They lost a boiler which caused an upset of their hydro treater whichresulted in releasing Sulfur Dioxide.

Not reported

Description:

Incident Date:

04/13/2001

Date Of PEAS Call:

04/14/2001

Complainant / Company:

David Linington w/Marathon Ashland Petroleum

Complainant Location:

Detroit, MI 1300 S. Fort St.

Complainant Address: Complainant Phone:

313-297-6341

Company Involved:

David Linington w/Marathon Ashland Petroleum

Company Involved Address:

1300 South Fort Street

Township Of Incident:

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number **EPA ID Number**

MARATHON PIPELINE CRYSTAL MINES (Continued)

S105144794

Name/Volume Of Contaminant:

Surface Water Involved ?: Dispatched To District Staff: None

Sue (Operator)

DEQ Division Involved: Date Dispatch:

Wayne Co. Dept. of Environ. 04/14/2001

Sulfur Dioxide/500 lbs.

PEAS Number:

229-01

Incident Description:

There was a Sulfur Dioxide release that went into the air. He said he wasgoing to call the Wayne County hotline number also to report this.

Not reported

Description:

Incident Date: Date Of PEAS Call: 04/29/2001 04/30/2001

Complainant / Company: Complainant Location:

Tonya Landis w/Marathon Ashland Petroleum Detroit, MI

Complainant Address: Complainant Phone:

1300 S. Fort St. 313-843-9100

Company Involved:

Tonya Landis w/Marathon Ashland Petroleum

Company Involved Address:

1300 S. Fort St.

Township Of Incident: Name/Volume Of Contaminant: Not reported Gas/500 lbs.

Surface Water Involved ?: Dispatched To District Staff: None Sylvia Martin

DEQ Division Involved:

Wayne Co. Health Dept.

Date Dispatch: PEAS Number: 04/30/2001 Not reported

Incident Description:

Fluid catalytic cracking unit was starting up after it was shut down.

Theprocess gases were released to flare. Everything was okay once the

unitstarted working properly.

Description:

Not reported

Incident Date:

05/06/2001

Date Of PEAS Call:

05/06/2001

Complainant / Company: Complainant Location:

David Linington w/Marathon Ashland Petroleum

Complainant Address:

Detroit, MI 1300 S. Fort Street 313-297-6341

Complainant Phone: Company Involved:

David Linington w/Marathon Ashland Petroleum

Company Involved Address: Township Of Incident: Name/Volume Of Contaminant:

1300 S. Fort St. Detroit (City of) SO2/1,000 pounds

Surface Water Involved ?: Dispatched To District Staff: None Operator Wayne Co. DOE

DEQ Division Involved: Date Dispatch:

05/06/2001

PEAS Number: Incident Description: 298-01

S02 released into the air. One of the units went into emergency shut down.Lost approximately 1,000 pounds.

Not reported

Description:

Incident Date: Date Of PEAS Call: 05/31/2001 05/31/2001

Complainant / Company:

David w/Marathon Ashland Petroleum Detroit, MI

Complainant Location: Complainant Address:

1300 S. Fort St. 313-297-6341

Complainant Phone: Company Involved:

David w/Marathon Ashland Petroleum

Company Involved Address:

1300 S. Fort St.

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number **EPA ID Number**

S105144794

MARATHON PIPELINE CRYSTAL MINES (Continued)

Township Of Incident:

Not reported

Name/Volume Of Contaminant:

Sulfur Dioxide/ Unknown

Surface Water Involved ?:

None

Dispatched To District Staff: DEQ Division Involved:

Wayne Co. DOE Not reported 05/31/2001

Date Dispatch: PEAS Number:

371-01

Incident Description:

Complainant said equipment malfunctioned and resulted in a Sulfur

Dioxidereleased to the ground and to the air.

Description:

Not reported

Incident Date: Date Of PEAS Call: 06/09/2001 06/10/2001

Complainant / Company:

Tonya Landis w/Marathon Ashland Petroleum

Complainant Location:

Detroit, MI 1300 S. Fort St.

Complainant Address: Complainant Phone:

313-843-9100

Company Involved:

Tonya Landis w/Marathon Ashland Petroleum Unknown

Company Involved Address: Township Of Incident:

Name/Volume Of Contaminant:

Not reported Sulfur Dioxide/More than 500 lbs.

Surface Water Involved ?: Dispatched To District Staff:

None Operator Wayne Co. DOE

DEQ Division Involved: Date Dispatch:

06/10/2001 404-01

PEAS Number: Incident Description:

Flaring incident from crude unit. There was a release of Sulfur

Dioxide.

Description:

Not reported

Incident Date: Date Of PEAS Call:

06/17/2001 06/17/2001

Complainant / Company:

Marathon Ashland Petroleum

Complainant Location: Complainant Address: Complainant Phone:

Detroit, MI 1300 S. Fort St. 313-297-6341

Company Involved: Company Involved Address: Marathon Ashland Petroleum

Township Of Incident:

1300 S. Fort St. Not reported

Name/Volume Of Contaminant: Surface Water Involved ?:

Sulfur Dioxide/ Unknown

Dispatched To District Staff:

None Sylvia Martin

DEQ Division Involved:

Wayne Co. Health Dept.

Date Dispatch: PEAS Number: 06/18/2001 433-01

Incident Description:

They had a release of Sulfur Dioxide.

Description:

Not reported

Incident Date: Date Of PEAS Call: 11/13/2001

Complainant / Company:

11/13/2001 Brian Duryee w/Marathon Ashland Petroleum

Complainant Location:

Detroit, MI

Complainant Address:

1300 South Fort Street

Complainant Phone:

Company Involved:

313-297-6364

Company Involved Address:

Brian Duryee w/Marathon Ashland Petroleum

1300 South Fort Street

Township Of Incident:

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

S105144794

MARATHON PIPELINE CRYSTAL MINES (Continued)

Name/Volume Of Contaminant:

SO2 gas/Approx. 500 lbs.

Surface Water Involved ?: Dispatched To District Staff: None Jeff Korniski

DEQ Division Involved:

AQD

Date Dispatch: PEAS Number:

11/13/2001 Not reported

Incident Description:

There was a release of SO2 gas.

Description:

Not reported

Incident Date:

12/20/2001 12/20/2001

Date Of PEAS Call: Complainant / Company:

David Linington w/Marathon Ashland Petroleum

Complainant Location:

Detroit, MI

Complainant Address:

1300 South Fort Street

Complainant Phone:

313-297-6341

Company Involved:

David Linington w/Marathon Ashland Petroleum

Company Involved Address: 1300 South Fort Street

Township Of Incident:

Not reported

Name/Volume Of Contaminant:

Sulfur dioxide/ Unknown

Surface Water Involved ?:

None

Dispatched To District Staff:

Lillian Woolley AQD

DEQ Division Involved: Date Dispatch:

12/20/2001 890-01

PEAS Number:

Unknown amount of sulfur dioxide was released due to a FCC unit upset.

Incident Description: Description:

Not reported

Incident Date:

12/23/2001 12/23/2001

Date Of PEAS Call:

Jeff Bruestle w/Marathon Ashland Petroleum

Complainant / Company: Complainant Location:

Detroit, MI

Complainant Address:

1300 South Fort Street

Complainant Phone:

313-843-9100

Company Involved:

Jeff Bruestle w/Marathon Ashland Petroleum

Company Involved Address: Township Of Incident:

1300 South Fort Street

Name/Volume Of Contaminant:

Not reported Greater than 500 pounds Sulfur dioxide/

Surface Water Involved ?:

None

Dispatched To District Staff:

Lillian Woolley

DEQ Division Involved: Date Dispatch:

AQD 12/23/2001

PEAS Number:

893-01

Incident Description:

A release of sulfur dioxide is coming from the recovery unit. They have hadprocess problems, which caused the release. They are shutting downa portion of the unit until the problem is found and repairs are

made.

Description:

Not reported

Incident Date:

03/11/2002

Date Of PEAS Call:

03/11/2002 Cindy Bain w/Marathon Ashland Petroleum

Complainant / Company:

Detroit, MI

Complainant Location:

Complainant Address:

1300 South Fort Street

Complainant Phone:

313-297-6309

Company Involved:

Cindy Bain w/Marathon Ashland Petroleum

Company Involved Address:

1300 South Fort Street

Township Of Incident:

Map ID MAP FINDINGS

Direction Distance Distance (ft.)

Elevation

Database(s)

EDR ID Number **EPA ID Number**

MARATHON PIPELINE CRYSTAL MINES (Continued)

S105144794

Name/Volume Of Contaminant:

Surface Water Involved ?:

Dispatched To District Staff: DEQ Division Involved:

Date Dispatch: PEAS Number:

Incident Description:

Sulfur dioxide/ None

Lee Varner AQD

03/12/2002 106-02

03/23/2000 03/23/2000

Detroit, MI

Paula Bremer

313-297-6364

1300 South Fort Street

1300 South Fort Street

Marathon Ashland Petroleum

Reporting a reportable quantity exceed for sulfur dioxide air release. Aseries of events happened today. Not sure if the 10:30 a.m.

eventtriggered the release. We may have exceeded more, if so we will

call toreport it. They are recalculating the amount estimated.

Greater than 500 lbs.

Description:

Not reported

Incident Date: Date Of PEAS Call:

Complainant / Company: Complainant Location:

Complainant Address: Complainant Phone:

Company Involved: Company Involved Address: Township Of Incident:

Name/Volume Of Contaminant: Surface Water Involved ?:

Dispatched To District Staff: DEQ Division Involved: Date Dispatch: PEAS Number:

Incident Description:

Description:

Hydrogen Sulfide/ Unknown None Operator

Wayne County 03/23/2000 135-00

Hydrogen Sulfide released in flaring incident. Not reported

Incident Date: Date Of PEAS Call:

Complainant / Company: Complainant Location: Complainant Address:

Complainant Phone: Company Involved:

Company Involved Address: Township Of Incident:

Name/Volume Of Contaminant: Surface Water Involved ?:

Dispatched To District Staff: DEQ Division Involved: Date Dispatch:

PEAS Number:

Incident Description: Description:

Incident Date: Date Of PEAS Call:

Complainant / Company: Complainant Location:

Complainant Address: Complainant Phone:

Company Involved: Company Involved Address:

Township Of Incident:

05/27/2003 05/27/2003

Marathon Ashland Petroleum Detroit, Michigan

1300 South Fort Street 313-297-6336

Marathon Ashland Petroleum 1300 South Fort Street

Not reported S.0/2-500 pounds None

Not reported Not reported

Not reported

S.0/2 release due to flaring. Not reported

08/01/2002

08/01/2002

David Linington w/Marathon Ashland Petroleum Detroit, MI

1300 South Fort Street 313-886-2544

David Linington w/Marathon Ashland Petroleum

1300 South Fort Street

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

S105144794

MARATHON PIPELINE CRYSTAL MINES (Continued)

Name/Volume Of Contaminant: Sulfur dioxide/700 lbs.

Surface Water Involved ?:

Dispatched To District Staff: DEQ Division Involved:

Lee Varner AQD 08/02/2002

None

Date Dispatch: PEAS Number:

504-02

Incident Description:

There was a sulfur dioxide release of approximately 700 lbs. It was

releasedat approximately 7:00 p.m. tonight.

Description:

Not reported

Incident Date: Date Of PEAS Call: 09/07/2002 09/07/2002

Complainant / Company:

Brian Duryee w/Marathon Petroleum

Complainant Location:

Detroit, MI

Complainant Address:

1300 South Fort Street

Complainant Phone: Company Involved:

313-297-6364

Company Involved Address:

Brian Duryee w/Marathon Petroleum

1300 South Fort Street

Township Of Incident:

Not reported

Name/Volume Of Contaminant:

Sulfur dioxide/500 to 1,000 lbs.

Surface Water Involved ?: Dispatched To District Staff: DEQ Division Involved: Date Dispatch:

Jon Lamb AQD 09/09/2002

None

PEAS Number: Incident Description:

624-02 The cat unit went down. There was a release of 500 to 1,000 pounds

ofof sulfur dioxide.

Description:

Not reported

Incident Date: Date Of PEAS Call: 09/28/2002 09/28/2002

Complainant / Company:

Cindy Bain w/Marathon Shalin Petroleum

Complainant Location: Complainant Address:

Detroit, MI 1300 South Fort Street

Complainant Phone:

313-297-6309

Company Involved:

Cindy Bain w/Marathon Shalin Petroleum

Company Involved Address:

1300 South Fort Street

Township Of Incident: Name/Volume Of Contaminant: Not reported

Surface Water Involved ?:

Sulfur dioxide/ Greater than 500 lbs.

Dispatched To District Staff: DEQ Division Involved: Date Dispatch:

Mike Gruber AQD 09/28/2002 681-02

None

PEAS Number: Incident Description:

Lost the heater unit, gas testing unit, and potential. The duration of thevent was from 1:03 p.m. to 1:30 p.m. Lost greater than 500

poundsof sulfur dioxide into the air.

Description:

Not reported

Incident Date: Date Of PEAS Call: 11/18/2002 11/18/2002

Complainant / Company:

Cindy Bain w/Marathon Ashland Petroleum

Complainant Location:

Detroit, MI

Complainant Address: Complainant Phone:

1300 South Fort Street

Company Involved:

313-297-6309

Cindy Bain w/Marathon Ashland Petroleum

Company Involved Address:

1300 South Fort Street

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number **EPA ID Number**

MARATHON PIPELINE CRYSTAL MINES (Continued)

S105144794

Township Of Incident:

Not reported

Name/Volume Of Contaminant:

Gas and oil/

Approx. 150 gallons

Surface Water Involved ?: Dispatched To District Staff: None Cheryl Wilson

DEQ Division Involved:

RRD

Date Dispatch: PEAS Number: 11/18/2002 Not reported

Incident Description:

There was a leak coming from a gas oil line to the soil. It did not make it toany sewers or other waters. It was noticed immediately. Has vac-trucks, booms, and pads on the scene. The leak has been

contained.

Description:

Not reported

Incident Date: Date Of PEAS Call: 11/20/2002 11/20/2002

Complainant / Company:

lan Ladomer w/Marathon

Complainant Location:

Detroit, MI

Complainant Address:

1300 South Fort Street

Complainant Phone:

313-297-6336

Company Involved: Company Involved Address: Ian Ladomer w/Marathon

Township Of Incident:

1300 South Fort Street Not reported

Name/Volume Of Contaminant:

SO2/Greater than 500 lbs.

Surface Water Involved ?: Dispatched To District Staff: None Mike Gruber AQD

DEQ Division Involved: Date Dispatch:

11/20/2002 773-02

PEAS Number: Incident Description:

There is a high SO release in SRU incinerator to the air. They are

attemptingto correct the problem. The volume is greater than 500 lbs.

Description: Not reported

Incident Date: Date Of PEAS Call: 12/07/2002 12/07/2002

Complainant / Company:

Honor w/Marathon Ashland Petroleum

Complainant Location:

Detroit, MI

Complainant Address: Complainant Phone:

1300 South Fort Street

Company Involved:

248-408-3034

Company Involved Address:

Honor w/Marathon Ashland Petroleum 1300 South Fort Street

Township Of Incident:

Not reported

Name/Volume Of Contaminant: Surface Water Involved ?:

Oil or gas/Approx. 850 gallons

Dispatched To District Staff:

None Ray Spaulding

DEQ Division Involved:

RRD

Date Dispatch: PEAS Number: 12/07/2002

786-02

Incident Description:

Discovered oil or gas spill to the ground. It was coming from one of theirtanks. They have already called a cleanup contractor and the

City of Detroit Water and Sewer Company. Cleanup contractor to be

on-site withinone hour.

Description:

Not reported

Incident Date: Date Of PEAS Call:

12/07/2002 12/07/2002

Complainant / Company:

Honor w/Marathon Ashland Petroleum

Complainant Location:

Detroit, MI

Map ID Direction Distance

MAP FINDINGS

Database(s)

EDR ID Number **EPA ID Number**

S105144794

MARATHON PIPELINE CRYSTAL MINES (Continued)

Complainant Address:

1300 South Fort Street

Complainant Phone:

Distance (ft.)

Site

Elevation

248-408-3034

Company Involved:

Honor w/Marathon Ashland Petroleum

Company Involved Address: Township Of Incident:

1300 South Fort Street

Name/Volume Of Contaminant:

Not reported

Oil or gas/25 gallons

Surface Water Involved ?:

None

Dispatched To District Staff:

Ray Spaulding

DEQ Division Involved: Date Dispatch:

RRD 12/07/2002 787-02

PEAS Number: Incident Description:

Regarding Incident #787-02, called back to revise spill volume

estimate from 850 gallons to 25 gallons.

Description:

Not reported

Incident Date:

07/29/04

Date Of PEAS Call:

Not reported

Complainant / Company:

Ian Ladomer @ Marathon Petroleum

Complainant Location:

Not reported

Complainant Address:

Not reported

Complainant Phone:

Not reported

Company Involved:

Marathon Petroleum

Company Involved Address:

Not reported

Township Of Incident: Name/Volume Of Contaminant: Not reported Sulfur dioxide (SO2)/Greater than 500 lbs.

Surface Water Involved ?:

Not reported

Dispatched To District Staff:

null

DEQ Division Involved:

null

Date Dispatch:

Not reported

PEAS Number:

Not reported

Incident Description:

Fire in the process heater. Release of SO2, hazaradous substance, in

the air.

Description:

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
DEARBORN	S108084450	STERLING GROUP	15080 AND 15090 NORTH COMMERCE DRIVE	48120	BEA
DEARBORN	S108084344	FORD MOTOR LAND DEVELOPMENT CORP.	15080 AND 15090 NORTH COMMERCE DRIVE	48120	BEA
DETROIT	1007101140	MI DEPT/TRANSPORTATION BRIDGE S04-82194	I-75 OVER SCHAEFER RD	48217	RCRA-SQG
DETROIT	S107924910	AL'S TRUCK STOP BP	2801 S SCHAEFER HWY		AUL
MELVINDALE	1000352060	FOUR WAY COLLISION INC	19125 DIX TOLEDO HWY	48122	RCRA-SQG, FINDS
MELVINDALE	1000374001	ARTS BODY SHOP INC	18801 DIX TOLEDO HWY	48122	RCRA-SQG, FINDS
MELVINDALE	U003320752	NONFOLK SOUTHERN CORP	1800 DIX	24042	UST
MELVINDALE	S105144803	MARATHON REFINERY WEATHERING PIT	1300 SOUTH FORT		SHWS, DEL SHWS, BROWNFIELDS
MELVINDALE	S108419451	MICHIGAN SITE NETWORK	FRANCIS STREET		BROWNFIELDS
MELVINDALE	S103095068	ROUGE RIVER	SCHAEFER HWY BRIDGE		SHWS, BROWNFIELDS
MELVINDALE	A100282623	MELVINDALE TANK FARM	1450 SCHAEFER	45840	AST
MELVINDALE	S103594556	NORFOLK AND WESTERN RAILROAD	17670 N WABASH ST	48122	SHWS
MELVINDALE	U003324511	NORFOLK SOUTHERN CORP	17670 N WABASH		LUST, UST
MELVINDALE	1002946272	NORFOLK WESTERN RR	17670 NORTH WABSH STREET	48122	CERC-NFRAP

EPA Waste Codes Addendum

Code	Description
F006	WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5) CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

FEDERAL RECORDS

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 07/18/2007 Date Data Arrived at EDR: 08/03/2007 Date Made Active in Reports: 08/29/2007

Number of Days to Update: 26

Source: EPA Telephone: N/A

Last EDR Contact: 07/31/2007

Next Scheduled EDR Contact: 10/29/2007 Data Release Frequency: Quarterly

NPL Site Boundaries

EPA's Environmental Photographic Interpretation Center (EPIC)

Telephone: 202-564-7333

EPA Region 1

Telephone 617-918-1143

EPA Region 3

Telephone 215-814-5418

EPA Region 4

Telephone 404-562-8033

EPA Region 5

Telephone 312-886-6686

EPA Region 10

Telephone 206-553-8665

EPA Region 6

Telephone: 214-655-6659

EPA Region 7

Telephone: 913-551-7247

EPA Region 8

Telephone: 303-312-6774

EPA Region 9

Telephone: 415-947-4246

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 04/20/2007 Date Data Arrived at EDR: 05/03/2007

Date Made Active in Reports: 07/05/2007

Number of Days to Update: 63

Source: EPA Telephone: N/A

Last EDR Contact: 08/31/2007

Next Scheduled EDR Contact: 10/29/2007 Data Release Frequency: Quarterly

DELISTED NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 04/20/2007 Date Data Arrived at EDR: 05/03/2007 Date Made Active in Reports: 06/25/2007

Number of Days to Update: 53

Source: EPA Telephone: N/A

Last EDR Contact: 08/29/2007

Next Scheduled EDR Contact: 10/29/2007 Data Release Frequency: Quarterly

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991 Date Data Arrived at EDR: 02/02/1994 Date Made Active in Reports: 03/30/1994

Number of Days to Update: 56

Source: EPA

Telephone: 202-564-4267 Last EDR Contact: 08/20/2007

Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: No Update Planned

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 04/23/2007 Date Data Arrived at EDR: 06/20/2007 Date Made Active in Reports: 08/29/2007

Number of Days to Update: 70

Source: EPA

Telephone: 703-412-9810 Last EDR Contact: 06/20/2007

Next Scheduled EDR Contact: 09/17/2007 Data Release Frequency: Quarterly

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Archived sites are sites that have been removed and archived from the inventory of CERCLIS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list this site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. This decision does not necessarily mean that there is no hazard associated with a given site; it only means that, based upon available information, the location is not judged to be a potential NPL site.

Date of Government Version: 06/21/2007 Date Data Arrived at EDR: 07/23/2007 Date Made Active in Reports: 08/29/2007

Number of Days to Update: 37

Source: EPA

Telephone: 703-412-9810 Last EDR Contact: 06/15/2007

Next Scheduled EDR Contact: 09/17/2007 Data Release Frequency: Quarterly

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 06/26/2007 Date Data Arrived at EDR: 08/08/2007 Date Made Active in Reports: 08/29/2007

Number of Days to Update: 21

Source: EPA

Telephone: 800-424-9346 Last EDR Contact: 09/04/2007

Next Scheduled EDR Contact: 12/03/2007 Data Release Frequency: Quarterly

RCRA: Resource Conservation and Recovery Act Information

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. RCRAInfo replaces the data recording and reporting abilities of the Resource Conservation and Recovery Information System (RCRIS). The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month. Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month. Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month. Transporters are individuals or entities that move hazardous waste from the generator off-site to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 06/13/2006 Date Data Arrived at EDR: 06/28/2006 Date Made Active in Reports: 08/23/2006

Number of Days to Update: 56

Source: EPA

Telephone: 312-886-6186 Last EDR Contact: 09/04/2007

Next Scheduled EDR Contact: 10/15/2007 Data Release Frequency: Quarterly

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/2006 Date Data Arrived at EDR: 01/24/2007 Date Made Active in Reports: 03/12/2007

Number of Days to Update: 47

Source: National Response Center, United States Coast Guard

Telephone: 202-267-2180 Last EDR Contact: 07/23/2007

Next Scheduled EDR Contact: 10/22/2007 Data Release Frequency: Annually

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 03/05/2007 Date Data Arrived at EDR: 04/17/2007 Date Made Active in Reports: 05/14/2007

Number of Days to Update: 27

Source: U.S. Department of Transportation

Telephone: 202-366-4555 Last EDR Contact: 07/18/2007

Next Scheduled EDR Contact: 10/15/2007 Data Release Frequency: Annually

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 04/20/2007 Date Data Arrived at EDR: 04/26/2007 Date Made Active in Reports: 05/25/2007

Number of Days to Update: 29

Source: Environmental Protection Agency

Telephone: 703-603-8905 Last EDR Contact: 07/02/2007

Next Scheduled EDR Contact: 10/01/2007 Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 04/20/2007 Date Data Arrived at EDR: 04/26/2007 Date Made Active in Reports: 05/25/2007

Number of Days to Update: 29

Source: Environmental Protection Agency

Telephone: 703-603-8905 Last EDR Contact: 07/02/2007

Next Scheduled EDR Contact: 10/01/2007

Data Release Frequency: Varies

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands. Source: USGS

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 11/10/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 62

Telephone: 703-692-8801

Last EDR Contact: 08/09/2007

Next Scheduled EDR Contact: 11/05/2007 Data Release Frequency: Semi-Annually

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 09/20/2006 Date Made Active in Reports: 11/22/2006

Number of Days to Update: 63

Source: U.S. Army Corps of Engineers

Telephone: 202-528-4285 Last EDR Contact: 08/31/2007

Next Scheduled EDR Contact: 10/01/2007

Data Release Frequency: Varies

US BROWNFIELDS: A Listing of Brownfields Sites

Included in the listing are brownfields properties addresses by Cooperative Agreement Recipients and brownfields properties addressed by Targeted Brownfields Assessments. Targeted Brownfields Assessments-EPA's Targeted Brownfields Assessments (TBA) program is designed to help states, tribes, and municipalities--especially those without EPA Brownfields Assessment Demonstration Pilots--minimize the uncertainties of contamination often associated with brownfields. Under the TBA program, EPA provides funding and/or technical assistance for environmental assessments at brownfields sites throughout the country. Targeted Brownfields Assessments supplement and work with other efforts under EPA's Brownfields Initiative to promote cleanup and redevelopment of brownfields. Cooperative Agreement Recipients-States, political subdivisions, territories, and Indian tribes become Brownfields Cleanup Revolving Loan Fund (BCRLF) cooperative agreement recipients when they enter into BCRLF cooperative agreements with the U.S. EPA. EPA selects BCRLF cooperative agreement recipients based on a proposal and application process. BCRLF cooperative agreement recipients must use EPA funds provided through BCRLF cooperative agreement for specified brownfields-related cleanup activities.

Date of Government Version: 06/20/2007 Date Data Arrived at EDR: 07/09/2007 Date Made Active in Reports: 08/29/2007

Number of Days to Update: 51

Source: Environmental Protection Agency

Telephone: 202-566-2777 Last EDR Contact: 06/11/2007

Next Scheduled EDR Contact: 09/10/2007 Data Release Frequency: Semi-Annually

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 04/13/2007 Date Data Arrived at EDR: 07/16/2007 Date Made Active in Reports: 08/29/2007

Number of Days to Update: 44

Source: Department of Justice, Consent Decree Library

Telephone: Varies

Last EDR Contact: 08/23/2007

Next Scheduled EDR Contact: 10/22/2007

Data Release Frequency: Varies

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 06/08/2007 Date Data Arrived at EDR: 07/03/2007 Date Made Active in Reports: 08/29/2007

Number of Days to Update: 57

Source: EPA

Telephone: 703-416-0223 Last EDR Contact: 07/02/2007

Next Scheduled EDR Contact: 10/01/2007 Data Release Frequency: Annually

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 11/08/2006 Date Made Active in Reports: 01/29/2007

Number of Days to Update: 82

Source: Department of Energy Telephone: 505-845-0011 Last EDR Contact: 07/05/2007

Next Scheduled EDR Contact: 09/17/2007 Data Release Frequency: Varies

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985 Date Data Arrived at EDR: 08/09/2004 Date Made Active in Reports: 09/17/2004

Number of Days to Update: 39

Source: Environmental Protection Agency

Telephone: 800-424-9346 Last EDR Contact: 06/09/2004 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 04/27/2007 Date Made Active in Reports: 07/05/2007

Number of Days to Update: 69

Source: EPA

Telephone: 202-566-0250 Last EDR Contact: 06/19/2007

Next Scheduled EDR Contact: 09/17/2007 Data Release Frequency: Annually

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant

Date of Government Version: 12/31/2002 Date Data Arrived at EDR: 04/14/2006 Date Made Active in Reports: 05/30/2006

Number of Days to Update: 46

Source: EPA

Telephone: 202-260-5521 Last EDR Contact: 07/30/2007

Next Scheduled EDR Contact: 10/15/2007 Data Release Frequency: Every 4 Years

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/13/2007 Date Data Arrived at EDR: 04/25/2007 Date Made Active in Reports: 07/05/2007

Number of Days to Update: 71

Source: EPA/Office of Prevention, Pesticides and Toxic Substances

Telephone: 202-566-1667 Last EDR Contact: 06/15/2007

Next Scheduled EDR Contact: 09/17/2007 Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act) A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/13/2007 Date Data Arrived at EDR: 04/25/2007 Date Made Active in Reports: 07/05/2007

Number of Days to Update: 71

Source: EPA

Telephone: 202-566-1667 Last EDR Contact: 06/15/2007

Next Scheduled EDR Contact: 09/17/2007 Data Release Frequency: Quarterly

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 03/13/2007 Date Made Active in Reports: 04/27/2007

Number of Days to Update: 45

Source: EPA

Telephone: 202-564-4203 Last EDR Contact: 07/16/2007

Next Scheduled EDR Contact: 10/15/2007 Data Release Frequency: Annually

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 03/08/2007 Date Data Arrived at EDR: 04/12/2007 Date Made Active in Reports: 05/14/2007

Number of Days to Update: 32

Source: Environmental Protection Agency

Telephone: 202-564-6023 Last EDR Contact: 08/20/2007

Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Varies

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 07/31/2007 Date Data Arrived at EDR: 08/01/2007 Date Made Active in Reports: 08/29/2007

Number of Days to Update: 28

Source: Environmental Protection Agency

Telephone: 202-343-9775 Last EDR Contact: 08/01/2007

Next Scheduled EDR Contact: 10/29/2007 Data Release Frequency: Quarterly

CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 12/01/2006 Date Data Arrived at EDR: 01/08/2007 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 3

Source: Drug Enforcement Administration

Telephone: 202-307-1000 Last EDR Contact: 06/29/2007

Next Scheduled EDR Contact: 09/24/2007 Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006 Date Data Arrived at EDR: 03/01/2007 Date Made Active in Reports: 04/10/2007

Number of Days to Update: 40

Source: Environmental Protection Agency

Telephone: 202-564-2501 Last EDR Contact: 06/15/2007

Next Scheduled EDR Contact: 09/17/2007 Data Release Frequency: No Update Planned

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 06/29/2007 Date Data Arrived at EDR: 07/02/2007 Date Made Active in Reports: 08/29/2007 Number of Days to Update: 58 Source: Environmental Protection Agency

Telephone: 202-564-5088 Last EDR Contact: 06/22/2007

Next Scheduled EDR Contact: 07/16/2007 Data Release Frequency: Quarterly

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 12/09/2005 Date Data Arrived at EDR: 12/11/2006 Date Made Active in Reports: 01/11/2007

Source: Department of the Navy Telephone: 843-820-7326 Last EDR Contact: 06/11/2007

Number of Days to Update: 31

Next Scheduled EDR Contact: 09/10/2007 Data Release Frequency: Varies

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 05/14/2007 Date Data Arrived at EDR: 05/30/2007 Date Made Active in Reports: 07/05/2007 Source: Department of Transporation, Office of Pipeline Safety

Telephone: 202-366-4595 Last EDR Contact: 08/29/2007

Number of Days to Update: 36

Next Scheduled EDR Contact: 11/26/2007 Data Release Frequency: Varies

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 04/12/2007 Date Data Arrived at EDR: 06/08/2007 Date Made Active in Reports: 08/29/2007 Source: EPA

Telephone: 202-566-0500 Last EDR Contact: 08/09/2007

Number of Days to Update: 82

Next Scheduled EDR Contact: 11/05/2007
Data Release Frequency: Annually

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/05/2007 Date Data Arrived at EDR: 04/25/2007 Date Made Active in Reports: 05/25/2007 Source: Nuclear Regulatory Commission

Telephone: 301-415-7169 Last EDR Contact: 07/02/2007

Number of Days to Update: 30 Next Scheduled EDR Contact: 10/01/2007
Data Release Frequency: Quarterly

MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 05/09/2007 Date Data Arrived at EDR: 06/28/2007 Date Made Active in Reports: 08/29/2007 Number of Days to Update: 62

Source: Department of Labor, Mine Safety and Health Administration

Telephone: 303-231-5959 Last EDR Contact: 06/28/2007

Next Scheduled EDR Contact: 09/24/2007 Data Release Frequency: Semi-Annually

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 04/12/2007 Date Data Arrived at EDR: 05/17/2007 Date Made Active in Reports: 07/05/2007

Number of Days to Update: 49

Source: EPA

Telephone: (312) 353-2000 Last EDR Contact: 07/02/2007

Next Scheduled EDR Contact: 10/01/2007 Data Release Frequency: Quarterly

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System, RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995 Date Data Arrived at EDR: 07/03/1995 Date Made Active in Reports: 08/07/1995

Number of Days to Update: 35

Source: EPA

Telephone: 202-564-4104 Last EDR Contact: 08/31/2007

Next Scheduled EDR Contact: 12/03/2007

Data Release Frequency: No Update Planned

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 03/06/2007 Date Made Active in Reports: 04/13/2007

Number of Days to Update: 38

Source: EPA/NTIS Telephone: 800-424-9346 Last EDR Contact: 06/12/2007

Next Scheduled EDR Contact: 09/10/2007 Data Release Frequency: Biennially

USGS WATER WELLS: National Water Information System (NWIS)

This database consists of well records in the United States. Available site descriptive information includes well location information (latitude and longitude, well depth, site use, water use, and aquifer).

Date of Government Version: 03/25/2005 Date Data Arrived at EDR: 03/25/2005 Date Made Active in Reports: N/A

Number of Days to Update: 0

Source: USGS Telephone: N/A

Last EDR Contact: 03/25/2005 Next Scheduled EDR Contact: N/A Data Release Frequency: N/A

PWS: Public Water System Data

This Safe Drinking Water Information System (SDWIS) file contains public water systems name and address, population served and the primary source of water

Date of Government Version: 02/24/2000 Date Data Arrived at EDR: 04/27/2005 Date Made Active in Reports: N/A

Number of Days to Update: 0

Source: EPA Telephone: N/A

Last EDR Contact: 08/20/2007

Next Scheduled EDR Contact: 11/19/2007

Data Release Frequency: N/A

STATE AND LOCAL RECORDS

SHWS: Contaminated Sites

State Hazardous Waste Sites. State hazardous waste site records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. Available information varies by state.

Date of Government Version: 08/17/2007 Date Data Arrived at EDR: 08/22/2007 Date Made Active in Reports: 09/05/2007

Number of Days to Update: 14

Source: Department of Environmental Quality

Telephone: 517-373-9541 Last EDR Contact: 08/22/2007

Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Semi-Annually

DEL SHWS: Delisted List of Contaminated Sites

Sites that have been delisted or deleted from the List of Contaminated Sites. The available documentation for the site does not support it's listing or the site no longer meets criteria specified in rules.

Date of Government Version: 08/23/2007 Date Data Arrived at EDR: 08/23/2007 Date Made Active in Reports: 09/05/2007

Number of Days to Update: 13

Source: Department of Environmental Quality

Telephone: 517-373-9541 Last EDR Contact: 08/20/2007

Next Scheduled EDR Contact: 11/19/2007

Data Release Frequency: Varies

SWF/LF: Solid Waste Facilities Database

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 07/24/2007 Date Data Arrived at EDR: 07/27/2007 Date Made Active in Reports: 09/05/2007

Number of Days to Update: 40

Source: Department of Environmental Quality

Telephone: 517-335-4035 Last EDR Contact: 07/23/2007

Next Scheduled EDR Contact: 10/22/2007 Data Release Frequency: Semi-Annually

HIST LF: Inactive Solid Waste Facilities

The database contains historical information and is no longer updated.

Date of Government Version: 03/01/1997 Date Data Arrived at EDR: 02/28/2003 Date Made Active in Reports: 03/06/2003

Number of Days to Update: 6

Source: Department of Environmental Quality

Telephone: 517-335-4034 Last EDR Contact: 02/28/2003 Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

LUST: Leaking Underground Storage Tank Sites

Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 06/11/2007 Date Data Arrived at EDR: 06/13/2007 Date Made Active in Reports: 06/29/2007

Number of Days to Update: 16

Source: Department of Environmental Quality

Telephone: 517-373-9837 Last EDR Contact: 06/13/2007

Next Scheduled EDR Contact: 09/10/2007 Data Release Frequency: Annually

UST: Underground Storage Tank Facility List

Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 06/11/2007 Date Data Arrived at EDR: 06/13/2007 Date Made Active in Reports: 07/27/2007

Number of Days to Update: 44

Source: Department of Environmental Quality

Telephone: 517-335-4035 Last EDR Contact: 06/13/2007

Next Scheduled EDR Contact: 09/10/2007 Data Release Frequency: Annually

AST: Aboveground Tanks

Registered Aboveground Storage Tanks.

Date of Government Version: 03/29/2007 Date Data Arrived at EDR: 03/29/2007 Date Made Active in Reports: 05/03/2007

Number of Days to Update: 35

Source: Department of Environmental Quality

Telephone: 517-373-8168 Last EDR Contact: 06/11/2007

Next Scheduled EDR Contact: 09/10/2007 Data Release Frequency: No Update Planned

LIENS: Lien List

An Environmental Lien is a charge, security, or encumbrance upon title to a property to secure the payment of a cost, damage, debt, obligation, or duty arising out of response actions, cleanup, or other remediation of hazardous substances or petroleum products upon a property, including (but not limited to) liens imposed pursuant to CERCLA 42 USC * 9607(1) and similar state or local laws. In other words: a lien placed upon a property's title due

to an environmental condition

Date of Government Version: 01/25/2007

Date Data Arrived at EDR: 03/06/2007 Date Made Active in Reports: 03/21/2007

Number of Days to Update: 15

Source: Department of Environmental Quality

Telephone: 517-373-9837

Last EDR Contact: 08/15/2007

Next Scheduled EDR Contact: 11/12/2007 Data Release Frequency: Varies

PEAS: Pollution Emergency Alerting System

Environmental pollution emergencies reported to the Department of Environmental Quality such as tanker accidents, pipeline breaks, and release of reportable quantities of hazardous substances.

Date of Government Version: 07/18/2007 Date Data Arrived at EDR: 07/20/2007 Date Made Active in Reports: 09/05/2007

Number of Days to Update: 47

Source: Department of Environmental Quality

Telephone: 517-373-8427 Last EDR Contact: 07/02/2007

Next Scheduled EDR Contact: 10/01/2007 Data Release Frequency: Quarterly

AUL: Engineering and Institutional Controls

A listing of sites with institutional and/or engineering controls in place.

Date of Government Version: 03/27/2007 Date Data Arrived at EDR: 03/29/2007 Date Made Active in Reports: 05/01/2007

Number of Days to Update: 33

Source: Department of Environmental Quality

Telephone: 517-373-4828 Last EDR Contact: 06/25/2007

Next Scheduled EDR Contact: 09/24/2007

Data Release Frequency: Varies

DRYCLEANERS: Drycleaning Establishments
A listing of drycleaning facilities in Michigan.

Date of Government Version: 05/16/2007 Date Data Arrived at EDR: 07/16/2007 Date Made Active in Reports: 09/05/2007

Number of Days to Update: 51

Source: Department of Environmental Quality

Telephone: 517-335-4586 Last EDR Contact: 08/13/2007

Next Scheduled EDR Contact: 11/12/2007

Data Release Frequency: Varies

BROWNFIELDS: Brownfields and USTfield Site Database

All state funded Part 201 and 213 sites, as well as LUST sites that have been redeveloped by private entities using the BEA process. Be aware that this is not a list of all of the potential brownfield sites in Michigan.

Date of Government Version: 08/27/2007 Date Data Arrived at EDR: 08/28/2007 Date Made Active in Reports: 09/05/2007

Number of Days to Update: 8

Source: Department of Environmental Quality

Telephone: 517-373-4805 Last EDR Contact: 08/20/2007

Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Varies

BROWNFIELDS 2: Brownfields Building and Land Site Locations

A listing of brownfield building and land site locations. The listing is a collaborative effort of Michigan Economic Development Corporation, Michigan Economic Developers Association, Detrot Edison, Detroit Area Commercial Board of Realtors

Date of Government Version: 04/09/2007 Date Data Arrived at EDR: 04/10/2007 Date Made Active in Reports: 05/01/2007

Number of Days to Update: 21

Source: Economic Development Corporation

Telephone: 888-522-0103 Last EDR Contact: 08/13/2007

Next Scheduled EDR Contact: 09/10/2007 Data Release Frequency: Varies

CDL: Clandestine Drug Lab Listing

A listing of clandestine drug lab locations.

Date of Government Version: 05/17/2007 Date Data Arrived at EDR: 05/31/2007 Date Made Active in Reports: 06/29/2007

Number of Days to Update: 29

Source: Department of Community Health

Telephone: 517-373-3740 Last EDR Contact: 08/22/2007

Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Varies

NPDES: List of Active NPDES Permits

General information regarding NPDES (National Pollutant Discharge Elimination System) permits and NPDES Storm

Date of Government Version: 07/23/2007 Date Data Arrived at EDR: 08/01/2007 Date Made Active in Reports: 09/05/2007

Number of Days to Update: 35

Source: Department of Environmental Quality

Telephone: 517-241-1300 Last EDR Contact: 08/01/2007

Next Scheduled EDR Contact: 10/29/2007 Data Release Frequency: Varies

AIRS: Permit and Emissions Inventory Data Permit and emissions inventory data.

> Date of Government Version: 05/03/2007 Date Data Arrived at EDR: 05/04/2007 Date Made Active in Reports: 06/05/2007 Number of Days to Update: 32

Source: Department of Environmental Quality

Telephone: 517-373-7074 Last EDR Contact: 08/08/2007

Next Scheduled EDR Contact: 10/15/2007 Data Release Frequency: Varies

BEA: BASELINE ENVIRONMENTAL ASSESSMENT DATABASE

A Baseline Environmental Assessment (BEA) allows people to purchase or begin operating at a facility without being held liable for existing contamination. BEAs are used to gather enough information about the property being transferred so that existing contamination can be distinguished from any new releases that might occur after the new owner or operator takes over the property.

Date of Government Version: 06/13/2007 Date Data Arrived at EDR: 06/14/2007 Date Made Active in Reports: 06/29/2007 Number of Days to Update: 15

Source: DEPT. OF ENVIRONMENTAL QUALITY

Telephone: 517-373-9541 Last EDR Contact: 06/11/2007

Next Scheduled EDR Contact: 09/10/2007 Data Release Frequency: Semi-Annually

TRIBAL RECORDS

INDIAN RESERV: Indian Reservations

This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 12/08/2006 Date Made Active in Reports: 01/11/2007

Number of Days to Update: 34

Source: USGS

Telephone: 202-208-3710 Last EDR Contact: 08/09/2007

Next Scheduled EDR Contact: 11/05/2007 Data Release Frequency: Semi-Annually

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 05/23/2007 Date Data Arrived at EDR: 05/24/2007 Date Made Active in Reports: 07/05/2007

Number of Days to Update: 42

Source: EPA Region 10 Telephone: 206-553-2857 Last EDR Contact: 08/20/2007

Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Quarterly

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 06/01/2007 Date Data Arrived at EDR: 06/14/2007 Date Made Active in Reports: 07/05/2007

Number of Days to Update: 21

Source: EPA Region 7 Telephone: 913-551-7003 Last EDR Contact: 08/20/2007

Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 01/04/2005 Date Data Arrived at EDR: 01/21/2005 Date Made Active in Reports: 02/28/2005

Number of Days to Update: 38

Source: EPA Region 6 Telephone: 214-665-6597 Last EDR Contact: 08/20/2007

Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 03/20/2007 Date Data Arrived at EDR: 04/16/2007 Date Made Active in Reports: 05/14/2007

Number of Days to Update: 28

Source: EPA Region 4 Telephone: 404-562-8677 Last EDR Contact: 08/20/2007

Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Semi-Annually

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 12/01/2006 Date Data Arrived at EDR: 12/01/2006 Date Made Active in Reports: 01/29/2007

Number of Days to Update: 59

Source: EPA Region 1 Telephone: 617-918-1313 Last EDR Contact: 08/20/2007

Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Varies

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 06/18/2007 Date Data Arrived at EDR: 06/18/2007 Date Made Active in Reports: 07/05/2007

Number of Days to Update: 17

Source: Environmental Protection Agency Telephone: 415-972-3372

Last EDR Contact: 08/20/2007

Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Quarterly

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land

LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 05/30/2007 Date Data Arrived at EDR: 05/31/2007 Date Made Active in Reports: 07/05/2007

Number of Days to Update: 35

Source: EPA Region 8 Telephone: 303-312-6271 Last EDR Contact: 08/20/2007

Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Quarterly

INDIAN UST R10: Underground Storage Tanks on Indian Land

Date of Government Version: 05/23/2007 Date Data Arrived at EDR: 05/24/2007 Date Made Active in Reports: 07/05/2007

Number of Days to Update: 42

Source: EPA Region 10 Telephone: 206-553-2857 Last EDR Contact: 08/20/2007

Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Quarterly

INDIAN UST R8: Underground Storage Tanks on Indian Land

Date of Government Version: 05/30/2007 Date Data Arrived at EDR: 05/31/2007 Date Made Active in Reports: 07/05/2007

Number of Days to Update: 35

Source: EPA Region 8 Telephone: 303-312-6137 Last EDR Contact: 08/20/2007

Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Quarterly

INDIAN UST R1: Underground Storage Tanks on Indian Land A listing of underground storage tank locations on Indian Land.

Date of Government Version: 12/01/2006 Date Data Arrived at EDR: 12/01/2006 Date Made Active in Reports: 01/29/2007

Number of Days to Update: 59

Source: EPA, Region 1 Telephone: 617-918-1313 Last EDR Contact: 08/20/2007

Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Varies

INDIAN UST R6: Underground Storage Tanks on Indian Land

Date of Government Version: 06/06/2007 Date Data Arrived at EDR: 06/07/2007 Date Made Active in Reports: 07/05/2007

Number of Days to Update: 28

Source: EPA Region 6 Telephone: 214-665-7591 Last EDR Contact: 08/20/2007

Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Semi-Annually

INDIAN UST R7: Underground Storage Tanks on Indian Land

Date of Government Version: 06/01/2007 Date Data Arrived at EDR: 06/14/2007 Date Made Active in Reports: 07/05/2007

Number of Days to Update: 21

Source: EPA Region 7 Telephone: 913-551-7003 Last EDR Contact: 08/20/2007

Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Varies

INDIAN UST R4: Underground Storage Tanks on Indian Land

Date of Government Version: 03/20/2007 Date Data Arrived at EDR: 04/16/2007 Date Made Active in Reports: 05/14/2007

Number of Days to Update: 28

Source: EPA Region 4 Telephone: 404-562-9424 Last EDR Contact: 08/20/2007

Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Semi-Annually

INDIAN UST R9: Underground Storage Tanks on Indian Land

Date of Government Version: 06/18/2007 Date Data Arrived at EDR: 06/18/2007 Date Made Active in Reports: 07/05/2007

Number of Days to Update: 17

Source: EPA Region 9 Telephone: 415-972-3368 Last EDR Contact: 08/20/2007

Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Quarterly

INDIAN UST R5: Underground Storage Tanks on Indian Land

Date of Government Version: 12/02/2004 Date Data Arrived at EDR: 12/29/2004 Date Made Active in Reports: 02/04/2005

Number of Days to Update: 37

Source: EPA Region 5 Telephone: 312-886-6136 Last EDR Contact: 08/20/2007

Next Scheduled EDR Contact: 11/19/2007 Data Release Frequency: Varies

EDR PROPRIETARY RECORDS

Manufactured Gas Plants: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A Date Data Arrived at EDR: N/A Date Made Active in Reports: N/A

Number of Days to Update: N/A

Source: EDR, Inc. Telephone: N/A Last EDR Contact: N/A

Next Scheduled EDR Contact: N/A

Data Release Frequency: No Update Planned

FEDERAL RECORDS

PUBLIC SCHOOLS: Public Schools

The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Date of Government Version: N/A Date Data Arrived at EDR: 07/13/2004 Date Made Active in Reports: N/A

Number of Days to Update: 0

Source: National Center for Education statistics

Telephone: 202-502-7300 Last EDR Contact: 07/11/2007

Next Scheduled EDR Contact: 10/08/2007

Data Release Frequency: N/A

NURSING HOMES: Directory of Nursing Homes

Information on Medicare and Medicaid certified nursing homes in the United States.

Date of Government Version: N/A Date Data Arrived at EDR: 10/11/2005 Date Made Active in Reports: N/A

Source: N/A Telephone: 800-568-3282

Last EDR Contact: 09/22/2006 Next Scheduled EDR Contact: N/A Data Release Frequency: N/A

HOSPITALS: AHA Hospital Guide

Number of Days to Update: 0

The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Date of Government Version: N/A Date Data Arrived at EDR: 10/19/1994 Date Made Active in Reports: N/A Number of Days to Update: 0

Source: American Hospital Association Telephone: 800-242-2626 Last EDR Contact: 09/22/2006 Next Scheduled EDR Contact: N/A Data Release Frequency: N/A

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

MEDICAL CENTERS: Provider of Services Listing

A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health & Human Services.

Date of Government Version: 06/01/1998 Date Data Arrived at EDR: 11/10/2005 Date Made Active in Reports: N/A Number of Days to Update: 0

Source: Centers for Medicare & Medicaid Services Telephone: 410-786-3000 Last EDR Contact: 01/12/2007

Next Scheduled EDR Contact: N/A Data Release Frequency: N/A

COLLEGES: Integrated Postsecondary Education Data

The National Center for Education Statistics' primary database on integrated postsecondary education in the United States.

Date of Government Version: N/A
Date Data Arrived at EDR: 10/12/2005
Date Made Active in Reports: N/A
Number of Days to Update: 0

Source: National Center for Education Statistics

Telephone: 202-502-7300 Last EDR Contact: 09/22/2006 Next Scheduled EDR Contact: N/A Data Release Frequency: N/A

PRIVATE SCHOOLS: Private Schools of the United States

The National Center for Education Statistics' primary database on private school locations in the United States.

Date of Government Version: N/A
Date Data Arrived at EDR: 10/07/2005
Date Made Active in Reports: N/A
Number of Days to Update: 0

Source: National Center for Education Statistics

Telephone: 202-502-7300 Last EDR Contact: 09/22/2006 Next Scheduled EDR Contact: N/A Data Release Frequency: N/A

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data

Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 06/15/2007 Date Made Active in Reports: 08/20/2007 Number of Days to Update: 66 Source: Department of Environmental Protection

Telephone: 860-424-3375 Last EDR Contact: 06/13/2007 Next Scheduled EDR Contact: 09/10/2007

Data Release Frequency: Annually

NJ MANIFEST: Manifest Information

Hazardous waste manifest information.

Date of Government Version: 04/01/2007 Date Data Arrived at EDR: 04/05/2007 Date Made Active in Reports: 05/08/2007 Number of Days to Update: 33

Source: Department of Environmental Protection

Telephone: N/A

Last EDR Contact: 07/03/2007

Next Scheduled EDR Contact: 10/01/2007 Data Release Frequency: Annually

NY MANIFEST: Facility and Manifest Data

Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Date of Government Version: 10/26/2006 Date Data Arrived at EDR: 11/29/2006 Date Made Active in Reports: 01/05/2007

Number of Days to Update: 37

Source: Department of Environmental Conservation

Telephone: 518-402-8651 Last EDR Contact: 08/30/2007

Next Scheduled EDR Contact: 11/26/2007 Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2005 Date Data Arrived at EDR: 03/17/2006 Date Made Active in Reports: 06/06/2006

Number of Days to Update: 81

Source: Department of Environmental Protection

Telephone: N/A

Last EDR Contact: 08/13/2007

Next Scheduled EDR Contact: 09/10/2007 Data Release Frequency: Annually

RI MANIFEST: Manifest information

Hazardous waste manifest information

Date of Government Version: 04/09/2007 Date Data Arrived at EDR: 04/12/2007 Date Made Active in Reports: 04/27/2007 Number of Days to Update: 15

Source: Department of Environmental Management

Telephone: 401-222-2797 Last EDR Contact: 06/18/2007

Next Scheduled EDR Contact: 09/17/2007 Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2006 Date Data Arrived at EDR: 04/27/2007

Date Made Active in Reports: 06/08/2007 Number of Days to Update: 42 Source: Department of Natural Resources

Telephone: N/A

Last EDR Contact: 07/09/2007

Next Scheduled EDR Contact: 10/08/2007 Data Release Frequency: Annually

Oil/Gas Pipelines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines.

Electric Power Transmission Line Data

Source: PennWell Corporation Telephone: (800) 823-6277

This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:

Source: American Hospital Association, Inc.

Telephone: 312-280-5991

The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing

Source: Centers for Medicare & Medicaid Services

Telephone: 410-786-3000

A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services,

a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes

Source: National Institutes of Health

Telephone: 301-594-6248

Information on Medicare and Medicaid certified nursing homes in the United States.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Public Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on elementary

and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools

Source: National Center for Education Statistics

Telephone: 202-502-7300

The National Center for Education Statistics' primary database on private school locations in the United States.

Daycare Centers: Day Care Centers, Group & Family Homes

Source: Bureau of REgulatory Services

Telephone: 517-373-8300

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 and 2005 from the U.S. Fish and Wildlife Service.


State Wetlands Data: Wetlands Inventory

Source: Department of Natural Resources

Telephone: 517-241-2254

STREET AND ADDRESS INFORMATION

© 2007 Tele Atlas North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.







APPENDIX E


AERIAL PHOTOGRAPH DOCUMENTATION






















Image courtesy of the U.S. Geological Survey
© 2004 Microsoft Corporation. **Terms of Use Privacy Statement**





APPENDIX F

SANBORN FIRE INSURANCE MAPS





The Sanborn Library, LLC


Copyright© 1941 The Sanborn Library, LLC HNS


EDR Remarch Associate

Reproduction in whole or in part of any ang of 1 he Sanborn Library, LLC may be prohibited without prior written
















APPENDIX G

HISTORICAL RESEARCH DOCUMENTATION

COMMERCIAL BUILDING FIELD SHEET

CODE:

MAP SUB.

0 0 6 0 1 0

	L	SPLIT		
0	0	8	1	
	0	00	008	LÓT

BUREAU OF TAXATION

WAYNE COUNTY, MICHIGAN

ITEM	NO.	0/	TA
	11	01	10
		85	

C	DWNSHIP ME		VINDAL		SECT	101	4	LEGAL DESC	RIPTION	1	***			8	5
STREET RAUPP EXAMINER NO.								LOT 8/	TO 8	°5	2				
1	OWNER														
	OWNER'S ADDRESS	-					M.D. Asasa. S	-							
,	YEAR BUILT 173	<u>6</u> €	ONDITION_F		STORIES	_CL	ASS AV . C +1	0 104 × 10	0						
			BUILDING D	ESC	RIPTION	_				-	COM	PUTATIO	NS		
	LAND IMPROVEMENTS		ROOF	Γ	BASEMENT	Γ	FLOORS	SQ FT STY RATE EXTRAS OR DED. COST PLOCOD ASSESSED A							
	SEWER		FLAT	1	NONE		WOOD	2667	1	23.39	ITEM	AMT.	62381		710020020 7712
	WATER	V	HIPEGNELE		PART	6	CONCRETE	1016	CAN	1			3150		
	SIDEWALK				FULL	-	ASP. TILE OVER	5376	COMC	.60			3226		
	PAVING	RC	OOF STRUCTURE		FOUNDATION		QUARRY TILE	0 010	Ė			-	68757	69	474117
	GAS	1	WOOD JOISTS	/	CONCRETE		TERRAZZO		<u> </u>				00107	01	1/17
			BAR JOISTS				=								
	TYPE		TRUSS		HEAT		INT. FINISH								
	STORE	V	WOOD DECK		NONE	/	PLAST. WALLS			1					
	SHOP		STEEL DECK		FORCED AIR		DRY WALL	 		-					
	GAS STATION		GYPSUM DECK		UNIT		CONC. BLOCK								
	GARAGE		= = _		UNIT BOILER	-	TRIM	·	٠	لجحنا	TOTAL	BLDG. A	SSMT		
	OFFICE			1	STEAM OR(H.W.)	-	CEILING (ATT)			PLAN	OF BUILDIN			YR.	T T T
	CLINIC		ROOF COVER	V	AIR CONDITION		CEIL.						150	16 74	- 23720
/	MOTEL	1	COMPOSITION		PKG.	S-							20	16 17	20100
	(NODAN)		TAR & GRAVEL		CENT.										
	EXT. WALLS				<i>ø</i>		LIGHTING								
3	CONC. BLOCK				PLUMBING		OLD STYLE							-	
1	BRICK ON BLK.	(CONSTRUCTION		NONE		FLUORESCENT								
	PORC. STEEL		WOOD FRAME		LAVATORY		ATTACHED				OVER			-	
	STONE	1	CONC. BLOCK		TILE FL.		RECESSED				OVER				
			STEEL FRAME		URINALS	/	INCOMO.								
			RE. CONC.		SHOWERS		MISC.								
	FRONT		BRICK	8	BATHS FULLE			6							
1	AVERAGE		BEAM & COL.		SPRINKLER			el el							
	RECESSED			Г										-	
	SUB STANDARD				ROOMS										-
				9	& UNITS			1					1.4	ND	
				1	£ U.R.									TAL	

COMMERCIAL BUILDING FIELD SHEET MAP SUB LOT SPLIT CODE: 006010072 **BUREAU OF TAXATION** WAYNE COUNTY, MICHIGAN ITEM NO. TOWNSHIP SECTION LEGAL DESCRIPTION DATE EXAMINER_ LOT 72 TO 80 STREET RAUPP CPIN NO. 17355 Dumpster Fence 100 OWNER. OWNER'S ADDRESS CLASS AV. C +10 198 x100 YEAR BUILT 1952 CONDITION F STORIES BUILDING DESCRIPTION COMPUTATIONS LAND IMPROVEMENTS ROOF BASEMENT EXTRAS OR DED. **FLOORS** SQ. FT. STY. RATE COST %GOOD ASSESSED VAL. ITEM SEWER FLAT NONE WOOD 23.39 130984 5600 WATER HIP & GAB PART CONCRETE 2013 CANPY 3,10 6240 SIDEWALK FULL ASP. TILE OVER 9500 CONC 5700 160 PAVING ROOF STRUCTURE FOUNDATION COULD QUARRY TILE 36 3.10 12 SLAB GAS **WOOD JOISTS** CONCRETE TERRAZZO 143036 64 **BAR JOISTS** 5 FA 10 50 98 MAG 28 420 517 TYPE TRUSS HEAT INT. FINISH STORE WOOD DECK NONE PLAST, WALLS SHOP STEEL DECK FORCED AIR DRY WALL GAS STATION GYPSUM DECK UNIT CONC. BLOCK GARAGE UNIT BOILER TRIM TOTAL BLDG, ASSMT. OFFICE STEAM OR H.W. CEILING PLAN OF BUILDING YR. CLINIC ROOF COVER AIR CONDITION CEIL. MOTEL COMPOSITION PKG. 99=64,390 TAR & GRAVEL CENT. EXT. WALLS LIGHTING CONC. BLOCK PLUMBING OLD STYLE BRICK ON BLK. CONSTRUCTION NONE **FLUORESCENT** PORC. STEEL WOOD FRAME LAVATORY ATTACHED OVER STONE TILE WALL CONC. BLOCK RECESSED RT. W.d. TRIM STEEL FRAME URINALS INCOND. FRANT. RE. CONC. SHOWERS MISC. BATHS FYLLE FRONT BRICK **AVERAGE** BEAM & COL. SPRINKLER RECESSED SUB STANDARD ROOMS (15 UNITS & V-7F LAND OFFICE TOTAL

MUNIC. COMMERCIAL BUILDING FIELD SHEET MAP SUB. LOT SPLIT CODE: 00601 **BUREAU OF TAXATION** WAYNE COUNTY, MICHIGAN ITEM NO. 7245 246 SECTION LEGAL DESCRIPTION DATE EXAMINER_ LOT 245, 246 STREET OAKWOOD NO. 2704-10 OWNER OWNER'S ADDRESS YEAR BUILT 1929 CONDITION. BUILDING DESCRIPTION COMPUTATIONS LAND IMPROVEMENTS ROOF EXTRAS OR DED. BASEMENT **FLOORS** SQ. FT. STY. RATE COST %GOOD ASSESSED VAL SEWER FLAT 3 NONE 42.21 WOOD 2440 2 102992 PART TOP WATER CONCRETE 24.47 4894 200 SIDEWALK **FULL** SLAD ASP. TILE OVER 308 4.50 1386 PAVING ROOF STRUCTURE FOUNDATION QUARRY TILE GAS WOOD JOISTS CONCRETE TERRAZZO 440 CONC ,60 264 **BAR JOISTS** TYPE TRUSS HEAT INT. FINISH Charge 11.32 98 STORE WOOD DECK NONE PLAST, WALLS SHOP STEEL DECK FORCED AIR DRY WALL GAS STATION GYPSUM DECK UNIT CONC. BLOCK GARAGE UNIT BOILER TRIM TOTAL BLDG. ASSMT. OFFICE (ATT) STEAM OR H.W. CEILING PLAN OF BUILDING AIR CONDITION CLINIC ROOF COVER CEIL. COMPOSITION PKG. TAR & GRAVEL CENT EXT. WALLS LIGHTING CONC. BLOCK PLUMBING OLD STYLE NONE IST BRICK-ON-BLK. CONSTRUCTION **FLUORESCENT** PORC. STEEL LAVATORY! WOOD FRAME ATTACHED OVER STONE TILE WALL NO CONC. BLOCK RECESSED STEEL FRAME URINALS RE. CONC. SHOWERS MISC. BATHS FLOORS FRONT BRICK AVERAGE BEAM & COL. SPRINKLER WOMEN'SQ RECESSED SUB STANDARD ROOMS 155 LAND 13 2ND TOTAL

COMMERCIAL BUILDING FIELD SHEET

CODE:

MUNIC. CODE MAP SUB. LOT 3 SPLIT

UREAU OF TAXATION	· · · · · ·
-------------------	-------------

WAYNE COUNTY, MICHIGAN

-	_			-	1.00	
ITEM	NO.	77	2	5.	5	

CITY MEIVINDALE SECTION						LEGAL DESC	RIPTION	4	F						
1	DATE			E>	CAMINER	_	76	LOT 25	75				di .	- 2	
	STREET OAKWOOD NO. 2750						101 2 -		, we	. J			1	0R40	
	OWNER							Res Car Doore Res Car 1000 Resident See Hore L							CEOULE
	YEAR BUILT 1945 CONDITION STORIES CLASS AV. C.						A . /	Vallet l							
)							20 × 93							EE MO	
BUILDING DESCRIPTION						COMPUTATIONS									
_	LAND IMPROVEMENTS		ROOF		BASEMENT		FLOORS	SQ. FT.	STY.	. RATE	EXTRAS OR DED.		eost	%GOOD	ASSESSED VAL.
	SEWER	V	FLAT		NONE 1	/	WOOD	800	2	49.28	TIEN	Aug.	39424		
	WATER			/	PART 15 KK	\$	CONCRETE	160	2	25.72			4115		,
	SIDEWALK				FULL		ASP. TILE OVER	598	1	12.86			7690		
	PAVING	RC	OOF STRUCTURE		FOUNDATION		QUARRY TILE			10.00			51229	56	28688
	GAS	1	WOOD JOISTS	4	CONCRETE		TERRAZZO						21001	-0	00000
		Ç.	BAR JOISTS					7.55							
	TYPE,		TRUSS		HEAT	1	INT. FINISH	-							
/	STORE & L.Q.	1	WOOD DECK		NONE	/	PLAST. WALLS		1.5						
- 500	SHOP		STEEL DECK		FORCED AIR		DRY WALL				, • • • • • • • • • • • • • • • • • • •				
	GAS STATION		GYPSUM DECK	1	UNIT	/	CONC. BLOCK								
	GARAGE				UNIT BOILER		TRIM				TOTAL	. BLDG. A	ASSMT.		
	OFFICE			1	STEAM OR H.W)	V	CEILING ATT			PLAN	OF BUILDIN			, YR.	
	CLINIC		ROOF COVER		AIR CONDITION		CEIL.	Ca Hanne de C						-	= 14340
		COMPOSITION PKG.					1981 50% 74 = 1434							= 24/10	
		/	TAR & GRAVEL		CENT.			ALT.					1 au	000	0,70
	EXT. WALLS		-				LIGHTING	NOCHAN	CE				NSTAI	21 2 / 7	- NC
3	CONC. BLOCK				PLUMBING	1	OLD STYLE	INVALUE	E		1	÷		000	=110
1	BRICK ON BLK.	0	CONSTRUCTION		NONE	E	FLUORESCENT				IVER			07	-//
	PORC. STEEL		WOOD FRAME	1	LAVATORY	1	ATTACHED	-	100	77-	aine 1	100.00	u u		
	STONE	/	CONC. BLOCK		TILE WALL		RECESSED	FOR					1		
			STEEL FRAME		URINALS			BLOG.	152	N VE	el Fook	E COM	MOTION		
	-		RE. CONC.		SHOWERS		MISC.	REDUC	1510	A = 1	1050				
	FRONT		BRICK	-	BATHS								reren		
1	AVERAGE		BEAM & COL.		SPRINKLER		A LONG	1.14	2071	MILL		acops	ESSED DE MADRE		
	RECESSED			-		1		WITH	400	WEUV	CATEN	15 /	KK I. III	-	
	SUB STANDARD				ROOMS										
	===			3	151								LA	ND	
				L-	210							100	TO	TAL	



Michigan on Search

WDS Quick Search ..:

What's this?

Advanced Search

Result List

WDS Online

Site ID

Site Identification

404596 / MID985607043 D AND K STARTER AND ALTERNATOR

Site Information

Site ID WMD ID MID985607043 404596

Site Legal Name

D AND K STARTER AND ALTERNATOR Site Specific Name D AND K STARTER AND ALTERNATOR

District

SOUTHEAST MICHIGAN

NAICS Codes

000000 - No NAICS Value Reported To Date

Location Address

2750 OAKWOOD

MELVINDALE, MI 48122

County: WAYNE

Country: U.S.A.

Mailing Address

2750 OAKWOOD MELVINDALE, MI 48122

County: WAYNE

Country: U.S.A.

Site Owners / Operators

Org Type Active Inactive Owner Operator Name 1/1/1970 GRASZAK DANIEL Private Yes No

Current Site Activities

Discovery Date Source

Activity

4/16/1999

State (State)

Generation of Waste Ceased/Site Closed


No Longer Generating/Still in Business

+ click to expand

Previous Site Activities

Site Comments

No records for this site





APPENDIX H

PREVIOUS ENVIRONMENTAL REPORTS



647 Academy Drive Northbrook, IL 60062 847-562-8577 888-680-8101 Fax 847-562-8552

(05-3401-0381) August 30, 2004

Mr. Edward Fitzgerald The National Republic Bank of Chicago 1201 West Harrison Street Chicago, IL 60607

Re:

Transaction Screen Environmental Site Assessment

Motor City Motel 17355 Raupp Road Melvindale, MI 48122

Dear Mr. Fitzgerald:

This Transaction Screen Environmental Site Assessment on the property listed above was completed by Northern Environmental Technologies, Inc. in accordance with American Society of Testing and Materials (ASTM) Standard Process E 1528-00 with the exceptions described within this report. The attached report describes the Site conditions, Site history and significant findings.

We appreciate the opportunity to do business with you. If you have any questions or comments regarding this report or our recommendations for the Site, please contact me at (847) 562-8577.

Sincerely

Northern Environmental Technologies, Incorporated.

Bob C. Soni, PE

Director

TRANSACTION SCREEN ENVIRONMENTAL SITE ASSESSMENT

MOTOR CITY MOTEL 17355 RAUPP ROAD MELVINDALE, MICHIGAN

August 30, 2004

Prepared For:

Mr. Edward Fitzgerald The National Republic Bank of Chicago 1201 West Harrison Street Chicago, IL 60607

Prepared By:

Northern Environmental Technologies, Incorporated 647 Academy Drive Northbrook, Illinois 60062

Project Number: 05-3401-0381

Sean M. McCuddy

Geologist

Bob C. Soni, PE

Director

© 2004 Northern Environmental Technologies, Inc.

Northern Environmental ** Hydrologists • Engineers • Geologists

TABLE OF CONTENTS

1.0 EXECUTIVE SUMMARY	1
2.0 INTRODUCTION	3
2.1 Purpose	ŝ
2.2 Detailed Scope of Services	
2.3 Limitations and Exceptions of Assessment	
2.4 User Reliance	5
3.0 SITE DESCRIPTION	
3.1 Location.	
3.1 Site and Wainity Council Change towisting	6
3.2 Site and Vicinity General Characteristics	6
3.3 Current Use of the Property	6
3.4 Current Use of Adjoining Properties	
4.0 USER PROVIDED INFORMATION	7
4.1 Environmental Liens or Activity and Use Limitations	7
4.2 Owner, Property Manager and Occupant Information	7
4.3 Additional Information	7
5.0 RECORDS REVIEW	8
5.1 Standard Environmental Record Sources	8
5.1.1 Federal	8
5.1.2 State	8
5.1.3 Unmapped Facilities	9
5.2 Sanborn Maps	9
5.3 Physical Setting	9
5.3.1 Topography	9
5.3.2 Hydrogeology	9
5.3.3 Geology	9
5.4 LUST Database	9
6.0 SITE RECONNAISSANCE	10
6.1 Methodology and Limiting Conditions	10
6.2 General Site Setting	10
6.2.1 Polychlorinated Biphenyls (PCBs)	10
6.2.2 Wetlands	10
6.3 Exterior Observations	10
6.3.1 Underground Storage Tanks (USTs)	10
6.3.2 Aboveground Storage Tanks (ASTs)	10
6.3,3 Solid Waste Disposal	10
6.3.4 Hazardous Substance Use	10
6.4 Interior Observations	
6.4.1 Building Materials	, 11
6.4.2 Hazardous Substance Use	. 11
6.4.3 Asbestos Containing Material (ACM)	. 11
6.4.4 Lead-Based Paint	. 11



	TABLE OF CONTENTS (CONTINUED)	
7.0 INTERVIE	EWS	12
7.1 Interviev 7.2 Interviev	v with Key Site Managerv with local Government Officials	
8.0 FINDINGS	S & CONCLUSIONS	13
9.0 REFEREN	CES CITED	14
Ę	<u>FIGURES</u>	
Figure 1: Site 1 Figure 2: Site 1	Location and Local Topography Layout	
	ATTACHMENTS	
Attachment C:	Questionnaire EDR Transaction Screen Map Report and Sanborn Maps Site Photographs Ouglifications of Northern Environmental Professionals	



647 Academy Drive Northbrook, IL 60062 847-562-8577 888-680-8101 Fax 847-562-8552

1.0 EXECUTIVE SUMMARY

On August 23, 2004, Northern Environmental Technologies, Incorporated (Northern Environmental), conducted an Environmental Site Assessment (ESA) transaction screen for the property at 17355 Raupp Road, Melvindale, Michigan (the Property). The ESA transaction screen was conducted in general conformance with American Society of Testing and Materials (ASTM) Standard Process E 1528-00. As part of this assessment, a questionnaire was completed by the owner of the Property. This questionnaire is included in Attachment A of this document.

The purpose of the Transaction Screen ESA is to provide information regarding potential environmental concerns associated with the Property, or nearby land uses that could affect soil and/or groundwater quality at the Property. This report describes the methods used to conduct the Transaction Screen ESA, summarizes the findings, discusses the significance of the findings, and assesses the need for additional work to better characterize potential environmental concerns.

The Property is located on the west side of Raupp Road, at the intersection of Raupp Road and Oakwood Boulevard. The Property is improved with a one-story brick, concrete block, and wood panel building near the center of the Site. The building was constructed approximately 35 years ago as a motel. Asphalt-paved parking is located east of the building. A garbage dumpster is located at the north end of the parking lot. A gravel alley runs along the north and west sides of the motel.

The Property is located in an area of commercial and residential properties. North of the Property are apartments and single-family residences. East of the Property, across Raupp Road, is a Wendy's restaurant and an apartment complex. The Crossroads Bar and another apartment complex are located west of the Property. South of the motel, across Oakwood Boulevard are a White Castle restaurant, a Citgo gas station, and a car wash.

Northern Environmental subcontracted Environmental Data Resources, Inc. (EDR), to perform a records search of the numerous federal and state databases for nearby potential environmental concerns associated with the Property. There is one CERCLIS site and one CORRACTS site located within a mile of the Property. There are thirteen LUST sites, two UST sites, and five State Hazardous Waste sites within the applicable search radii of the Property. None of the federal or state sites appears to pose an environmental threat to the Property.

A database of Leaking Underground Storage Tank sites, both active and closed, was searched for Melvindale, Michigan. The database program is maintained by the Michigan Department of Environmental Quality. No LUST incidents were found on or adjacent to the Property.



647 Academy Drive Northbrook, IL 60062 847-562-8577 888-680-8101 Fax 847-562-8552

Northern Environmental contracted EDR to review fire insurance maps to determine whether any building or other improvements on the Property or adjoining properties are identified as having been used for an industrial use or uses likely to lead to contamination of the Property. Six Sanborn maps from the following years were available for the Property: 1941, 1950, 1952, 1957, 1961, and 1966. The maps show what appears to be an old gasoline station at the southeast corner of the intersection of Oakwood Boulevard and Dix Road, opposite of the motel. If the gasoline tanks at this gas station ever leaked, it is conceivable that petroleum products could have contaminated the Property if they spread outward far enough from the facility.

Mr. Nick Patel (for Ms. Sangita Patel), owner of the Property, completed the Transaction Screen Questionnaire on August 23, 2004. Mr. Patel answered negative to questions 1-20. Mr. Sean McCuddy of Northern Environmental completed the questionnaire during the site visit. Mr. McCuddy answered questions 11a and 11b affirmative because of a pipe of unknown use identified in the ground on the west side of the building. The pipe represents a potential Recognized Environmental Condition (REC).

No other environmental concerns were identified on the Property or surrounding properties than those listed above. Based on the specific objectives of this assessment, Northern Environmental recommends that further environmental investigation be conducted on the subject Property to determine the exact nature of the pipe identified as a potential REC.

The results of this study are based on the professional interpretation of information reasonably available to Northern Environmental during the project. Northern Environmental has presumed that the information provided by the cited references is complete and correct. Northern Environmental does not warrant that this report represents an exhaustive study of all possible environmental conditions at the Property. However, the items investigated as part of this study represent the most likely sources of environmental concern, and are consequently believed to address the required subject material contained within the ASTM Transaction Screen Standard, with noted exception(s) previously mentioned.

August 30, 2004

Motor City Motel Transaction Screen ESA

2.0 INTRODUCTION

Ms. Sangita Patel authorized Northern Environmental Technologies, Incorporated (Northern Environmental) on August 19, 2004, to perform a Transaction Screen Environmental Site Assessment on the Motor City Motel at 17355 Raupp Road, Melvindale, Michigan (the Property). Refer to Figure 1, Site location and Local Topography, for the location of the Property.

2.1 Purpose

The purpose of the Transaction Screen ESA is to provide information regarding potential environmental concerns associated with the Property, or nearby land uses that could affect soil and/or groundwater quality at the Property. This report describes the methods used to conduct the Transaction Screen ESA, summarizes the findings, discusses the significance of the findings, and assesses the need for additional work to better characterize potential environmental concerns.

2.2 Detailed Scope of Services

Three tasks were completed which focused on specific information or potential environmental concerns. Each task uses information gathered in previous tasks to better direct subsequent portions of the assessment. The following tasks were completed:

Task 1.0	Review Existing Data
Task 2 0	Inspect Site

Task 3.0 Evaluate Data and Prepare Report

The methods used to complete the tasks conform to the requirements of American Society for Testing and Materials (ASTM) Designation: E 1528-00 (ASTM, 2000) and are described in more detail in the following subsections.

Task 1.0 Review Existing Data

Existing data were reviewed to identify recognized environmental concerns associated with the Property. Environmental records (Environmental Data Resources, Incorporated, 2004), and user provided environmental information were evaluated to determine historical land ownership and use of the Property.

Northern Environmental subcontracted EDR to perform a records search of the following federal and state databases for nearby potential environmental concerns. The EDR Transaction Screen Map Report is included in Attachment B.

Federal Databases

- ▶ NPL (National Priorities List)
- CERCLIS, CERCLIS NFRAP (Comprehensive Environmental Response, Compensation, and Liability Information System)
- ► CORRACTS (Corrective Action Report)

August 30, 2004

- ► RCRIS-TSD (Resources Conservation and Recovery Information System Treatment, Storage, and Disposal Facilities)
- RCRIS (Resources Conservation and Recovery Information System Large and Small Quantities Generators)
- ERNS (Emergency Response Notification System)
- FINDS (Facility Index System/Facility Identification Initiative Program)
- ► HMIRS (Hazardous Materials Information Reporting System)
- ► MLTS (Materials Licensing Tracking System)
- MINES (Mines Master Index File)
- ▶ PADS (Polychlorinated Biphenyls [PCB] Activity Database System)
- RAATS (RCRA Administrative Action Tracking System)
- ► TRI (Toxic Release Inventory)
- ► TSCA (Toxic Substances Control Act Inventory)
- ► FTTS, FIFRA TSCA (Federal Insecticide, Fungicide, & Rodenticide Act)

State Databases

- ► SHWS (State Oversight List)
- SCL (Michigan State Category List)
- ▶ UST (Michigan Registered Underground Storage Tank List)
- ► SWF (Michigan Permitted Solid Waste/Inventory Facilities)
- LUST (Michigan Leaking Underground Storage Tank List)
- ▶ NEIPC (Michigan NEIPC Historical Solid Waste Disposal Inventory)
- SRP (Site Remediation Program Database)

Task 2.0 Inspect Site

Northern Environmental inspected the Property at 17355 Raupp Road, Melvindale, Michigan, on August 23, 2004. The site inspection was used to identify and record visible environmental conditions such as USTs or ASTs, hazardous substances, discolored soil or pavement, stressed vegetation, burn piles, and solid waste that could affect soil and/or groundwater quality at the Property. Site photographs were taken and are included in Attachment C.

Task 3.0 Evaluate Data and Prepare Report

Data collected from Tasks 1.0 and 2.0 were evaluated to determine if potential environmental concerns are associated with the Property, and if nearby land uses could affect soil or groundwater quality at the Property. The findings of Tasks 1.0 and 2.0 are summarized in the following sections.

2.3 Limitations and Exceptions of Assessment

The results of this study are based on the professional interpretation of information reasonably available to Northern Environmental during the project. Northern Environmental has presumed that the information provided by the cited references is complete and correct. Northern Environmental does not warrant that this report represents an exhaustive study of all possible environmental conditions at the Property. However, the items investigated as part of this study represent the most likely sources of environmental concern, and are consequently believed to address the required subject material contained within the ASTM Transaction Screen Standard,



August 30, 2004

with noted exception(s) previously mentioned. Qualifications of Northern Environmental Personnel are included in Attachment D.

2.4 User Reliance

The conclusions presented in this report are professional opinions based upon visual observations and a review of readily available public records. Quantitative environmental testing of soil and groundwater was not conducted. Northern Environmental's interpretation of the available historical information and documents reviewed, as described in this report were also considered in the conclusions.

The users (The National Republic Bank of Chicago & their client) may rely upon this transaction screen in order to facilitate the purchase or refinancing of the Property. No other parties may rely upon this transaction screen without permission from the users and Northern Environmental Technologies, Inc.

August 30, 2004

3.0 SITE DESCRIPTION

3.1 Location

The Property is located on the west side of Raupp Road, at the intersection of Raupp Road and Oakwood Boulevard. Please see Figure 1 in the attachments of this document for a site location map.

3.2 Site and Vicinity General Characteristics

The Property is improved with a one-story brick, concrete block, and wood panel building near the center of the Site. The building was constructed approximately 35 years ago as a motel. Asphalt-paved parking is located east of the building. A garbage dumpster is located at the north end of the parking lot. A gravel alley runs along the north and west sides of the motel. Please see Figure 2 of this document for a site map.

The building has 22 rooms available for boarding customers. The building also holds an office area, living quarters for the motel manager, a laundry room, and a boiler room. There is no swimming pool at the Site. Each room is equipped with its own air conditioning unit. The building is heated centrally by a gas-fired boiler. The building is connected to the city water and sanitary sewer systems. Photographs of the Property are included in Attachment C.

3.3 Current Use of the Property

The Property is currently occupied by the Motor City Motel. Mr. Patel, owner of the Property, indicated that the motel was constructed approximately 35 years ago. Mr. Patel thought that the Property had always been a motel.

3.4 Current Use of Adjoining Properties

The Property is located in an area of commercial and residential properties. North of the Property are apartments and single-family residences. East of the Property, across Raupp Road, is a Wendy's restaurant and an apartment complex. The Crossroads Bar and another apartment complex are located west of the Property. South of the motel, across Oakwood Boulevard are a White Castle restaurant, a Citgo gas station, and a car wash.

August 30, 2004

4.0 USER PROVIDED INFORMATION

4.1 Environmental Liens or Activity and Use Limitations

The user has provided no information regarding any environmental liens or governmental notification relating to past or recurrent violations of environmental laws with respect to the Property.

4.2 Owner, Property Manager and Occupant Information

Property Owner: Ms. Sangita Patel.

Property Manager: Ms. Sangita Patel.

Property Occupant: Ms. Sangita Patel.

4.3 Additional Information

No additional information was provided by the user.

August 30, 2004

5.0 RECORDS REVIEW

5.1 Standard Environmental Record Sources

Northern Environmental subcontracted EDR to perform a records search of the numerous federal and state databases for nearby potential environmental concerns associated with the Property, or nearby land uses that could affect soil and/or groundwater quality at the Property. The records were reviewed and are included in Attachment B. The following sections summarize the results presented in the EDR report.

5.1.1 Federal

There are five RCRIS Small Quantity Generator (SQG) sites within a quarter-mile of the Property. One CERCLIS site and one CORRACTS site are present within a half-mile and mile of the Property, respectively.

Two of the RCRIS-SQG sites are located less than 1/8-mile from the Property. However, neither of them is directly adjacent to the Motor City Motel. The two closest RCRIS sites are at D & K Starter and Alternator, 2750 Oakwood Blvd, and at Express Auto, 17420 Dix Rd. Both sites are more than 300 feet from the motel and do not appear to pose an environmental threat to the Property. None of the five RCRIS sites has any reported violations.

Neither the CERCLIS site nor the CORRACTS site appears to threaten the environmental integrity of the Property.

5.1.2 State

There are five State Hazardous Waste (SHW) sites located ¼ to 1 mile from the Site. Two UST sites are present within a ¼-mile of the Site. Thirteen LUST sites were found within 1/8- to 1/2-mile of the motel. None of the SHW sites, all of which are more than 1300 feet from the site, appears to affect the environmental integrity of the Property.

Only two of the thirteen LUST incidents occurred within a ¼-mile radius of the Site. These two closest incidents occurred at the Detroit Bumper Mart (17162 Francis Street) and the Salem Machine Company (17100 Francis Street). Both of the incidents are closed, and both sites are more than 1100 feet from the Property. None of the thirteen LUST incidents appear to have impacted the Motor City Motel.

The Detroit Bumper Mart is also a state UST site. The only registered tank, a 2000-gallon gasoline tank, was removed from the ground in August of 1996. The only other UST site within a ¼-mile of the Property is at the Oakwood Minimart at 2661 Oakwood Blvd. This UST site is believed to be the location of the Citgo gas station south of the motel across Oakwood Blvd. The site is approximately 140 feet from the motel. Five tanks are registered at the site. No LUST incidents have been reported. Given the proximity of the Citgo station to the Motor City Motel, any future release at the station could pose a potential threat to the environmental integrity of the Property.

There is also a coal gas site within the EDR search radius. The site is approximately 4500 feet from the Property and does not appear to threaten the environmental integrity of the Property.



August 30, 2004

5.1.3 Unmapped Facilities

Four unmapped facilities were listed in the EDR report. None of these sites appears to threaten the environmental integrity of the Property.

5.2 Sanborn Maps

Northern Environmental contracted EDR to review fire insurance maps to determine whether any building or other improvements on the Property or adjoining properties are identified as having been used for an industrial use or uses likely to lead to contamination of the Property. Six Sanborn maps from the following years were available for the Property: 1941, 1950, 1952, 1957, 1961, and 1966. The maps show what appears to be an old gasoline station at the southeast corner of the intersection of Oakwood Boulevard and Dix Road, opposite of the motel. If the gasoline tanks at this gas station ever leaked, it is conceivable that petroleum products could have contaminated the Property if they spread outward far enough from the facility. The Sanborn Maps are included in Attachment B.

5.3 Physical Setting

5.3.1 Topography

General topography at the Property is at an elevation of approximately 590 feet above mean sea level (MSL). The general surface topography of the Property is slab-on-grade asphalt. The Property location and local topography is included in Figure 1.

5.3.2 Hydrogeology

The expected groundwater flow direction is generally north toward River Rouge. Man-made features such as wells, roads, filled areas, buried utility lines and sewers, drainage ditches, and railroads may alter the natural shallow groundwater flow direction. Surface drainage on the Property is overland and toward the storm sewer inlets located in surrounding streets.

5.3.3 Geology

The surficial geology of the subject area, according to the Michigan Surficial Geology map (http://www.ncrs.fs.fed.us/gla/geology/mi-surf.htm), appears to be lacustrine clay and silt. If this area is confirmed to be lacustrine clay and silt, there is a slight risk of contamination of the Property if environmental incidents occur on adjacent properties.

5.4 LUST Database

A database of Leaking Underground Storage Tank sites, both active and closed, was searched for Melvindale, Michigan. The database program is maintained by the Michigan Department of Environmental Quality (http://www.deq.state.mi.us/lustcs/LUST_Download.asp). No LUST incidents were found on or adjacent to the Property.

August 30, 2004

6.0 SITE RECONNAISSANCE

6.1 Methodology and Limiting Conditions

Northern Environmental conducted an Environmental Site Assessment (ESA) transaction screen on August 23, 2004. Photographs taken during the site visit are included in Attachment C. The ESA transaction screen was conducted in general conformance with American Society of Testing and Materials (ASTM) Standard Process E 1528-00. As part of this standard, a questionnaire was completed by the owner of the Property and by the environmental professional who conducted the site visit. A copy of the questionnaire is located in Attachment A of this document.

6.2 General Site Setting

6.2.1 Polychlorinated Biphenyls (PCBs)

There is a pole-mounted transformer located on the west side of the gravel alley behind the motel (Figure 2). The transformer was not marked as to PCB content on the day of inspection. There were no leaks noted in the area of the transformer. There were no other potential sources of PCBs noted on the day of inspection.

6.2.2 Wetlands

Northern Environmental did not observe wetlands in the immediate vicinity of the Property.

6.3 Exterior Observations

6.3.1 Underground Storage Tanks (USTs)

Northern Environmental observed no physical evidence of underground storage tanks (USTs) on the Property. However, a pipe of unknown use was observed in the ground in the grassy area between the west wall of the building and the gravel alley. Although the pipe is believed to be a sewer clean out, it is a potential Recognized Environmental Condition (REC). There were no vent pipes, fill ports, copper lines or tanks noted on the day of inspection.

6.3.2 Aboveground Storage Tanks (ASTs)

Northern Environmental observed no physical evidence of ASTs on the Property.

6.3.3 Solid Waste Disposal

Northern Environmental did not observe any areas that appeared to be filled or graded by non-natural materials.

6.3.4 Hazardous Substance Use

Hazardous substances are used on site in association with the general maintenance and upkeep of the Property. No hazardous substances were observed outside of the building on the day of inspection.

August 30, 2004

6.4 Interior Observations

6.4.1 Building Materials

Buildings were constructed of concrete block, brick, wood, drywall interior, and poured cement or tiled floors.

6.4.2 Hazardous Substance Use

The general maintenance and upkeep of the building are associated with the use of hazardous substances. Cleaning solutions, mild solvents, and paint were noted on the Property on the day of inspection. All containers are five gallons or less and in sound condition.

6.4.3 Asbestos Containing Material (ACM)

Northern Environmental did not observe any asbestos-containing material during the site visit. A comprehensive asbestos study is beyond the scope of this assessment. If information is required regarding ACM, Northern Environmental can be retained to conduct an asbestos study.

6.4.4 Lead-Based Paint

No evidence of lead based paint was observed during the site visit. If further information is required regarding lead based paint, limited testing can be completed by Northern Environmental.

August 30, 2004

7.0 INTERVIEWS

7.1 Interview with Key Site Manager

The current owner of the Motor City Motel, Mr. Nick Patel, was interviewed on the day of inspection. Mr. Patel completed the ASTM questionnaire as part of this interview. Mr. Patel answered negative to all questions. The questionnaire is included in Attachment A.

7.2 Interview with Local Government Officials

No local government officials were interviewed for this report.

August 30, 2004

8.0 FINDINGS & CONCLUSIONS

Information gathered from a review of existing data and a site inspection was evaluated to determine the potential for soil or groundwater impacts at the Site. Based on this information, the following conclusions were made:

- ▶ The general maintenance and upkeep of the building are associated with the use of hazardous substances. Cleaning solutions, mild solvents, and paint were noted on the Property on the day of inspection. All containers are five gallons or less and in sound condition.
- A pipe of unknown use was observed in the ground behind the motel. Although it is believed to be a sewer line clean-out, the pipe represents a potential REC.
- ▶ One CERCLIS site and one CORRACTS site are located more than a ½-mile from the Property. Five RCRIS-SQG sites are present within ¼-mile of the motel. None of these sites is adjacent to the Property, and none of them has any recorded violations.
- ► There are thirteen LUST sites, two UST sites, and five State Hazardous Waste sites within the applicable search radii of the Property. One of the UST sites is the Citgo gas station located just south of the motel across Oakwood Blvd. None of the other sites is directly adjacent to the Property.
- ▶ None of the federal or state sites near the Motor City Motel appears to threaten the environmental integrity of the Property.

We have performed a *Transaction Screen Environmental Site Assessment*, in conformance with the scope and limitations of ASTM Practice E 1528-00, of the Property located at 17355 Raupp Road, Melvindale, Michigan. Any exceptions to or deletions from this practice are described in the Summary of Findings section of this report.

No other environmental concerns were identified on the Property or surrounding properties than those listed above. Based on the specific objectives of this assessment, Northern Environmental recommends that further environmental investigation be conducted on the subject Property to determine the exact nature of the pipe identified as a potential REC.

The results of this Transaction Screen ESA are based upon interpretation of the information available to Northern Environmental given the time and budget constraints of this project. Northern Environmental has assumed that the information provided by the cited references is complete and correct. Northern Environmental does not warrant that this report represents an exhaustive study of all possible environmental concerns.

August 30, 2004

9.0 REFERENCES CITED


American Society for Testing and Materials, Standard Practice for Environmental Site Assessments: Transaction Screen Environmental Site Assessment Process, Designation: E 1528-00, 2000.

Environmental Data Resources, Inc., "The EDR Transaction Screen Map Report," August 25, 2004.

Http://www.ncrs.fs.fed.us/gla/geology/mi-surf.htm. Michigan Surficial Geology Map, August 26, 2004.

Http://www.deq.state.mi.us/lustcs/LUST_Download.asp. Leaking Underground Storage Tank Sites, Michigan Department of Environmental Quality, August 26, 2004.

Http://www.topozone.com. Topographic map of Motor City Motel location, Melvindale, MI, August 25, 2004.



http://www.topozone.com



CONTOUR INTERVAL 10 FEET NATIONAL GEODETIC VERTICAL DATUM

Northern Environmentalsm
Hydrologists · Engineers · Surveyors · Scientists

647 ACADEMY DRIVE, NORTHBROOK, ILLINOIS Phone: 847-562-8577 Fax 847-562-8552

_	WISCONSIN						
Į	DATE: 8/25/04						

CREATION DATE: 8/25/0-DRAWN BY: SXM

REVISION DATE:

THIS DRAWING AND ALL INFORMATION CONTAINED THEREON IS THE PROPERTY OF NORTHERN ENVIRONMENTAL INCORPORATED AND SHALL NOT BE COPIED OR USED EXCEPT FOR THE PURPOSE FOR WHICH IT IS EXPRESSLY FURNISHED.

MICHIGAN A ILLINOIS A IOWA


SITE LOCATION & LOCAL TOPOGRAPHY

MOTOR CITY MOTEL 17355 RAUPP ROAD MELVINDALE, MICHIGAN

PROJECT NUMBER:

05-3401-0381

FIGURE 1



ATTACHMENT A
QUESTIONNAIRE



ENVIRONMENTAL SITE ASSESSMENT TRANSACTION SCREEN QUESTIONNAIRE

This document is an excerpt of Practice E 1528-00: Standard Practice for Environmental Site Assessments: Transaction Screen Process, which is under the jurisdiction of ASTM Committee E50 on Environmental Assessment and is the direct responsibility of Subcommittee E50.02 on Commercial Real Estate Transactions. This questionnaire represents only Sections 5 and 6 of Practice E 1528-00 and should not be construed as being the complete standard. It is necessary to refer to the full standard prior to using this questionnaire. COPYRIGHT© 2000 ASTM INTERNATIONAL, West Conshohocken, PA. Prior edition copyrighted 1996. Stock #: ADJE1528. For the complete standard, or to order additional copies of this questionnaire, contact ASTM Customer Service at (610) 832-9585.

5. Introduction to Transaction Screen Questionnaire

- 5.1 Process—The transaction screen process consists of asking questions contained within the transaction screen questionnaire of owners and occupants of the property, observing site conditions at the property with direction provided by the transaction screen questionnaire, and, to the extent reasonably ascertainable, conducting limited research regarding certain government records and certain standard historical sources. The questions asked of owners are the same questions as those asked of occupants.
- 5.2 Guide—The transaction screen questionnaire is followed by a guide designed to assist the person completing the transaction screen questionnaire. The guide to the transaction screen questionnaire is set out in Sections 7-10 of this practice. The guide is divided into three sections: Guide for Owner/Occupant Inquiry, Guide to Site Visit, and Guide to Government Records/Historical Sources Inquiry.
- 5.2.1 To assist the user, its employee or agent, or the environmental professional in preparing a report, the guide repeats each of the questions set out in the transaction screen questionnaire in both the guide for owner/accupant inquiry and the guide to site visit. The questions regarding government records/historical sources inquiry are also repeated in the guide to that section.
- 5.2.2 The guide also describes the procedures to be followed to determine if reliance upon the information in a prior *environmental site assessment* is appropriate under this practice.
- 5.2.3 A user, his employee or agent, or environmental professional conducting the transaction screen process should not use the transaction screen questionnaire without reference to, or familiarity from prior usage with, the guide.
- 5.3 User and Preparer—The user conducting the transaction screen process is the party seeking to perform appropriate inquiry with respect to the property. The user may delegate the preparation of the transaction screen questionnaire to an employee or agent of the user or may contract with a third party to prepare the questionnaire on behalf of the user. The person preparing the questionnaire is the preparer, who may be either the user or the person to whom the user has delegated the preparation of the transaction screen questionnaire.
- 5.4 Exercise of Care— The preparer conducting the transaction screen process should use good faith efforts in determining answers to the questions set forth in the transaction screen questionnaire. The user should take time and care to check whatever records are in the user's possession. The preparer should ask all persons to whom questions are directed to give answers to the best of the respondent's knowledge. As required by Section 9601(35)(B) of CERCLA, the user or preparer should discuss with a responsible person in authority in the user's organization (if any) any specialized knowledge or experience relating to hazardous substances on the property and the preparer should understand such information.
- 5.5 Knowledge—The owner or occupant of the property to which portions of the transaction screen questionnaire are directed should have sufficient knowledge and experience with respect to the property or in the owner's or occupant's particular business to understand the purpose and use of the transaction screen questionnaire. All answers should be given to the best of the owner's or occupant's actual knowledge.
- 5.5.1 While the person conducting the *transaction screen process* has an obligation to ask the questions set forth in the *transaction screen questionnaire*, in many instances the parties to whom the questions are addressed will have no obligation to answer them. The *user* is only required to obtain information to the extent it is *reasonably ascertainable*.
- 5.5.2 If the preparer asks the questions set forth in the transaction screen questionnaire, but does not receive any response or receives partial responses, the questions will be deemed to have been answered provided the questions have been asked, or were attempted to be asked, in person or by telephone and written records have been kept of the person to whom the questions were addressed and their responses, or the questions have been asked in writing sent by certified or

- registered mail, return receipt requested, postage prepaid, or by private, commercial overnight carrier and no responses have been obtained after at least two follow-up telephone calls were made or written request was sent again asking for responses.
- 5.5.3 The transaction screen questionnaire and the transaction screen guide sometimes include the phrase "to the best of your knowledge." Use of this phrase shall not be interpreted as imposing a constructive knowledge standard when it is not included or as imposing anything other than an actual knowledge standard for the person answering the questions, regardless of whether it is used. It is sometimes included as an assurance to the person being questioned that he or she is not obligated to search out information he or she does not currently have in order to answer the particular question.
- 5.6. Conclusions Regarding Affirmative or Unknown Answers.—If any of the questions set forth in the transaction screen questionnaire are answered in the affirmative, the user must document the reason for the affirmative answer. If any of the questions are not answered or the answer is unknown, the user should document such nonresponse or answer of unknown and evaluate it in light of the other information obtained in the transaction screen process, including, in particular, the xiv visit and the government records/historical sources inquiry. If the user decides no further inquiry is warranted after receiving no response, an answer of unknown or an affirmative answer, the user must document the reasons for any such conclusion.
- 5.6.1 Upon obtaining an affirmative answer, an answer of unknown or no response, the *user* should first refer to the guide. The guide may provide sufficient explanation to allow a *user* to conclude that no further inquiry is appropriate with respect to the particular question.
- 5.6.2 If the guide to a particular question does not, in itself, permit a user to conclude that no further inquiry is appropriate, then the user should consider other information obtained from the transaction screen process relating to this question. For example, while on the site performing a site visit, a person may find a storage tank on the property and therefore answer Question 10 of the transaction screen questionnaire in the affirmative. However, during or subsequent to the owner/occupant inquiry, the owner may produce evidence that substances now or historically contained in the tank (for example, water) are not likely to cause contamination.
- 5.6.3 If either the guide to the question or other information obtained during the transaction screen process does not permit a user to conclude no further inquiry is appropriate with respect to such question, then the user must determine, in the exercise of the user's reasonable business judgment, based upon the totality of unresolved affirmative answers or answers of unknown received during the transaction screen process, whether further inquiry may be limited to those specific issues identified as of concern or should proceed with a full Phase 1 Environmental Site Assessment.
- 5.7 Presumption—A presumption exists that further inquiry is necessary if an affirmative answer is given to a question or because the answer was unknown or no response was given. In rebutting this presumption, the user should evaluate information obtained from each component of the transaction screen process and consider whether sufficient information has been obtained to conclude that no further inquiry is necessary. The user must determine, in the exercise of the user's reasonable business judgment, the scope of such further inquiry; whether to proceed with a Phase I Environmental Site Assessment prepared in accordance with Practice E 1527 or a lesser inquiry directed at specific issues raised by the questionnaire.
- 5.8 Further Inquiry Under Practice E 1527—Upon completing the transaction screen questionnaire, if the user concludes that a Phuse I Environmental Site Assessment is needed, the user should proceed with such inquiry with the advice and guidance of an environmental professional. Such further inquiry should be undertaken in accordance with Practice E 1527.
- 5.9 Signature—The user and the preparer of the transaction screen questionnaire must complete and sign the questionnaire as provided at the end of the questionnaire.

			-			9 2			111.0
	6.1 Persons to Be Questioned—The following questions should be asked of (1) the current owner of the property, (2) any major occupant of the property or, if the property does not have any major occupants, at least 10 % of the occupants of the property, and (3) in addition to the current owner and the occupants identified in (2), any occupant likely to be using, treating, generating, storing, or disposing of hazardous substances or petroleum products on or from the property. A major occupant is any occupant using at least 40 % of the leasable area of the property	propert need to person and in g sure to	y containi ask quest to answer good faith observe th y. The gu	ng both re ions of the all questic . When co ne property	sidential ar residentia ons to the b	nd comm I occupa est of the ne site vi ouildings	nercial use unts. The p e responde sit column and other	s, the <i>prep</i> reparer s ent's <i>actu</i> n, the <i>prep</i> structure	multifamily parer does not hould ask each al knowledge parer should be s on the c of this
	Description of Site: Address:								
	motor City motel								
-	17355 Raupp St.								
	Melvindale MI 48122								
1	χ		Õ		ŏ			0.1	
	Question	,	Owner			upants plicab			erved During lite Visit
7	la. Is the <i>property</i> used for an industrial use?	Yes	(No)	Unk	Yes	No	Unk	Yes	No
	1b. Is any adjoining property used for an industrial use?	Yes	(No)	Unk	Yes	No	Unk	Yes	No
1	2a. Did you observe evidence or do you have any prior knowledge that the property has been used for an industrial use in the past?	Yes	(No)	Unk	Yes	No	Unk	Yes	(No)
	2b. Did you observe evidence or do you have any prior knowledge that any adjoining property has been used for an industrial use in the past?	Yes	(N)	Unk	Yes	No	Unk	Yes	No
	3a. Is the <i>property</i> used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	Yes	(No)	Unk	Yes	No	Unk	Yes	(No)
J	3b. Is any <i>adjoining property</i> used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	Yes	No	Unk	Yes	No	Unk	Yes	(No)
	4a. Did you observe evidence or do you have any prior knowledge that the <i>property</i> has been used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	Yes	(No)	Unk	Yes	No	Unk	Yes	No
]	4b. Did you observe evidence or do you have any prior knowledge that any adjoining property has been used as a gasoline station, motor repair facility, commercial printing facility, dry cleaners, photo developing laboratory, junkyard or landfill, or as a waste treatment, storage, disposal, processing, or recycling facility (if applicable, identify which)?	Yes	(No)	Unk	Yes	No	Unk	Yes	No
	5a. Are there currently any damaged or discarded automotive or industrial batteries, pesticides, paints, or other chemicals in individual containers of >5 gal (19 L) in volume or 50 gal (190 L) in the aggregate, stored on or used at the property or at the facility?	Yes	(No)	Unk	Yes	No	Unk	Yes	(No)
	5b. Did you observe evidence or do you have any prior knowledge that there have been previously any damaged or discarded automotive or industrial batteries, or pesticides, paints, or other chemicals in individual containers of >5 gal (19 L) in volume or 50 gal (190 L) in the aggregate, stored on or used at the <i>property</i> or at the facility?	Yes	No	Unk	Yes	No	Unk	Yes	(No)
	6a. Are there currently any industrial <i>drums</i> (typically 55 gal (208 L)) or sacks of chemicals located on the <i>property</i> or at the facility?	Yes	(No)	Unk	Yes	No	Unk	Yes	(N)
	6b. Did you observe evidence or do you have any prior knowledge that there have been previously any industrial <i>drums</i> (typically 55 gal (208L)) or sacks of chemicals located on the <i>property</i> or at the facility?	Yes	(No	Unk	Yes	No	Unk	Yes	No
	7a. Did you observe evidence or do you have any prior knowledge that fill dirt has been brought onto the property that originated from a contaminated site?	Yes	No) Unk	Yes	No	Unk	Yes	No
	* Unk = "unkown" or "no response". Copyright © 2000 ASTM INTERNATIONAL, West Conshobocken, PA	1						J	1005

Copyright © 2000 ASTM INTERNATIONAL, West Conshohocken, PA
This document is an excerpt of E 1528-09: Standard Practice for Environmental Site Assessments: Transaction Screen Process, which is under the jurisdiction of ASTM Committee E50 on Environmental Assessment and is the direct responsibility of Subcommittee E50.02 on Commercial Real Estate Transactions. This questionnaire represents only Sections 5 and 6 of Practice E 1528-00 and should not be construed as being the complete standard. It

1.0				
	Question	Owner	Occupants (if applicable)	Observed During Site Visit
	7b. Did you observe evidence or do you have any prior knowledge that <i>fill dirt</i> has been brought onto the <i>property</i> that is of an unknown origin?	Yes No Unk	Yes No Unk	Yes (No
3	8a. Are there currently any <i>pits, ponds</i> , or <i>lagoons</i> located on the <i>property</i> in connection with waste treatment or waste disposal?	Yes No Unk	Yes No Unk	Yes (No)
	8b. Did you observe evidence or do you have any prior knowledge that there have been previously, any pits, ponds, or lagoons located on the <i>property</i> in connection with waste treatment or waste disposal?	Yes (No) Unk	Yes No Unk	Yes No
	9a. Is there currently any stained soil on the <i>property</i> ?	Yes (No) Unk	Yes No Unk	Yes (No)
	9b. Did you observe evidence or do you have any prior knowledge that there has been previously, any stained soil on the <i>property</i> ?	Yes No Unk	Yes No Unk	Yes (No)
	10a. Are there currently any registered or unregistered storage tanks(above or underground) located on the <i>property</i> ?	Yes (No) Unk	Yes No Unk	Yes No
	10b. Did you observe evidence or do you have any prior knowledge that there have been previously, any registered or unregistered storage tanks(above or underground) located on the <i>property</i> ?	Yes No Unk	Yes No Unk	Yes (No
	11a. Are there currently any vent pipes, fill pipes, or access ways indicating a fill pipe protruding from the ground on the <i>property</i> or adjacent to any structure located on the <i>property</i> ?	Yes (No) Unk	Yes No Unk	(Ye) \$ 5M.
	11b. Did you observe evidence or do you have any prior knowledge that there have been previously, any vent pipes, fill pipes, or access ways indicating a fill pipe protruding from the ground on the <i>property</i> or adjacent to any structure located on the <i>property</i> ?	Yes No Unk	Yes No Unk	Yes SM.
	12a. Is there currently evidence of leaks, spills or staining by substances other than water, or foul odors, associated with any flooring, drains, walls, ceilings, or exposed grounds on the <i>property</i> ?	Yes (No) Unk	Yes No Unk	Yes (No)
	12b. Did you observe evidence or do you have any prior knowledge that there have been previously any leaks, spills, or staining by substances other than water, or foul odors, associated with any flooring drains, walls, ceilings or exposed grounds on the <i>property</i> ?	Yes (No) Unk	Yes No Unk	Yes (No)
	13a. If the <i>property</i> is served by a private well or non-public water system, is there evidence or do you have prior knowledge that contaminants have been identified in the well or system that exceed guidelines applicable to the water system?	Yes No Unk	Yes No Unk	Yes (No
	13b. If the <i>property</i> is served by a private well or non-public water system, is there evidence or do you have prior knowledge that the well has been designated as contaminated by any government environmental/health agency?	Yes (No) Unk	Yes No Unk	Yes (No)
	14. Does the <i>owner</i> or <i>occupant</i> of the <i>property</i> have any knowledge of <i>environmental</i> liens or governmental notification relating to past or recurrent violations of environmental laws with respect to the <i>property</i> or any facility located on the <i>property</i> ?	Yes No Unk	Yes No Unk	v
	15a. Has the owner or occupant of the <i>property</i> been informed of the past existence of hazardous substances or petroleum products with respect to the property or any facility located on the <i>property</i> ?	Yes No Unk	Yes No Unk	
	15b. Has the owner or occupant of the property been informed of the current existence of hazardous substances or petroleum products with respect to the property or any facility located on the property?	Yes No Unk	Yes No Unk	
	15c. Has the owner or occupant of the property been informed of the past existence of environmental violations with respect to the property or any facility located on the property?	Yes No Unk	Yes No Unk	
	15d. Has the owner or occupant of the <i>property</i> been informed of the current existence of environmental violations with respect to the <i>property</i> or any facility located on the <i>property</i> ?	Yes No Unk	Yes No Unk	
	16. Does the owner or occupant of the property have any knowledge of any environmental site assessment of the property or facility that indicated the presence of hazardous substances or petroleum products on, or contamination of, the property or recommended further assessment of the property?	Yes No Unk	Yes No Unk	
	Converent © 2000 ASTM INTERNATIONAL Wast Constanting DA			

Copyright © 2000 ASTM INTERNATIONAL, West Conshohocken, PA
This document is an excerpt of E 1528-00: Standard Practice for Environmental Site Assessments: Transaction Sercen Process, which is under the jurisdiction of ASTM Committee E50 on Environmental Assessment and is the direct responsibility of Subcommittee E50.02 on Commercial Real Estate Transactions. This questionnaire represents only Sections 5 and 6 of Practice E 1528-00 and should not be construed as being the complete standard. It is necessary to refer to the full standard prior to using this questionnaire. For the complete standard, or to order additional copies of this questionnaire, contact ASTM Customer Service at (610) 832-9585

	Question	Owner	Occupan (if applic		Observed During Site Visit	
bend relea	ooes the owner or occupant of the property know of any past, threatened, or ing lawsuits or administrative proceedings concerning a release or threatened se of any hazardous substance or petroleum products involving the property by owner or occupant of the property?	Yes No Unk	Yes No) Ünk		
18a, storn	Does the <i>property</i> discharge waste water (not including sanitary waste or a water) onto or adjacent to the <i>property</i> and/or into a storm water system?	Yes (No) Unk	Yes No	Unk	Yes (No)	
-18b. storn	Does the <i>property</i> discharge waste water (not including sanitary waste or water) onto or adjacent to the <i>property</i> and/or into a sanitary sewer system?	Yes No Unk	Yes No	Unk	Yes (No)	
haza autor	old you observe evidence or do you have any prior knowledge that any rdous substances or petroleum products, unidentified waste materials, tires, notive or industrial batteries, or any other waste materials have been dumped e grade, buried and/or burned on the property?	Yes No Unk	Yes No	Unk	Yes (No)	
20. 1.	s there a transformer, capacitor, or any hydraulic equipment for which there ny records indicating the presence of PCBs?	Yes No Unk	Yes No	Unk	Yes (No)	
	Government Records/His (See guide, Section 10 of A	storical Sources Inqui STM Practice E 1528-0	y 00)			
21.	Do any of the following Federal government record systems list	t the				
	property or any property within the search distance noted below	v: proximate Minimum Sea miles (kilomete:		,		
	Federal NPL site list	1.0 (1.6)	2)	V.		
	Federal CERCLIS list	0.5 (0.8)		Ye		
	Federal CERCLIS NFRAP site list	property and adjoining	ncoperfiee			
	Federal RCRA CORRACTS facilities list	1.0 (1.6)	proportios	Ye		
	Federal RCRA non-CORRACTS TSD facilities list	0.5 (0.8)	,	Ye Ye		
	E-1-1 DOD (property and adjoining	aronerlier			
	Federal ERNS list	property only		Yes No		
22.	Do any of the following state record systems list the property or any property within the search distance noted below:			1.6	s (No)	
		proximate Minimum Sea	rch Distance	,		
		miles (kilometer				
	State lists of hazardous waste sites					
	identified for Investigation or remediation:					
	State — Equivalent NPL	1.0 (1.6)		Ye	s) No	
	State — Equivalent CERCLIS	0.5 (0.8)		Ye	—	
	State landfill and/or solid waste disposal site lists	0.5 (0.8)		Ye		
	State leaking UST lists	0.5 (0.8)		Ye	s No	
	State registered UST lists	property and adjoining p	properties	Ye.		
23.	Based upon a review of <i>fire insurance maps</i> 10.3.1.3 or consultate serving the <i>property</i> , all as specified in the guide, are any building property or on an adjoining property identified as having been a likely to lead to contamination of the property?	ation with the local fire	lepartment	(Yes	s) No	
					y ±10	

The Owner questionnaire was completed by:	The Government Records and Historical Sources Inquiry
Name & Scengiter Poetel	questionnaire was completed by:
Title President	Name
Firm Moto. & city motel	Title
Address 17355 Raupp pd	Title Same in site Visi
melvindelle, MP 48122	Address =
Phone number 3/3-382-9200	
	Phone number
	Date
Preparer's relationship to site	Preparer's relationship to site
Preparer's relationship to user (for example, principal, employee, agent, consultant)	
agent, consultant) 78 (5° FCC)	Preparer's relationship to user (for example, principal, employ agent, consultant)
The Occupant questionnaire was completed by:	
Name	User's relationship to the site (for example, owner, prospe-
	tive purchaser, lender, etc.)
Title	If the preparer(s) is different from the user, complete the
Firm	following:
Address	Name of User
Dhana numbar	User's address
Phone number	
Date	User's phone number
Preparer's relationship to site	
Preparer's relationship to user (for example, principal, employee, agent, consultant)	Copies of the completed questionnaires have been filed at:
agent, consultant)	
The Site Visit questionnaire was completed by:	
	Copies of the completed questionnaires have been mailed of
hi Wasan I I	delivered to:
Firm Northern Chrismental	
Address 64+ Academy Drive	
Northbrook, IL 60062	
Phone number 847 - 562 - 857 3	Prenarer convergence that the there are it is
Date 8/23/04	Preparer represents that to the best of the preparer's knowledg the above statements and facts are true and correct and to the
Preparer's relationship to site Cun Sun / funf	best of the preparer's actual knowledge no material facts have
	been suppressed or misstated.
Preparer's relationship to user (for example, principal, employee, / agent, consultant)	Signature S. P. Patet.
-b-nd sometimes	Date 8 (23)04
	Signature Sam To persolugi
	Date 8/7 3/04
	(=) (1 ₀ (2 (4 (4 (4 (4 (4 (4 (4 (4 (4 (4 (4 (4 (4
	Signature
Copyright © 2000 ASTM INTERNATIONAL, West Conshohocken, PA	Signature

To order additional copies of this questionnaire, contact ASTM International, Customer Service.

phone: (610) 832-9585 fax: (610) 832-9555 e-mail: service@astm.org



100 Barr Harbor Drive PO Box C700 West Conshohocken, PA 19428-2959

ATTACHMENT B

EDR TRANSACTION SCREEN MAP REPORT AND SANBORN MAPS



The EDR Transaction ScreenTM **Map Report**

Motor City Motel 17355 Raupp Road Melvindale, MI 48122

Inquiry Number: 01256609.1r

August 25, 2004

The Standard in **Environmental Risk Management Information**

440 Wheelers Farms Road Milford, Connecticut 06460

Nationwide Customer Service

Telephone: 1-800-352-0050 Fax:

1-800-231-6802

Internet:

www.edrnet.com

TABLE OF CONTENTS

SECTION	PAGE
Executive Summary	ES1
Overview Map	2
Map Summary - All Sites	. 3
Map Findings	. 5
Orphan Summary	45
APPENDICES	
Government Records Searched / Data Currency Tracking Addendum	GR-1

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This report contains information obtained from a variety of public and other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL EDR BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. It can not be concluded from this report that coverage information for the target and surrounding properties does not exist from other sources. Any analyses, estimates, ratings or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Any liability on the part of EDR is strictly limited to a refund of the amount paid for this report.

Copyright 2004 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

The EDR-Transaction Screen Map Report is a screening tool which maps sites with potential liability or existing environmental liabilities. Specified government databases are searched in accordance with ASTM Standard E 1528-00.

The ASTM E 1528-00 Transaction Screen property due diligence standard consists of four major components: a government records check, an historical inquiry, an owner/occupant questionnaire, and a site survey. This report contains the results of the government records search on the target property and surrounding area in accordance with the government records search requirements of the ASTM E 1528-00 standard.

The results of the government records search in accordance with QUESTIONS 21 and 22 (page 15, E 1528-00) of the standard indicated the following:

QUESTION 21

Do any of the following **Federal** government record systems list the property or any property within the circumference of the area noted below:

circumierence of the area noted below.					
National Priorities List (NPL) CERCLIS List CERCLIS NFRAP List RCRA-CORRACTS Facilities RCRA-TSD Non-CORRACTS Facilities RCRA LQG Facilities RCRA SQG Facilities ERNS		on the property on the property			Within 1 Mile Within 1/2 Mile Within 1/4 Mile Within 1 Mile Within 1/2 Mile Within 1/4 Mile Within 1/4 Mile
QUESTION 22 Do any of the following state government record system circumference of the area noted below:	is list	the property or an	y prop	perty	within the
State equivalent to NPL State equivalent to CERCLIS Solid Waste/Landfill Facilities (SWF/LS) Leaking Underground Storage Tank List (LUST) Underground Storage Tank List (UST)		on the property on the property on the property on the property on the property			Within 1 Mile Within 1/2 Mile Within 1/2 Mile Within 1/2 Mile Within 1/4 Mile

In accordance with Section 5.6 (page 10, E 1528) if the answer is (yes) or unknown, then the user will have to decide what further action, if any, is appropriate. Answers should be evaluated in light of the other information obtained in the transaction screen process. If the user decides no further inquiry is warranted, the rationale must be documented. If the user decides that further inquiry is warranted, it may be necessary to contact an environmental professional.


Additional Research - ASTM Supplemental Government Databases

To provide additional information which may assist in the assessment of other components of the ASTM E 1528-00 Transaction Screen, EDR also searches government databases *not* included in Questions 21 and 22 of ASTM E 1528-00. This information may be useful in completing the owner/occupant questionnaire.

The results of the search of these additional government records indicated affirmative (yes) responses on the target property for the following government databases:

No affirmative responses found in the non-ASTM E 1528-00 government databases.

OVERVIEW MAP - 01256609.1r - Northern Environmental



TARGET PROPERTY: ADDRESS: CITY/STATE/ZIP:

LAT/LONG:

Motor City Motel 17355 Raupp Road Melvindale MI 48122 42.2842 / 83.1689

CUSTOMER: CONTACT: INQUIRY #:

DATE:

Northern Environmental Sean McCuddy

01256609.1r

August 25, 2004 12:33 pm

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
FEDERAL ASTM STANDARD)							
NPL Proposed NPL CERCLIS CERC-NFRAP CORRACTS RCRIS-TSD RCRIS Lg. Quan. Gen. RCRIS Sm. Quan. Gen. ERNS STATE ASTM STANDARD		1.000 1.000 0.500 0.250 1.000 0.500 0.250 0.250 TP	0 0 0 0 0 0 0 0 2 NR	0 0 0 0 0 0 0 3 NR	0 0 1 NR 0 0 NR NR NR	0 0 NR NR 1 NR NR NR NR	NR NR NR NR NR NR NR	0 0 1 0 1 0 0 5 0
		1.000	0	0	á	4	ND	F
State Haz. Waste State Landfill LUST UST BEA HIST LF INDIAN UST		1.000 0.500 0.500 0.250 TP 0.500 0.250	0 0 1 NR 0	0 0 2 1 NR 0 0	1 0 11 NR NR 0 NR	4 NR NR NR NR NR	NR NR NR NR NR NR	5 0 13 2 0 0
FEDERAL ASTM SUPPLEME	NTAL							
Delisted NPL FINDS HMIRS MLTS MINES NPL Liens PADS UMTRA FUDS INDIAN RESERV US BROWNFIELDS DOD RAATS TRIS TSCA SSTS FTTS		1.000 TP TP TP TP TP 0.500 1.000 1.000 0.500 1.000 TP TP TP	ORRIVER NEW OOOORRENER NEW OOOOORRENER NEW OOOOORRENER NEW OOOORRENER NEW	0 R R R R R R O O O O O R R R R R R R R	0 R R R R R R O O O O O R R R R R R R R	0 R R R R R R R O O R O R R R R R R R R	NR	
STATE OR LOCAL ASTM SU	IPPLEMENTA	<u> </u>						
AST DEL SHWS PEAS DRYCLEANERS		TP 1.000 TP 0.250	NR 0 NR 0	NR 0 NR 0	NR 0 NR NR	NR 1 NR NR	NR NR NR NR	0 1 0 0

MAP FINDINGS SUMMARY

Database	Target Property	Search Distance (Miles)	< 1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	> 1	Total Plotted
EDR PROPRIETARY HISTO	RICAL DATAB	ASES						
Coal Gas		1.000	0	0	0	1	NR	1
BROWNFIELDS DATABASE	ES							
US BROWNFIELDS		0.500	0	0	0	NR	NR	0

NOTES:

TP = Target Property

NR = Not Requested at this Search Distance

Sites may be listed in more than one database

Map ID Direction Distance Distance (ft.) Elevation

Site

Database(s)

UST

EDR ID Number EPA ID Number

sw < 1/8 136 ft. OAKWOOD MINIMART INC 2661 OAKWOOD BLVD MELVINDALE, MI 48122

U003325671 N/A

Relative: Equal

UST:

Facility ID:

00035570

Tank ID:

Oakwood Minimart Inc

Actual: 587 ft.

Owner: Owner Country: USA Not reported Owner Contact:

2661 Oakwood Blvd Owner Address: Melvindale, MI 48122 (313) 386-2100

Owner Phone: Product:

Gasoline 10000

Capacity: Tank Status:

Currently In Use Not reported

Remove Date: Cathodically Protected Steel Constr Material: Piping Material: Fiberglass reinforced plastic

Piping Type: Contact:

Pressure YOSSEF CHARARA

(517) 388-2100 Contact Phone: Impressed Device No Oct 1 1991

Install Date:

Release Detection:

Tank:

Automatic Tank Gauging, Inventory Control

Pipe:

Automatic Line Leak Detectors

Facility ID:

00035570

Tank ID:

Owner:

Oakwood Minimart Inc

Owner Country: Owner Contact:

USA Not reported

2

2661 Oakwood Blvd Owner Address:

Melvindale, MI 48122

Owner Phone:

(313) 386-2100

Product:

Diesel

Capacity:

10000 Currently In Use

Tank Status: Remove Date:

Not reported

Constr Material:

Cathodically Protected Steel Fiberglass reinforced plastic

Piping Material: Piping Type:

Pressure

Contact:

YOSSEF CHARARA (517) 388-2100

Contact Phone: Impressed Device No

Install Date:

Oct 1 1991

Release Detection:

Tank: Pipe:

Automatic Tank Gauging, Inventory Control

Automatic Line Leak Detectors

Facility ID:

00035570

Tank ID:

Oakwood Minimart Inc Owner: Owner Country:

USA

Owner Contact:

Not reported

Owner Address:

2661 Oakwood Blvd

Melvindale, MI 48122

Map ID Direction Distance Distance (ft.) Elevation Site

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

U003325671

OAKWOOD MINIMART INC (Continued)

Owner Phone:

(313) 386-2100

Product:

Gasoline 6000

Capacity: Tank Status:

Currently In Use

Remove Date:

Not reported

Constr Material:

Cathodically Protected Steel Fiberglass reinforced plastic

Piping Material: Piping Type:

Pressure

Contact:

YOSSEF CHARARA

Contact Phone:

(517) 388-2100

Impressed DeviceNo

Install Date:

Oct 1 1991

Release Detection:

Tank:

Automatic Tank Gauging, Inventory Control

Pipe:

Automatic Line Leak Detectors

Facility ID: Tank ID:

00035570

Oakwood Minimart Inc

Owner: Owner Country:

USA

Owner Contact:

Not reported 2661 Oakwood Blvd

Owner Address:

Melvindale, MI 48122

Owner Phone:

(313) 386-2100

Product:

Gasoline

Capacity:

6000 Currently In Use

Tank Status: Remove Date:

Not reported

Constr Material:

Cathodically Protected Steel

Piping Material:

Fiberglass reinforced plastic

Piping Type:

Pressure

Contact:

YOSSEF CHARARA (517) 388-2100

Contact Phone:

Impressed Device No

Install Date:

Oct 1 1991

Release Detection:

Tank:

Automatic Tank Gauging, Inventory Control

Pipe:

Automatic Line Leak Detectors

Facility ID:

00035570

Tank ID: Owner:

Oakwood Minimart Inc

Owner Country:

USA

Owner Contact:

Not reported

Owner Address:

2661 Oakwood Blvd Melvindale, MI 48122

(313) 386-2100

Owner Phone: Product:

Capacity:

Kerosene

6000

Tank Status:

Currently In Use Not reported

Remove Date:

Cathodically Protected Steel

Constr Material: Piping Material:

Fiberglass reinforced plastic

Piping Type:

Pressure

Contact:

YOSSEF CHARARA

Contact Phone: (517) 388-2100

Impressed DeviceNo

Map ID Direction Distance Distance (ft.)

Site Elevation

Database(s)

RCRIS-SQG

RCRIS-SQG

FINDS

EDR ID Number EPA ID Number

U003325671

1000465978

MID985607043

OAKWOOD MINIMART INC (Continued)

Oct 1 1991 Install Date:

Release Detection:

Tank:

Automatic Tank Gauging, Inventory Control

Pipe:

Automatic Line Leak Detectors

D AND K STARTER AND ALTERNATOR 2 2750 OAKWOOD WSW

< 1/8

MELVINDALE, MI 48122

307 ft.

Relative: Higher

RCRIS:

Owner: EPA ID: **GRASZAK DANIEL** MID985607043

Actual: 588 ft.

Contact:

DANIEL GRASZAK

(313) 388-4112

Classification:

Small Quantity Generator

TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Resource Conservation and Recovery Act Information system

SSW

EXPRESS AUTO

17420 DIX

< 1/8 372 ft. MELVINDALE, MI 48122

Relative: Equal

RCRIS: Owner:

EXPRESS AUTO

EPA ID:

MIK666324868

Actual: 587 ft.

Contact:

AHMAD MANSOUR

(313) 388-9995

Classification:

Small Quantity Generator

TSDF Activities: Not reported

Violation Status: No violations found

East

B AND K COLLISION INC 2521 OAKWOOD BLVD MELVINDALE, MI 48122

1/8-1/4

670 ft.

Relative: Equal

Actual: 587 ft.

RCRIS-SQG 1000309445 **FINDS**

MID052038395

1007099423

MIK666324868

Map ID Direction Distance Distance (ft.) Elevation Site MAP FINDINGS

Database(s)

RCRIS-SQG

FINDS

RCRIS-SQG 1000866441

FINDS MID985665983

EDR ID Number EPA ID Number

B AND K COLLISION INC (Continued)

1000309445

1000979950

MI0000996884

RCRIS:

Owner:

MICHAEL BRENNAN

EPA ID:

MID052038395

Contact:

MICHAEL BRENNAN

(313) 386-2580

Classification:

Small Quantity Generator

TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Resource Conservation and Recovery Act Information system

5 SSE KAIER SCHOOL

17525 DORA ST

1/8-1/4 743 ft.

MELVINDALE, MI 48122

Relative: Equal

RCRIS:

Owner:

ECONOMIC DEVEL CORP

EPA ID:

MI0000996884

Actual: 587 ft.

Contact:

MIKE INGELS

(313) 455-9070

Classification:

Small Quantity Generator

TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Resource Conservation and Recovery Act Information system

A6

VALVE RECONDITIONING

ESE

17180 FRANCIS

1/8-1/4 1109 ft. MELVINDALE, MI 48122

Relative:

Site 1 of 2 in cluster A

Lower

RCRIS:

VALVE RECONDITIONING SVC

Actual: 586 ft.

Owner: EPA ID:

MID985665983

Contact:

MICHAEL CARBONARD (313) 928-5980

Classification:

Small Quantity Generator

TSDF Activities: Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

VALVE RECONDITIONING (Continued)

Violation Status: No violations found

1000866441

FINDS:

Other Pertinent Environmental Activity Identified at Site: Resource Conservation and Recovery Act Information system

A7 ESE 1/8-1/4 1124 ft. DETROIT BUMPER MART 17162 FRANCIS ST MELVINDALE, MI 48122

LUST U000267356 UST N/A

Relative: Lower

Actual: 586 ft.

Site 2 of 2 in cluster A

LUST:

Facility ID: 00019991 Release Number: Closed

Sep 5 1996

Release Date: District:

SE Michigan District Office

Closed Date:

Jan 14 1997

Owner Contact: Not reported Owner Name: Supreme Bumpers Inc

Owner Address: 420 S 15th St

Toledo, OH 43602

Country:

USA

Owner Phone: Contact:

(419) 241-5261 ROBERT J MURRAY (248) 546-9910

Facility Phone: Leak Number:

C-0572-96

UST:

Facility 1D:

00019991

USA

Tank ID: Owner:

Supreme Bumpers Inc

Owner Country: Owner Contact:

Not reported Owner Address: 420 S 15th St

Owner Phone:

Toledo, OH 43602 (419) 241-5261

Product: Capacity: Gasoline 2000

Tank Status:

Removed from Ground

Remove Date:

Aug 8 1996

Constr Material:

Fiberglass Reinforced plastic, Lined Interier

Piping Material:

Unknown

Piping Type:

Not reported

Contact: Contact Phone: ROBERT J MURRAY (248) 546-9910

Impressed Device No

Install Date:

Jun 20 1978 Release Detection:

Tank: Pipe:

Not reported Not reported

Map ID Direction Distance Distance (ft.) Elevation

Database(s)

LUST

UST

U003325692

N/A

EDR ID Number EPA ID Number

LUST S102852212

N/A

8 East SALEM MACHINE CO.-SAC PROPERTIES

17100 FRANCIS ST

1/8-1/4

MELVINDALE, MI 48122

1246 ft.

586 ft.

Relative: Lower

LUST:

Facility ID:

50000938 Release Number: Closed

Actual:

Oct 1 1991 Release Date:

District:

SE Michigan District Office Nov 12 1991

Closed Date: Owner Contact: Not reported

Nrt Owner

Owner Name: Owner Address: Unknown Unknown, MI 99999

USA

Country:

Owner Phone:

Not reported

C-2001-91

Contact: Facility Phone: CORBERTT CRIDER (313) 328-3234

Leak Number:

J & J BUILDING CO 17730 DORA ST

South 1/4-1/2

MELVINDALE, MI 48122

1502 ft.

Relative: Higher

LUST:

Facility ID:

00035624 Release Number: Open

Actual: 588 ft.

Jul 13 1999 Release Date:

District:

SE Michigan District Office Not reported Closed Date:

Owner Contact: Not reported Owner Name:

J & J Bldg Co Owner Address: 17730 Dora St

Melvindale, MI 48122

USA

Country: Owner Phone: Contact:

(734) 782-1111 JOE PUTZ

Facility Phone:

(734) 782-1111

Leak Number:

C-0678-99

UST:

Facility ID:

00035624

J & J Bldg Co

Tank ID:

Owner:

Owner Country: USA

Owner Contact:

Not reported

Owner Address:

17730 Dora St Melvindale, MI 48122

Owner Phone:

(734) 782-1111

Product:

WATER

Capacity:

500

Tank Status:

Removed from Ground

Remove Date:

Oct 25 1996 Asphalt Coated or Bare Steel

Constr Material: Piping Material:

Bare Steel

Piping Type:

Not reported

JOE PUTZ

Contact: Contact Phone:

(734) 782-1111

Impressed DeviceNo

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

U003325692

J & J BUILDING CO (Continued)

Install Date: Release Detection:

Not reported

Tank:

Not reported

Pipe:

Not reported

Facility ID: Tank ID:

00035624

Owner:

J & J Bldg Co USA

Owner Country: Owner Contact:

Not reported 17730 Dora St

Owner Address: Owner Phone:

Melvindale, MI 48122

(734) 782-1111

Product:

WATER

Capacity:

500

Tank Status:

Removed from Ground

Remove Date: Oct 25 1996

Asphalt Coated or Bare Steel Constr Material:

Piping Material: Piping Type:

Bare Steel Not reported

JOE PUTZ

Contact: Contact Phone:

(734) 782-1111

Impressed DeviceNo

Install Date:

Not reported

Release Detection:

Tank: Pipe:

Not reported

Not reported

Facility ID: Tank ID:

00035624 3

J & J Bldg Co

Owner:

Owner Country: USA

Owner Contact:

Not reported 17730 Dora St

Owner Address:

Melvindale, MI 48122

Owner Phone:

(734) 782-1111

Product:

WATER

Capacity: Tank Status: 500

Remove Date:

Removed from Ground Oct 25 1996

Constr Material:

Asphalt Coated or Bare Steel

Piping Material:

Bare Steel

Piping Type:

Not reported JOE PUTZ

Contact:

Contact Phone:

(734) 782-1111

Impressed Device No

Install Date:

Not reported

Release Detection:

Not reported

Tank: Pipe:

Not reported

Map ID Direction Distance Distance (ft.) Elevation

Database(s)

RCRIS-SQG

FINDS

LUST UST EDR ID Number EPA ID Number

1001493328 MIR000041673

10 ENE WORLD CLASS AUTO WASH

1/4-1/2

2311 S SCHAFER MELVINDALE, MI 48122

1543 ft.

Relative:

RCRIS:

Owner:

WORLD CLASS AUTO WASH

EPA ID:

MIR000041673

Actual: 585 ft.

Lower

Contact:

KAL RABAN

(619) 660-6144

Classification:

Small Quantity Generator

TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Resource Conservation and Recovery Act Information system

LUST:

Facility ID:

00040074

Release Number: Closed

Release Date:

Mar 8 1999

District:

SE Michigan District Office

Closed Date:

Dec 7 2000 Owner Contact: Not reported

Owner Name:

World Class Autowash

Owner Address:

2311 Schaefer Rd

Melvindale, MI 48122

Country:

USA

Owner Phone:

(313) 386-4730

Contact: Facility Phone: KAL RABAN (313) 386-4730

Leak Number:

C-0264-99

UST:

Facility ID:

00040074

USA

Tank ID:

Owner:

World Class Autowash

Owner Country:

Owner Contact:

Not reported

Owner Address:

2311 Schaefer Rd Melvindale, MI 48122

Owner Phone:

Product:

(313) 386-4730 Used Oil

Capacity:

500

Tank Status:

Removed from Ground

Remove Date: Constr Material: Mar 17 1999

Piping Material:

Asphalt Coated or Bare Steel Unknown

Piping Type:

Not reported

Contact:

KAL RABAN (313) 386-4730

Contact Phone: Impressed DeviceNo

Install Date:

Not reported

Release Detection:

Tank:

Pipe:

Not reported Not reported

Map ID Direction Distance Distance (ft.) Elevation NORFOLK SOUTHERN CORP FORB POOL 11 17801 DIX RD SSW 1/4-1/2 MELVINDALE, MI 48122 1562 ft. LUST: Relative: Facility ID: 00011817 Higher Release Number: Closed Actual: Release Date: Mar 1 1991 591 ft. District: Closed Date: Oct 25 1996 Owner Contact: Not reported Owner Name : Norfolk Southern Corp Owner Address: 8 N JEFFERSON MELVINDALE, MI 48122 USA Country: Owner Phone: (734) 246-1995 R.M. DIXON Contact: Facility Phone: (313) 928-6950 Leak Number: C-0368-91 UST: Facility ID: 00011817 Tank ID: Owner: Norfolk Southern Corp Owner Country: USA Owner Contact: Not reported Owner Address; 8 N JEFFERSON MELVINDALE, MI 48122 Owner Phone: (734) 246-1995 Product: Kerosene Capacity: 8000 Tank Status: Removed from Ground Remove Date: Oct 1 1990 Constr Material: Unknown Piping Material: Unknown Piping Type: Not reported R.M. DIXON Contact: (313) 928-6950 Contact Phone: Impressed Device No Install Date: May 8 1951 Release Detection: Tank: Not reported

Database(s)

EDR ID Number EPA ID Number

LUST U000267404 N/A

UST

SE Michigan District Office

Pipe:

Not reported

Facility ID: Tank ID:

Owner:

00011817

Norfolk Southern Corp

Owner Country: USA

Owner Contact:

Not reported 8 N JEFFERSON

Owner Address:

Owner Phone:

MELVINDALE, MI 48122 (734) 246-1995

Product:

Gasoline

Capacity:

5000

Tank Status:

Removed from Ground

Remove Date:

Aug 1 1990

Constr Material:

Unknown

Piping Material:

Unknown

Piping Type:

Not reported

Map ID Direction Distance Distance (ft.)

Elevation

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

U000267404

LUST U000267935

N/A

UST

NORFOLK SOUTHERN CORP FORB POOL (Continued)

Contact: Contact Phone:

R.M. DIXON (313) 928-6950

Impressed Device:No

May 8 1951 Install Date:

Release Detection:

Tank:

Not reported

Pipe:

Not reported

12 NE SCHAEFER SERVICE 2625 SCHAEFER RD MELVINDALE, MI 48122

1/4-1/2

1604 ft.

LUST:

Relative: Facility ID: Lower

00034155

Release Number: Open

Aug 1 1995

Actual: 585 ft.

Release Date:

SE Michigan District Office

District: Closed Date:

Not reported

Owner Contact:

Not reported Schaefer Serv Sta

Owner Name:

Owner Address: 2625 Schaefer Rd

Melvindale, MI 48122

Country:

USA

Owner Phone:

(313) 382-2044

Contact:

MUSTAPHA AKBLAR

Facility Phone:

(313) 382-2044

Leak Number:

C-0610-95

Facility ID:

00034155 Release Number: Open

Release Date:

Aug 20 1999

District:

SE Michigan District Office

Closed Date:

Not reported

Owner Contact: Not reported

Owner Name:

Schaefer Serv Sta

Owner Address: 2625 Schaefer Rd

Melvindale, MI 48122

Country:

Owner Phone: Contact:

(313) 382-2044

Facility Phone:

MUSTAPHA AKBLAR (313) 382-2044

Leak Number:

C-0869-99

UST:

Facility ID: 00034155

Tank ID:

Owner:

Schaefer Serv Sta

Owner Country:

USA Not reported

Owner Contact:

2625 Schaefer Rd

Owner Address:

Melvindale, MI 48122

(313) 382-2044

Owner Phone:

Product:

Diesel

Capacity:

12000

Tank Status:

Removed from Ground Aug 1 1999

Remove Date:

Asphalt Coated or Bare Steel

Constr Material: Piping Material:

Galvanized Steel

Map 1D Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number **EPA ID Number**

U000267935

SCHAEFER SERVICE (Continued)

Piping Type:

Not reported

Contact:

MUSTAPHA AKBLAR

(313) 382-2044 Contact Phone:

Impressed DeviceNo

Install Date: Jan 1 1986

Release Detection:

Tank:

Groundwater Monitoring

Pipe:

Not reported

Facility ID:

00034155

Tank ID: Owner:

Schaefer Serv Sta

Owner Country:

USA

Owner Contact:

Not reported

Owner Address:

2625 Schaefer Rd

Melvindale, MI 48122

(313) 382-2044

Owner Phone: Product:

Gasoline

Capacity:

6000

Tank Status:

Remove Date:

Removed from Ground

Constr Material:

Aug 1 1999

Piping Material:

Asphalt Coated or Bare Steel

Piping Type:

Galvanized Steel Not reported

MUSTAPHA AKBLAR

Contact: Contact Phone:

(313) 382-2044

Impressed Device No

Install Date:

Not reported

Release Detection: Tank:

Pipe:

Groundwater Monitoring

Not reported

Facility ID:

00034155

Tank ID:

Owner:

Schaefer Serv Sta

Owner Country:

USA Not reported

Owner Contact:

2625 Schaefer Rd

Owner Address:

Melvindale, MI 48122

Owner Phone:

(313) 382-2044

Product:

Gasoline

Capacity:

8000

Tank Status:

Removed from Ground

Remove Date:

Aug 1 1999

Constr Material: Piping Material:

Asphalt Coated or Bare Steel

Galvanized Steel

Piping Type:

Not reported

Contact:

MUSTAPHA AKBLAR

Contact Phone:

(313) 382-2044

Impressed Device No Install Date: Not reported

Release Detection:

Tank:

Groundwater Monitoring

Pipe:

Not reported

Facility ID:

Tank ID:

00034155

Map ID Direction Distance Distance (ft.) Elevation

Database(s)

EDR ID Number EPA ID Number

U000267935

SCHAEFER SERVICE (Continued)

Owner:

Schaefer Serv Sta

Owner Country: USA

Not reported Owner Contact: 2625 Schaefer Rd Owner Address:

Melvindale, MI 48122

Owner Phone:

(313) 382-2044

Product:

Kerosene

Capacity:

4000

Tank Status:

Removed from Ground

Remove Date: Constr Material:

Aug 1 1999 Asphalt Coated or Bare Steel

Piping Material:

Galvanized Steel

Piping Type: Not reported MUSTAPHA AKBLAR

Contact: Contact Phone:

(313) 382-2044

Impressed DeviceNo

Install Date:

Not reported

Release Detection:

Tank:

Groundwater Monitoring

Pipe:

Not reported

Facility ID:

00034155

Tank ID:

Schaefer Serv Sta

Owner: Owner Country:

USA

Not reported Owner Contact:

2625 Schaefer Rd Owner Address:

Melvindale, MI 48122

Owner Phone:

(313) 382-2044

Product:

Gasoline 6000

Capacity: Tank Status:

Removed from Ground

Remove Date: Constr Material:

Aug 1 1999 Asphalt Coated or Bare Steel

Piping Material:

Galvanized Steel Not reported

Piping Type:

MUSTAPHA AKBLAR

Contact: Contact Phone:

(313) 382-2044

Impressed DeviceNo

Install Date:

Jan 1 1989

Release Detection:

Tank:

Groundwater Monitoring

Pipe:

Not reported

Facility ID:

00034155

Tank ID:

Owner:

Schaefer Serv Sta

Owner Country:

USA Not reported

Owner Contact:

2625 Schaefer Rd

Owner Address:

Melvindale, MI 48122

Owner Phone:

(313) 382-2044

Product:

Gasoline

Capacity:

12000

Tank Status:

Currently In Use

Remove Date:

Not reported

Constr Material: Composite(Steel w/Fiberglass), Double Walled

Map ID Direction Distance Distance (ft.) Elevation

Database(s)

EDR ID Number **EPA ID Number**

U000267935

SCHAEFER SERVICE (Continued)

Piping Material:

Double Walled, Fiberglass reinforced plastic

Piping Type:

Pressure

Contact:

MUSTAPHA AKBLAR

Contact Phone:

(313) 382-2044

Impressed DeviceNo Sep 1 1999

Install Date:

Release Detection:

Tank:

Automatic Tank Gauging, Inventory Control

Pipe: Automatic Line Leak Detectors

Facility ID:

00034155

Tank ID:

Owner:

Schaefer Serv Sta

Owner Country:

USA

Owner Contact:

Not reported

Owner Address:

2625 Schaefer Rd

Melvindale, MI 48122

Owner Phone:

(313) 382-2044

Product:

Gasoline

Capacity:

8000 Currently In Use

Tank Status:

Not reported

Remove Date:

Composite(Steel w/Fiberglass), Double Walled

Constr Material: Piping Material:

Double Walled, Fiberglass reinforced plastic

Piping Type:

Pressure

Contact:

MUSTAPHA AKBLAR

Contact Phone: (313) 382-2044

Impressed DeviceNo

Install Date: Sep 1 1999

Release Detection:

Tank:

Automatic Tank Gauging, Inventory Control

Pipe:

Automatic Line Leak Detectors

Facility ID: Tank ID:

00034155

Owner:

Schaefer Serv Sta

Owner Country:

USA Owner Contact:

Owner Address:

Not reported 2625 Schaefer Rd

Melvindale, MI 48122

Owner Phone:

(313) 382-2044

Product:

Gasoline

Capacity:

8000

Tank Status:

Currently In Use

Remove Date:

Not reported

Constr Material:

Composite(Steel w/Fiberglass), Double Walled

Piping Material:

Double Walled, Fiberglass reinforced plastic

Piping Type:

Pressure

Contact:

MUSTAPHA AKBLAR (313) 382-2044

Contact Phone:

Impressed DeviceNo

Sep 1 1999 Install Date: Release Detection:

Tank:

Automatic Tank Gauging, Inventory Control

Pipe:

Automatic Line Leak Detectors

Facility ID:

00034155

Map ID Direction Distance Distance (ft.) Elevation

MAP FINDINGS

Database(s)

LUST

UST

U003325696

N/A

EDR ID Number EPA ID Number

U000267935

SCHAEFER SERVICE (Continued)

Tank ID: Owner:

Schaefer Serv Sta

Owner Country:

USA

Owner Contact: Owner Address: Not reported 2625 Schaefer Rd

Melvindale, MI 48122

Owner Phone: Product:

(313) 382-2044 Kerosene

Capacity:

4000

Currently In Use

Tank Status:

Not reported

Remove Date: Constr Material:

Composite(Steel w/Fiberglass), Double Walled Double Walled, Fiberglass reinforced plastic

Piping Material:

Pressure

Piping Type: Contact:

MUSTAPHA AKBLAR

Contact Phone:

(313) 382-2044

Impressed Device No

Install Date: Sep 1 1999

Release Detection:

Tank:

Automatic Tank Gauging, Inventory Control

Pipe:

Automatic Line Leak Detectors

13 ESE

CAPITOL INVESTMENT PROPERTIES

17065 HESS ST

1/4-1/2 1686 ft. MELVINDALE, MI 48122

Relative: Lower

Actual:

585 ft.

LUST:

Facility ID:

00035653

Release Number: Closed

Release Date:

Oct 9 1998

USA

District:

SE Michigan District Office

Closed Date:

Jan 5 1999

Owner Contact: Not reported

Owner Name:

Capitol Investment Prop 17065 Hess St

Owner Address:

Melvindale, MI 48122

Country:

Owner Phone:

(313) 928-4000

Contact:

MICHAEL A MARTORANO (248) 926-1199

Facility Phone: Leak Number:

C-0939-98

UST:

Facility ID:

00035653

Tank ID: Owner:

Owner Country:

Capitol Investment Prop USA

Owner Contact:

Not reported

Owner Address:

17065 Hess St Melvindale, MI 48122

Owner Phone:

(313) 928-4000

Product:

Diesel

Capacity:

10000

Tank Status:

Removed from Ground

Remove Date: Constr Material: Sep 30 1998

Piping Material:

Asphalt Coated or Bare Steel

Piping Type:

Bare Steel Suction: No Valve At Tank

Map ID Direction Distance Distance (ft.) Elevation

Database(s)

EDR ID Number EPA ID Number

U003325696

CAPITOL INVESTMENT PROPERTIES (Continued)

Contact:

MICHAEL A MARTORANO

Contact Phone:

(248) 926-1199

Impressed Device No

Install Date:

Not reported

Release Detection:

Tank: Pipe:

Not reported Not reported

Facility ID:

00035653

Tank ID:

Owner:

Capitol Investment Prop

Owner Country: USA

Owner Contact:

Not reported Owner Address: 17065 Hess St

Melvindale, MI 48122

Owner Phone: (313) 928-4000

Product:

Diesel

Capacity:

10000

Tank Status:

Removed from Ground

Remove Date:

Sep 30 1998

Constr Material:

Asphalt Coated or Bare Steel

Piping Material:

Bare Steel

Piping Type: Contact:

Suction: No Valve At Tank MICHAEL A MARTORANO

Contact Phone:

(248) 926-1199 Impressed Device No

Install Date:

Not reported

Release Detection:

Tank:

Not reported

Pipe:

Not reported 00035653

Facility ID: Tank ID:

Owner:

Owner Country: USA

Owner Contact:

Not reported 17065 Hess St

Owner Address:

Melvindale, MI 48122

Capitol Investment Prop

Owner Phone: Product:

(313) 928-4000

Gasoline

Capacity:

10000

Tank Status:

Removed from Ground Sep 30 1998

Remove Date:

Asphalt Coated or Bare Steel

Constr Material: Piping Material:

Bare Steel

Piping Type:

Suction: No Valve At Tank MICHAEL A MARTORANO

Contact:

(248) 926-1199

Contact Phone: Impressed DeviceNo

Install Date: Not reported

Release Detection:

Tank:

Not reported

Pipe:

Not reported

Facility ID:

00035653

Tank ID:

Owner:

Capitol Investment Prop

Map ID Direction Distance Distance (ft.)

Site

Elevation

MAP FINDINGS

Database(s)

LUST

UST

U002303666

N/A

EDR ID Number EPA ID Number

U003325696

CAPITOL INVESTMENT PROPERTIES (Continued)

Owner Country: USA

Owner Contact:

Not reported 17065 Hess St

Owner Address:

Melvindale, MI 48122

Owner Phone:

(313) 928-4000 Used Oil

Product:

10000

Capacity: Tank Status:

Removed from Ground

Remove Date:

Dec 18 1992

Constr Material: Unknown

Piping Material:

Bare Steel

Piping Type:

Suction: No Valve At Tank MICHAEL A MARTORANO

Contact:

(248) 926-1199

Contact Phone:

Impressed DeviceNo

Install Date: Not reported Release Detection:

Tank:

Not reported

Pipe:

Not reported

14 North

C J ROGERS INC 2947 GREENFIELD RD

1/4-1/2

MELVINDALE, MI 48122

1723 ft.

Relative: Lower

LUST:

Facility ID:

00006527

Release Number: Closed

Actual: 582 ft.

Release Date:

Oct 5 1993

District:

SE Michigan District Office

Closed Date: Owner Contact: Not reported

Dec 21 1995

Owner Name:

C J Rogers Inc

Owner Address: 2947 Greenfield Rd

Melvindale, MI 48122

Country:

Owner Phone:

USA (312) 407-6448

Contact:

MR LEE KAPLAN

Facility Phone:

(312) 407-6448

Leak Number:

C-1221-93

UST:

00006527

Facility ID: Tank ID:

Owner:

C J Rogers Inc USA

Owner Country:

Not reported

Owner Contact:

2947 Greenfield Rd

Owner Address:

Melvindale, MI 48122

Owner Phone: Product:

(312) 407-6448

Capacity:

Diesel 10000

Tank Status:

Removed from Ground

Dec 22 1993

Remove Date: Constr Material:

Asphalt Coated or Bare Steel

Piping Material:

Galvanized Steel

Piping Type:

Not reported

Contact:

MR LEE KAPLAN

Contact Phone:

(312) 407-6448

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

U002303666

C J ROGERS INC (Continued)

Impressed DeviceNo

Install Date:

Feb 11 1961

Release Detection:

Tank:

Not reported Not reported

Pipe:

Facility ID: Tank ID:

00006527 2

Owner:

C J Rogers Inc

Owner Country:

USA Not reported

Owner Contact:

2947 Greenfield Rd

Owner Address:

Melvindale, MI 48122

Owner Phone:

(312) 407-6448

Product:

Gasoline

Capacity:

10000

Tank Status:

Removed from Ground Dec 22 1993

Remove Date: Constr Material:

Asphalt Coated or Bare Steel

Piping Material:

Galvanized Steel

Piping Type:

Not reported

Contact: MR LEE KAPLAN Contact Phone: (312) 407-6448

Impressed Device No

Install Date:

Feb 11 1961

Release Detection:

Tank:

Not reported

Pipe:

Not reported

15 NNE RIVER ROUGE FILL AREA

SCHAEFER RD E GREENFIELD RD WS N BUTLER

1/4-1/2

MELVINDALE, MI 48122

1789 ft.

Relative: Lower

CERCLIS Classification Data:

Site Incident Categoriylot reported

Non NPL Status: Ownership Status:

Other Cleanup Activity: State-Lead Cleanup Unknown

Actual: 582 ft. CERCLIS Assessment History:

Assessment:

DISCOVERY

UNILATERAL ADMIN ORDER

Assessment:

ADMIN ORDER ON CONSENT

Assessment: Assessment:

PRP REMOVAL

Assessment:

PRELIMINARY ASSESSMENT

Assessment:

SITE INSPECTION

CERCLIS Site Status:

CERCLIS Alias Name(s):

RIVER ROUGE FILL AREA

Other Pertinent Environmental Activity Identified at Site:

Comprehensive Environmental Response, Compensation and Liability Information System

CERCLIS 1000211215

FINDS

Not on the NPL

08/17/1988

05/03/1990

06/06/1990 06/08/1990

08/05/1991

09/30/1992

Federal Facility: Not a Federal Facility

NPL Status:

Completed:

Completed:

Completed:

Completed:

Completed:

Completed:

MID985569144

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

N/A

16 North 1/4-1/2 1911 ft. GREENFIELD DPW YARD 2951 GREENFIELD RD DEARBORN, MI 48120

LUST U000267567 UST

Relative: Lower

LUST:

Facility ID: 00004333 Release Number: Closed

Actual: 580 ft.

Dec 9 1993 Release Date: District:

Closed Date:

SE Michigan District Office Jun 7 1994

Owner Contact: Not reported Owner Name:

City Of Dearborn Owner Address: 2951 Greenfield Rd

Dearborn, MI 48120

Country:

Owner Phone: (313) 943-2952

USA

Contact:

MR RICHARD E ELLIOTT

Facility Phone: (313) 943-2452 Leak Number: C-1534-93

UST:

Facility ID:

00004333

USA

Tank ID: Owner:

City Of Dearborn

Owner Country:

Owner Contact: Not reported

Owner Address:

2951 Greenfield Rd Dearborn, MI 48120

Owner Phone:

(313) 943-2952

Product:

Diesel 10000

Capacity: Tank Status:

Removed from Ground

Remove Date:

Apr 20 1994

Constr Material: Piping Material: Fiberglass Reinforced plastic Galvanized Steel

Piping Type:

Not reported

Contact:

MR RICHARD E ELLIOTT

Contact Phone: (313) 943-2452

Impressed Device No Apr 22 1976

Install Date:

Release Detection:

Tank:

Not reported

Pipe:

Not reported

Facility ID:

00004333

Tank ID:

Owner: City Of Dearborn

Owner Country:

USA Owner Contact:

Owner Address:

Not reported 2951 Greenfield Rd

Dearborn, MI 48120 (313) 943-2952

Owner Phone: Product:

Gasoline

Capacity:

10000

Tank Status:

Remove Date:

Removed from Ground Apr 20 1994

Constr Material:

Fiberglass Reinforced plastic

Piping Material:

Galvanized Steel

Piping Type:

Not reported

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

U000267567

GREENFIELD DPW YARD (Continued)

Contact:

MR RICHARD E ELLIOTT

Contact Phone:

(313) 943-2452

Impressed DeviceNo

Install Date:

Apr 22 1976

Release Detection:

Tank:

Not reported

Pipe:

Not reported

Facility ID:

00004333 3

Tank ID:

Owner:

City Of Dearborn USA

Owner Country:

Not reported

Owner Contact: Owner Address:

2951 Greenfield Rd

Dearborn, MI 48120

Owner Phone:

(313) 943-2952

Product:

Gasoline

Capacity:

10000

Tank Status:

Removed from Ground

Remove Date:

Apr 20 1994

Constr Material:

Asphalt Coated or Bare Steel

Piping Material:

Piping Type:

BLACK STEEL

Not reported

Contact:

MR RICHARD E ELLIOTT (313) 943-2452

Contact Phone:

Impressed DeviceNo Apr 22 1968

Install Date: Release Detection:

Tank:

Not reported

Pipe:

Not reported

Facility ID:

00004333

Tank ID:

City Of Dearborn

Owner:

Owner Country: USA

Not reported Owner Contact: Owner Address: 2951 Greenfield Rd

Dearborn, MI 48120

Owner Phone:

(313) 943-2952

Product:

Diesel

Capacity:

3000

Tank Status:

Removed from Ground

Remove Date:

Apr 20 1994 Constr Material:

Piping Material:

Asphalt Coated or Bare Steel

Piping Type:

BLACK STEEL

Not reported

Contact:

MR RICHARD E ELLIOTT (313) 943-2452

Contact Phone: Impressed DeviceNo

Install Date:

Apr 22 1968

Release Detection:

Tank:

Not reported

Pipe:

Not reported

Facility ID:

Tank ID:

00004333

Owner:

City Of Dearborn

Map ID Direction Distance Distance (ft.) MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

U000267567

GREENFIELD DPW YARD (Continued)

Owner Country: USA

Owner Contact: Not reported

Owner Address:

2951 Greenfield Rd

Dearborn, MI 48120

Owner Phone: Product:

Site

Elevation

(313) 943-2952 Gasoline

Capacity:

15000

Tank Status:

Currently In Use Not reported

Remove Date: Constr Material:

Double Walled, Fiberglass Reinforced plastic

Piping Material:

Double Walled, Fiberglass reinforced plastic

Piping Type:

Pressure

Contact:

MR RICHARD E ELLIOTT

Contact Phone: (313) 943-2452

Impressed DeviceNo

Install Date:

Jan 1 1994

Release Detection:

Tank:

Not reported

Pipe:

Not reported

Facility ID:

00004333

Tank ID:

City Of Dearborn

Owner:

Owner Country:

USA

Owner Contact:

Not reported Owner Address:

2951 Greenfield Rd Dearborn, MI 48120

Owner Phone:

(313) 943-2952

Product:

Diesel 15000

Capacity: Tank Status:

Currently In Use Not reported

Remove Date: Constr Material:

Double Walled, Fiberglass Reinforced plastic

Piping Material:

Double Walled, Fiberglass reinforced plastic

Piping Type:

Pressure

MR RICHARD E ELLIOTT Contact: Contact Phone: (313) 943-2452

Impressed DeviceNo

Jan 1 1994 Install Date:

Release Detection:

Tank: Pipe:

Not reported Not reported

17

NORFOLK SOUTHERN RAILROAD

18100 DIX

SSW 1/4-1/2 DETROIT, MI 99999

2490 ft.

Relative:

LUST:

Facility ID: Higher

50000024

Release Number: Open Release Date:

Actual:

Aug 30 1989

589 ft.

SE Michigan District Office

Closed Date:

District:

Not reported

Owner Contact: Not reported

Owner Name:

Owner Address: Unknown

Nrt Owner

Unknown, MI 99999

Country:

USA

LUST S102851734 N/A

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

SHWS

LUST

UST

EDR ID Number EPA ID Number

S102851734

S103095068

1000314507

N/A

N/A

NORFOLK SOUTHERN RAILROAD (Continued)

Owner Phone:

Not reported

Contact:

Not reported

Facility Phone:

()-

Leak Number: C-0472-89

18 North ROUGE RIVER

SCHAEFER HWY BRIDGE MELVINDALE, MI 48122

1/4-1/2 2507 ft.

Relative:

SHWS:

Lower Actual:

Facility ID:

82000047 Facility Status: Interim Response conducted - No further activities anticipated

Source:

Unknown

580 ft. Pollutant(s):

CN; Pb; PCB's 34

SAM Score:

03/05/2004 SAM Score Date:

Township:

null

Range:

null

Section:

0

Quarter:

null

Quarter/Quarter:

null

19 South **EBONEX CORP**

1/4-1/2

2380 S WABASH ST MELVINDALE, MI 48122

2571 ft.

Relative: Higher

LUST:

Facility ID:

00035097

Release Date:

Release Number: Closed

Actual: 588 ft.

May 23 1991

District: Closed Date: SE Michigan District Office

Owner Contact: Not reported

Nov 6 1991

Michael F. Szczepanik

Owner Name:

Owner Address: 9934 Sterling Ave

Allen Park, MI 48101

Country: Owner Phone:

Contact:

(313) 381-5977 MICHAEL F. SZCZEPANIK

Facility Phone:

(313) 388-0060

Leak Number:

C-1002-91

UST:

Facility ID:

00035097

Tank ID:

Owner:

Michael F. Szczepanik

Owner Country:

USA

Owner Contact: Owner Address:

Not reported 9934 Sterling Ave

Allen Park, MI 48101

Owner Phone:

(313) 381-5977

Product:

Gasoline

Capacity:

2000

Tank Status:

Removed from Ground

Remove Date:

Jul 18 1991

Constr Material:

Unknown

Piping Material:

Galvanized Steel, Unknown

Map ID Direction Distance Distance (ft.)

Elevation

MAP FINDINGS

Database(s)

LUST

UST

EDR ID Number **EPA ID Number**

1000314507

U003160812

N/A

EBONEX CORP (Continued)

Piping Type: Contact:

Suction: No Valve At Tank MICHAEL F. SZCZEPANIK

Contact Phone: (313) 388-0060

Impressed DeviceNo

Install Date: Apr 11 1991

Release Detection:

Tank: Pipe:

Not reported Not reported

FUEL MART OF AMERICA INC 335 S SCHAEFER HWY DETROIT, MI 48217

1/4-1/2 2607 ft.

Higher

20

ESE

Relative:

LUST:

Facility ID:

00036546 Release Number: Closed

Actual: 588 ft.

Release Date:

Apr 26 1993

District:

SE Michigan District Office

Closed Date:

Nov 29 1995

Owner Name:

Owner Contact: Not reported Mustapha Akhdar

Owner Address: 335 S Schaefer Hwy

Detroit, MI 48217

Country:

USA

Owner Phone: Contact:

(313) 842-8500 MUSTAPHA AKHDAR

Facility Phone:

(313) 842-8500

Leak Number:

C-0489-93

UST:

Facility ID:

00036546

Tank ID:

Owner: Mustapha Akhdar

Owner Country: USA Not reported

Owner Contact:

Owner Address:

335 S Schaefer Hwy Detroit, MI 48217

(313) 842-8500

Owner Phone: Product:

Gasoline

Capacity:

10000

Tank Status:

Removed from Ground

Remove Date:

Apr 26 1993

Constr Material:

Asphalt Coated or Bare Steel

Piping Material:

Galvanized Steel

Piping Type:

Suction: No Valve At Tank, Suction: Valve at Tank MUSTAPHA AKHDAR

Contact:

Contact Phone: (313) 842-8500

Impressed DeviceNo

Jan 1 1960 Install Date:

Release Detection:

Tank:

Not reported

Pipe:

Not reported

Facility ID:

00036546

Tank ID: Owner:

Mustapha Akhdar

Owner Country:

Owner Contact:

Not reported

Map ID Direction Distance Distance (ft.) Elevation

Database(s)

EDR ID Number **EPA ID Number**

U003160812

FUEL MART OF AMERICA INC (Continued)

335 S Schaefer Hwy Owner Address:

Detroit, MI 48217

Owner Phone:

(313) 842-8500

Product:

Diesel

Capacity:

10000

Tank Status:

Removed from Ground

Remove Date:

Apr 26 1993

Constr Material:

Asphalt Coated or Bare Steel Galvanized Steel

Piping Material: Piping Type:

Suction: Valve at Tank

Contact:

MUSTAPHA AKHDAR (313) 842-8500

Contact Phone:

Impressed DeviceNo

Install Date: Jan 1 1960

Release Detection:

Tank:

Not reported

Pipe:

Not reported

Facility ID:

00036546

Tank ID:

Mustapha Akhdar

Owner:

USA

Owner Country: Owner Contact:

Not reported

Owner Address:

335 S Schaefer Hwy

Detroit, MI 48217 (313) 842-8500

Owner Phone: Product:

Gasoline

Capacity:

4000

Tank Status:

Removed from Ground

Apr 26 1993 Remove Date:

Constr Material: Asphalt Coated or Bare Steel

Piping Material:

Galvanized Steel

Piping Type:

Suction: No Valve At Tank

Contact:

MUSTAPHA AKHDAR (313) 842-8500

Contact Phone: Impressed DeviceNo

Install Date:

Not reported

Release Detection:

Tank:

Not reported

Pipe:

Not reported

Facility ID:

00036546

Tank ID:

Owner:

Mustapha Akhdar Owner Country: USA

Owner Contact:

Not reported

Owner Address:

335 S Schaefer Hwy

Detroit, MI 48217

Owner Phone:

(313) 842-8500

Product:

Gasoline

Capacity:

3000

Tank Status:

Removed from Ground

Remove Date:

Apr 26 1993

Constr Material:

Asphalt Coated or Bare Steel

Piping Material:

Galvanized Steel

Piping Type:

Suction: No Valve At Tank

Contact:

MUSTAPHA AKHDAR

Map ID Direction Distance Distance (ft.) Elevation Site

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

U003160812

FUEL MART OF AMERICA INC (Continued)

Contact Phone: (313) 842-8500

Impressed Device No

Install Date: Not reported

Release Detection:

Tank: Pipe:

Not reported Not reported

Facility ID:

00036546

Tank ID:

Owner:

Mustapha Akhdar

Owner Country: USA

Not reported Owner Contact:

335 S Schaefer Hwy Owner Address:

Detroit, MI 48217

Owner Phone:

(313) 842-8500

Product:

Diesel

Capacity:

12000

Tank Status:

Currently In Use

Remove Date:

Not reported

Constr Material: Piping Material:

Double Walled Double Walled

Piping Type:

Pressure

Contact:

MUSTAPHA AKHDAR

Contact Phone:

(313) 842-8500

Impressed Device No

Install Date:

Jul 10 1995 Release Detection:

Tank:

Automatic Tank Gauging, Groundwater Monitoring, Manual Tank Gauging

Pipe:

Automatic Line Leak Detectors, GroundWater Monitoring

Facility ID:

00036546 Tank ID:

Owner:

Mustapha Akhdar

Owner Country:

USA Not reported

Owner Contact: 335 S Schaefer Hwy Owner Address:

Detroit, MI 48217

Owner Phone:

(313) 842-8500

Product:

Diesel

Capacity:

Tank Status:

12000 Currently In Use

Remove Date:

Not reported

Constr Material:

Double Walled

Piping Material:

Double Walled

Piping Type:

Pressure

MUSTAPHA AKHDAR

Contact:

(313) 842-8500

Contact Phone:

Impressed Device No

Install Date: Jul 10 1995

Release Detection:

Tank:

Automatic Tank Gauging, Groundwater Monitoring, Manual Tank Gauging

Pipe:

Automatic Line Leak Detectors, GroundWater Monitoring

Facility ID:

00036546

Tank ID:

Owner:

Mustapha Akhdar

Owner Country:

USA

Map ID Direction Distance Distance (ft.) Elevation

Database(s)

EDR ID Number EPA ID Number

U003160812

FUEL MART OF AMERICA INC (Continued)

Owner Contact:

Not reported

Owner Address:

335 S Schaefer Hwy Detroit, MI 48217

Owner Phone:

(313) 842-8500 Gasoline

Product:

Capacity:

12000

Tank Status: Remove Date:

Currently In Use Not reported Double Walled

Constr Material: Piping Material: Piping Type:

Double Walled Pressure

Contact:

MUSTAPHA AKHDAR

Contact Phone:

(313) 842-8500

Impressed Device No

Install Date:

Jul 10 1995

Release Detection:

Tank:

Automatic Tank Gauging, Groundwater Monitoring, Manual Tank Gauging

Pipe:

Automatic Line Leak Detectors, GroundWater Monitoring

Facility ID:

00036546

Tank ID:

Mustapha Akhdar

Owner:

Owner Country: USA

Owner Contact: Not reported

Owner Address: 335 S Schaefer Hwy

Detroit, MI 48217

Owner Phone:

(313) 842-8500

Product:

Gasoline

Capacity:

10000

Tank Status:

Currently In Use

Remove Date: Constr Material:

Not reported Double Walled

Piping Material:

Double Walled

Piping Type:

Pressure

Contact:

MUSTAPHA AKHDAR

Contact Phone:

(313) 842-8500

Impressed DeviceNo

Install Date:

Jul 10 1995

Release Detection:

Tank:

Automatic Tank Gauging, Groundwater Monitoring, Manual Tank Gauging

Pipe:

GroundWater Monitoring

Facility ID:

00036546

Tank ID:

Mustapha Akhdar

Owner:

Owner Country: USA

Owner Contact:

Not reported

Owner Address:

335 S Schaefer Hwy

Owner Phone:

Detroit, MI 48217

Product:

(313) 842-8500

Gasoline

Capacity:

8000

Tank Status:

Currently In Use

Remove Date: Constr Material:

Not reported Double Walled

Piping Material: Piping Type:

Double Walled Pressure

Map ID Direction Distance Distance (ft.) Elevation Site

MAP FINDINGS

Database(s)

LUST

UST

U000268243

N/A

EDR ID Number EPA ID Number

U003160812

FUEL MART OF AMERICA INC (Continued)

Contact:

MUSTAPHA AKHDAR

Contact Phone:

(313) 842-8500

Impressed DeviceNo

Jul 10 1995 Install Date:

Release Detection:

Tank:

Automatic Tank Gauging, Groundwater Monitoring, Manual Tank Gauging

Automatic Line Leak Detectors, GroundWater Monitoring

Pipe:

Facility ID:

00036546

Tank ID:

Owner:

Mustapha Akhdar

Owner Country:

USA

Not reported

Owner Contact:

335 S Schaefer Hwy

Owner Address:

Detroit, MI 48217

Owner Phone: Product:

(313) 842-8500

Capacity:

Diesel

8000

Tank Status:

Currently In Use

Remove Date:

Not reported Double Walled

Constr Material:

Double Walled

Piping Material: Piping Type:

Pressure

Contact:

MUSTAPHA AKHDAR

Contact Phone:

(313) 842-8500

Impressed DeviceNo

Install Date: Jul 10 1995

Release Detection:

Tank:

Automatic Tank Gauging, Groundwater Monitoring, Manual Tank Gauging

Pipe:

Automatic Line Leak Detectors, GroundWater Monitoring

21

WNN

DPW YARD 3315 GREENFIELD RD

1/4-1/2

MELVINDALE, MI 48122

2613 ft.

Relative: Lower

580 ft.

LUST:

Facility ID:

00034930

Release Number: Closed

Actual:

Release Date: Dec 21 1994

District:

SE Michigan District Office

Closed Date:

Sep 25 1997

Owner Contact: Not reported

Owner Name:

City Of Melvindale

Owner Address:

3100 Oakwood Blvd

Melvindale, MI 48122

Country:

USA

Owner Phone: Contact:

(313) 389-2000 **ERIC WITTE**

Facility Phone: Leak Number:

(313) 389-1129 C-1536-94

UST:

Facility ID:

00034930

Tank ID: Owner

City Of Melvindale

Owner Country:

USA

Owner Contact:

Not reported

Owner Address:

3100 Oakwood Blvd

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

U000268243

DPW YARD (Continued)

Melvindale, MI 48122

Owner Phone:

(313) 389-2000 Gasoline

Product: Capacity:

6000

Tank Status:

Removed from Ground

Remove Date: Constr Material:

Feb 28 1995 Unknown Unknown

Piping Material: Piping Type: Contact:

Not reported **ERIC WITTE** (313) 389-1129

Impressed Device No

Install Date:

Jan 1 1970

00034930

Release Detection:

Contact Phone:

Tank:

Inventory Control, Tank Tightness Testing

Pipe:

Line Tightness Testing

Facility ID:

Tank ID:

Owner:

City Of Melvindale

Owner Country: USA

Owner Contact: Not reported

3100 Oakwood Blvd Owner Address:

Melvindale, MI 48122

Owner Phone:

(313) 389-2000

Product:

Diesel 6000

Capacity: Tank Status:

Currently In Use

Remove Date:

Not reported

Constr Material:

Lined Interior FLEX, Secondary Containment

Piping Material: Piping Type:

Suction: Valve at Tank

Contact:

ERIC WITTE (313) 389-1129

Contact Phone:

Impressed Device No

Install Date: Jan 1 1965

Release Detection:

Tank:

Automatic Tank Gauging

Pipe:

Not reported

Facility ID:

00034930

Tank ID: Owner:

City Of Melvindale USA

Owner Country:

Owner Contact: Not reported

Owner Address:

3100 Oakwood Blvd

Melvindale, MI 48122

Owner Phone:

(313) 389-2000

Product:

Gasoline

Capacity:

12000

Tank Status:

Removed from Ground

Remove Date: Constr Material: Feb 28 1995

Piping Material:

Unknown Unknown

Piping Type:

Not reported

Contact: Contact Phone:

ERIC WITTE (313) 389-1129 Map ID Direction Distance Distance (ft.)

Elevation

MAP FINDINGS

Database(s)

RCRIS-SQG

CORRACTS

FINDS RCRIS-TSD

EDR ID Number EPA ID Number

U000268243

SHWS S105144810

N/A

1000439958

MID094549425

DPW YARD (Continued)

Impressed DeviceNo

Install Date:

Jan 1 1965

Release Detection:

Tank:

Inventory Control, Tank Tightness Testing

Pipe:

Not reported

22

DETROIT STRIP CYCLOPS STEEL

ENE

971 SOUTH OAKWOOD DETROIT, MI 48217

1/2-1

3271 ft.

Relative: Lower

SHWS:

Facility ID:

82000173 Inactive - no actions taken to address contamination

Facility Status:

Metal Processing

Actual: 580 ft.

Pollutant(s):

Source:

PCB's; Gasoline; Petroleum; Sulfuric acid

SAM Score:

SAM Score Date:

09/05/1990

Township: Range:

02S 11E

Section:

30 NW

Quarter: Quarter/Quarter:

NW

23 NE LEVY EDW C CO PLT 6 13950 MELON RD

DETROIT, MI 48217

1/2-1 3473 ft.

Relative:

Lower

CORRACTS Data:

Actual: 579 ft.

EPA Id: Region:

Area Name:

MID094549425 **ENTIRE FACILITY**

Actual Date:

04/06/1988

Corrective Action:

CA050 - RFA Completed

2002 NAICS Title:

Waste Treatment and Disposal

EPA ld:

MID094549425

Region:

ENTIRE FACILITY Area Name:

Actual Date:

Corrective Action:

CA070NO - RFA Determination Of Need For An RFI, RFI is Not Necessary

2002 NAICS Title:

Waste Treatment and Disposal

EPA ld:

MID094549425

Region: Area Name:

Actual Date:

ENTIRE FACILITY

Corrective Action:

09/27/1991

CA075LO - CA Prioritization, Facility or area was assigned a low corrective

action priority

2002 NAICS Title:

Waste Treatment and Disposal

EPA Id:

MID094549425

Region:

Area Name:

ENTIRE FACILITY

Actual Date:

11/04/1999

Corrective Action:

CA725YE - Current Human Exposures Under Control, Yes, Current Human Exposures

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

LEVY EDW C CO PLT 6 (Continued)

1000439958

2002 NAICS Title:

Under Control has been verified Waste Treatment and Disposal

EPA Id:

MID094549425

Region:

Area Name:

ENTIRE FACILITY

Actual Date:

11/04/1999

Corrective Action:

CA750YE - Migration of Contaminated Groundwater under Control, Yes, Migration of

Contaminated Groundwater Under Control has been verified

2002 NAICS Title:

Waste Treatment and Disposal

RCRIS Corrective Action Summary:

Event: Current Human Exposures under Control, Yes, Current Human Exposures Under

> Control has been verified. Based on a review of information contained in the El determination, current human exposures are expected to be under control at the facility under current and reasonably expected conditions. This

determination will be re-evaluated when the Agency/State becomes aware of

significant changes at the facility.

Event Date:

11/04/1999

Event:

Igration of Contaminated Groundwater under Control, Yes, Migration of Contaminated Groundwater Under Control has been verified. Based on a review of information contained in the El determination, it has been determined

that migration of contaminated groundwater is under control at the facility.

Specifically, this determination indicates that the migration of

contaminated groundwater is under control, and that monitoring will be conducted to confirm that contaminated groundwater remains within the existing area of contaminated groundwater. This determination will be re-evaluated when the Agency becomes aware of significant changes at the

facility.

Event Date:

11/04/1999

Event:

CA Prioritization, Facility or area was assigned a low corrective action

Event Date:

09/27/1991

Event:

RFA Completed

Event Date:

04/06/1988

Event:

RFA Determination Of Need For An RFI, RFI is Not Necessary;

Event Date:

04/06/1988

RCRIS:

Owner: EPA ID: EDW. C. LEVY CO.

MID094549425 FRANK RIORDAN

Contact: (313) 843-7200

Classification:

TSDF Activities: Not reported

TSDF

Map ID Direction Distance Distance (ft.) Elevation Site

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

1000439958

LEVY EDW C CO PLT 6 (Continued)

Violation Status: Violations exist

Regulation Violated:

Area of Violation:

Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action:

Enforcement Action Date:

Penalty Type:

Regulation Violated: Area of Violation:

Date Violation Determined:

Actual Date Achieved Compliance:

Enforcement Action:

Enforcement Action Date:

Penalty Type:

Regulation Violated: Area of Violation:

Date Violation Determined:

Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date:

Penalty Type:

Regulation Violated:

Area of Violation:

Date Violation Determined:

Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date:

Penalty Type:

Enforcement Action: Enforcement Action Date:

Penalty Type:

Enforcement Action: **Enforcement Action Date:**

Penalty Type:

Enforcement Action: **Enforcement Action Date:**

Penalty Type:

Regulation Violated:

Area of Violation:

Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date:

Penalty Type:

Enforcement Action: Enforcement Action Date:

Penalty Type:

Enforcement Action: Enforcement Action Date: Not reported

TSD-PERMIT CONDITION

12/18/2001 02/19/2002

WRITTEN INFORMAL

12/18/2001 Not reported

Not reported

TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS

09/25/1989 09/28/1989

WRITTEN INFORMAL

09/25/1989 Not reported

Not reported

TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS

08/09/1988 09/29/1989

WRITTEN INFORMAL

03/31/1989 Not reported

Not reported

TSD-GOUNDWATER MONITORING REQUIREMENTS

06/24/1986 10/27/1987

VERBAL INFORMAL

11/30/1983

Final Monetary Penalty

WRITTEN INFORMAL

07/10/1986

Final Monetary Penalty

INITIAL 3008(A) COMPLIANCE ORDER

10/24/1986

Final Monetary Penalty

FINAL 3008(A) COMPLIANCE ORDER

07/13/1987

Final Monetary Penalty

Not reported

TSD-CLOSURE/POST-CLOSURE REQUIREMENTS

06/24/1986 10/27/1987

VERBAL INFORMAL

11/30/1983

Final Monetary Penalty

WRITTEN INFORMAL

07/10/1986

Final Monetary Penalty

WRITTEN INFORMAL

09/23/1986

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number **EPA ID Number**

1000439958

LEVY EDW C CO PLT 6 (Continued)

Penalty Type:

Enforcement Action:

Enforcement Action Date:

Penalty Type:

Enforcement Action:

Enforcement Action Date:

Penalty Type:

Regulation Violated:

Area of Violation:

Date Violation Determined:

Actual Date Achieved Compliance:

Enforcement Action:

Enforcement Action Date:

Penalty Type:

Enforcement Action: Enforcement Action Date:

Penalty Type:

Enforcement Action:

Enforcement Action Date:

Penalty Type:

Enforcement Action:

Enforcement Action Date: Penalty Type:

Regulation Violated:

Area of Violation:

Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action:

Enforcement Action Date:

Penalty Type:

Enforcement Action:

Enforcement Action Date:

Penalty Type:

Regulation Violated:

Area of Violation:

Date Violation Determined: Actual Date Achieved Compliance:

Enforcement Action:

Enforcement Action Date: Penalty Type:

Regulation Violated: Area of Violation:

Date Violation Determined:

Actual Date Achieved Compliance:

Enforcement Action: Enforcement Action Date:

Penalty Type:

Final Monetary Penalty

INITIAL 3008(A) COMPLIANCE ORDER

10/24/1986

Final Monetary Penalty

FINAL 3008(A) COMPLIANCE ORDER

07/13/1987

Final Monetary Penalty

Not reported

TSD-OTHER REQUIREMENTS 06/24/1986

10/27/1987

VERBAL INFORMAL

11/30/1983

Final Monetary Penalty

WRITTEN INFORMAL 07/10/1986

Final Monetary Penalty

INITIAL 3008(A) COMPLIANCE ORDER

10/24/1986

Final Monetary Penalty

FINAL 3008(A) COMPLIANCE ORDER

07/13/1987

Final Monetary Penalty

Not reported

TSD-OTHER REQUIREMENTS

08/19/1985

11/07/1985

WRITTEN INFORMAL

08/27/1985

Not reported

WRITTEN INFORMAL

10/03/1985

Not reported

Not reported

TSD-GOUNDWATER MONITORING REQUIREMENTS

11/20/1983

05/14/1984

WRITTEN INFORMAL

11/04/1983 Not reported

Not reported

TSD-GOUNDWATER MONITORING REQUIREMENTS

09/22/1983 05/14/1985

WRITTEN INFORMAL

11/04/1983

Not reported

There are 9 violation record(s) reported at this site:

Evaluation

Area of Violation

Date of Compliance Map ID Direction Distance Distance (ft.)

Elevation

MAP FINDINGS

TSD-PERMIT CONDITION

TSD-OTHER REQUIREMENTS

Database(s)

EDR ID Number EPA ID Number

1000439958

S103594553

N/A

LEVY EDW C CO PLT 6 (Continued)

Non-Financial Record Review Financial Record Review

TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS Financial Record Review Compliance Evaluation Inspection

TSD-FINANCIAL RESPONSIBILITY REQUIREMENTS TSD-GOUNDWATER MONITORING REQUIREMENTS TSD-CLOSURE/POST-CLOSURE REQUIREMENTS

19890929 19871027 19871027 19871027

20020219

19890928

Compliance Evaluation Inspection Compliance GW Monitoring Evaluation

Compliance Evaluation Inspection

TSD-OTHER REQUIREMENTS TSD-GOUNDWATER MONITORING REQUIREMENTS TSD-GOUNDWATER MONITORING REQUIREMENTS 19851107 19840514 19850514

SHWS

FINDS:

Other Pertinent Environmental Activity Identified at Site:

Resource Conservation and Recovery Act Information system

24 NW MICH CON GAS CO MELVINDALE

3900 GREENFIELD RD MELVINDALE, MI 48122

1/2-1

4412 ft. Relative:

Lower

SHWS:

Facility ID:

82000028 Interim Response in progress Facility Status:

Actual:

Source:

Petroleum & Coal Products As; B; T; X; Heavy metals

583 ft. Pollutant(s): SAM Score:

SAM Score Date:

03/02/2004 Township: 02S

Range:

12E

Section:

10 null

Quarter:

Quarter/Quarter: null

25 WNN MICHIGAN CONSOLIDATED GAS CO. RIVER ROUGE STATION GREENFIELD ROAD

Coal Gas N/A

G000001402

1/2-1

MELVINDALE, MI 48122

4483 ft.

Relative:

COAL GAS SITE DESCRIPTION:

Lower

Site is located on north and northwest side of Greenfield Road, west of P rospect Ave. and is

bordered on the River Rouge on the west and north. 1949 no indication of gas

Actual:

manufacturing.

576 ft.

©Copyright 1993 Real Property Scan, Inc.

B26 **ESE** MARATHON PIPELINE CRYSTAL MINES 1300 SOUTH FORT STREET

SHWS

PEAS

S105144794 N/A

1/2-1

DETROIT, MI 0

4829 ft.

Site 1 of 2 in cluster B

Facility ID:

Relative: Lower

SHWS:

82000076

Actual: 585 ft.

Facility Status:

Interim Response conducted - No further activities anticipated

Source: Pollutant(s): Petroleum Refining

Cl; Fuel oil 38

SAM Score: SAM Score Date:

12/08/1993

Township:

025

Map ID Direction Distance Distance (ft.) Elevation Site

Database(s)

EDR ID Number EPA ID Number

S105144794

MARATHON PIPELINE CRYSTAL MINES (Continued)

Range:

11E 33

Section: Quarter:

NW

Quarter/Quarter:

NW

MI PEAS:

PEAS Number:

Not reported

Incident Date:

Not reported Not reported

Date Of PEAS Call: Complainant / Company:

Not reported

Complainant Location:

Not reported

Complainant Address:

Not reported

Complainant Phone: Company Involved:

Not reported MarathonAshland Petrolium

Company Involved Address:

Not reported

Township Of Incident:

Not reported

Name/Volume Of Contaminant:

Not reported

Surface Water Involved ?:

Not reported

Dispatched To District Staff: DEQ Division Involved:

null

Date Dispatch:

null

Not reported

Incident Desc:

Not Reported

PEAS Number:

135-00

Incident Date:

03/23/2000

Date Of PEAS Call: Complainant / Company: 03/23/2000 Paula Bremer

Complainant Location: Complainant Address:

Detroit, MI 1300 South Fort Street

Complainant Phone:

313-297-6364

Company Involved:

Marathon Ashland Petroleum

Company Involved Address:

1300 South Fort Street City

Township Of Incident: Name/Volume Of Contaminant:

Hydrogen Sulfide/ Unknown

Surface Water Involved ?:

None Operator

Dispatched To District Staff: DEQ Division Involved:

Wayne County

Date Dispatch:

03/23/2000

Incident Desc:

Hydrogen Sulfide released in flaring incident.

PEAS Number: Incident Date:

843-00 10/18/2000

Date Of PEAS Call:

10/18/2000

Complainant / Company:

Carol Bremer w/Marathon National

Detroit, MI

Complainant Location: Complainant Address:

1300 South Fort

Complainant Phone:

313-397-6364

Company Involved:

Carol Bremer w/Marathon National

Company Involved Address:

1300 South Fort

Township Of Incident:

Not reported

Name/Volume Of Contaminant:

Sulfur Dioxide/

Surface Water Involved ?:

None

Dispatched To District Staff: DEQ Division Involved:

P. Samuel George Wayne Co. DOE 10/18/2000

Date Dispatch: Incident Desc:

They lost a boiler which caused an upset of their hydro treater

whichresulted in releasing Sulfur Dioxide.

Unknown

Map ID Direction Distance Distance (ft.) Elevation Site

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

MARATHON PIPELINE CRYSTAL MINES (Continued)

S105144794

PEAS Number:

229-01

Incident Date:

04/13/2001

Date Of PEAS Call: Complainant / Company: 04/14/2001

Complainant Location:

David Linington w/Marathon Ashland Petroleum Detroit, MI

Complainant Address:

1300 S. Fort St. 313-297-6341

Complainant Phone: Company Involved:

David Linington w/Marathon Ashland Petroleum

Company Involved Address:

1300 South Fort Street

Township Of Incident:

Not reported

Name/Volume Of Contaminant:

Sulfur Dioxide/500 lbs.

Surface Water Involved ?:

None

Dispatched To District Staff:

Sue (Operator)

DEQ Division Involved:

Wayne Co. Dept. of Environ.

Date Dispatch:

Incident Desc:

There was a Sulfur Dioxide release that went into the air. He said he

wasgoing to call the Wayne County hotline number also to report this.

PEAS Number:

Not reported

Incident Date:

04/29/2001 04/30/2001

Date Of PEAS Call: Complainant / Company:

Tonya Landis w/Marathon Ashland Petroleum

Complainant Location:

Detroit, MI

Complainant Address:

1300 S. Fort St. 313-843-9100

Complainant Phone: Company Involved:

Tonya Landis w/Marathon Ashland Petroleum

Company Involved Address:

1300 S. Fort St.

Township Of Incident:

Not reported

Name/Volume Of Contaminant:

Gas/500 lbs.

Surface Water Involved?:

None

Dispatched To District Staff:

Sylvia Martin Wayne Co. Health Dept.

DEQ Division Involved: Date Dispatch:

04/30/2001

Incident Desc:

Fluid catalytic cracking unit was starting up after it was shut down.

Theprocess gases were released to flare. Everything was okay once the

unitstarted working properly.

PEAS Number:

Incident Date:

298-01 05/06/2001

Date Of PEAS Call:

05/06/2001

Complainant / Company:

Complainant Location:

David Linington w/Marathon Ashland Petroleum Detroit, MI

Complainant Address:

1300 S. Fort Street

Complainant Phone:

Company Involved:

313-297-6341

Company Involved Address:

David Linington w/Marathon Ashland Petroleum 1300 S. Fort St.

Township Of Incident:

Detroit (City of)

Name/Volume Of Contaminant:

SO2/1,000 pounds

Surface Water Involved ?:

None

Dispatched To District Staff:

Operator

DEQ Division Involved:

Wayne Co. DOE

Date Dispatch:

05/06/2001

Incident Desc:

S02 released into the air. One of the units went into emergency shut

down.Lost approximately 1,000 pounds.

PEAS Number:

371-01

Map ID Direction Distance Distance (ft.) Site Elevation

Database(s)

EDR ID Number EPA ID Number

S105144794

MARATHON PIPELINE CRYSTAL MINES (Continued)

Incident Date:

05/31/2001

Date Of PEAS Call:

05/31/2001

Complainant / Company:

David w/Marathon Ashland Petroleum Detroit, MI

Complainant Location: Complainant Address:

1300 S. Fort St. 313-297-6341

Complainant Phone: Company Involved:

David w/Marathon Ashland Petroleum

Company Involved Address:

1300 S. Fort St.

Township Of Incident: Name/Volume Of Contaminant:

Not reported Sulfur Dioxide/ Unknown

Surface Water Involved ?:

None

Dispatched To District Staff: DEQ Division Involved:

Wayne Co. DOE Not reported

Date Dispatch:

05/31/2001

Incident Desc:

Complainant said equipment malfunctioned and resulted in a Sulfur

Dioxidereleased to the ground and to the air.

PEAS Number:

404-01 06/09/2001 06/10/2001

Incident Date: Date Of PEAS Call:

Tonya Landis w/Marathon Ashland Petroleum

Complainant / Company: Complainant Location:

Detroit, MI 1300 S. Fort St.

Complainant Address: Complainant Phone:

313-843-9100 Tonya Landis w/Marathon Ashland Petroleum

Company Involved: Company Involved Address:

Unknown Not reported

Township Of Incident: Name/Volume Of Contaminant:

Sulfur Dioxide/More than 500 lbs.

Surface Water Involved ?: Dispatched To District Staff: None Operator

DEQ Division Involved: Date Dispatch:

Wayne Co. DOE 06/10/2001

Incident Desc:

Flaring incident from crude unit. There was a release of Sulfur Dioxide.

PEAS Number: Incident Date:

433-01 06/17/2001 06/17/2001

Date Of PEAS Call: Complainant / Company:

Marathon Ashland Petroleum

Complainant Location: Complainant Address:

Detroit, MI 1300 S. Fort St. 313-297-6341

Complainant Phone: Company Involved:

Marathon Ashland Petroleum

Company Involved Address: Township Of Incident:

1300 S. Fort St. Not reported

Name/Volume Of Contaminant:

Sulfur Dioxide/ Unknown

Surface Water Involved ?:

None Sylvia Martin

Dispatched To District Staff: DEQ Division Involved:

Wayne Co. Health Dept.

Date Dispatch: Incident Desc:

06/18/2001

They had a release of Sulfur Dioxide.

PEAS Number: Incident Date:

Not reported 11/13/2001

Date Of PEAS Call:

11/13/2001 Brian Durvee w/Marathon Ashland Petroleum

Complainant / Company: Complainant Location:

Detroit, MI

Complainant Address:

1300 South Fort Street

Map 1D Direction Distance Distance (ft.) Elevation

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

S105144794

MARATHON PIPELINE CRYSTAL MINES (Continued)

Complainant Phone:

313-297-6364

Company Involved:

Brian Duryee w/Marathon Ashland Petroleum

Company Involved Address:

1300 South Fort Street

Township Of Incident:

Not reported

Name/Volume Of Contaminant: Surface Water Involved ?:

SO2 gas/Approx. 500 lbs.

Dispatched To District Staff:

None Jeff Korniski

DEQ Division Involved:

AQD 11/13/2001

Date Dispatch: Incident Desc:

There was a release of SO2 gas.

PEAS Number: Incident Date :

890-01

Date Of PEAS Call:

12/20/2001

Complainant / Company:

12/20/2001

Complainant Location:

David Linington w/Marathon Ashland Petroleum

Detroit, MI

Complainant Address:

Complainant Phone:

1300 South Fort Street 313-297-6341

Company Involved:

David Linington w/Marathon Ashland Petroleum

Company Involved Address:

1300 South Fort Street

Township Of Incident:

Not reported

Name/Volume Of Contaminant:

Sulfur dioxide/

Surface Water Involved ?:

None Lillian Woolley

Dispatched To District Staff:

AQD

DEQ Division Involved:

12/20/2001

Date Dispatch: Incident Desc:

Unknown amount of sulfur dioxide was released due to a FCC unit upset.

PEAS Number:

893-01

Incident Date:

12/23/2001 12/23/2001

Date Of PEAS Call:

Jeff Bruestle w/Marathon Ashland Petroleum

Unknown

Complainant / Company: Complainant Location:

Detroit, MI

Complainant Address:

1300 South Fort Street

Complainant Phone:

313-843-9100

Company Involved: Company Involved Address: Jeff Bruestle w/Marathon Ashland Petroleum 1300 South Fort Street

Township Of Incident:

Not reported

Name/Volume Of Contaminant:

Surface Water Involved ? :

Sulfur dioxide/ None

Dispatched To District Staff:

Lillian Woolley

DEQ Division Involved:

AQD

Date Dispatch:

12/23/2001

Incident Desc:

A release of sulfur dioxide is coming from the recovery unit. They have hadprocess problems, which caused the release. They are shutting downa

portion of the unit until the problem is found and repairs are made.

Greater than 500 pounds

PEAS Number:

106-02

Incident Date:

03/11/2002

Date Of PEAS Call: Complainant / Company: 03/11/2002 Cindy Bain w/Marathon Ashland Petroleum

Complainant Location:

Detroit, MI

Complainant Address:

1300 South Fort Street

Complainant Phone:

313-297-6309

Company Involved:

Cindy Bain w/Marathon Ashland Petroleum

Company Involved Address:

1300 South Fort Street

Township Of Incident:

Not reported

Map ID Direction Distance Distance (ft.) Site Elevation

Database(s)

EDR ID Number EPA ID Number

MARATHON PIPELINE CRYSTAL MINES (Continued)

S105144794

Name/Volume Of Contaminant: Sulfur dioxide/

Surface Water Involved ?:

None

Dispatched To District Staff:

Lee Varner

DEQ Division Involved:

AQD

Date Dispatch:

03/12/2002

Incident Desc:

Reporting a reportable quantity exceed for sulfur dioxide air release. Aseries of events happened today. Not sure if the 10:30 a.m.

eventtriggered the release. We may have exceeded more, if so we will call

toreport it. They are recalculating the amount estimated.

Greater than 500 lbs.

PEAS Number:

504-02

Incident Date: Date Of PEAS Call: 08/01/2002 08/01/2002

Complainant / Company:

David Linington w/Marathon Ashland Petroleum

Complainant Location:

Detroit, MI

Complainant Address:

1300 South Fort Street

Complainant Phone:

313-886-2544

Company Involved:

David Linington w/Marathon Ashland Petroleum

Company Involved Address:

1300 South Fort Street

Township Of Incident: Name/Volume Of Contaminant: Not reported

Surface Water Involved ?:

Sulfur dioxide/700 lbs. None

Dispatched To District Staff:

Lee Varner AQD

DEQ Division Involved:

08/02/2002

Date Dispatch: Incident Desc:

There was a sulfur dioxide release of approximately 700 lbs. It was

releasedat approximately 7:00 p.m. tonight.

PEAS Number:

624-02

Incident Date Date Of PEAS Call: 09/07/2002 09/07/2002

Complainant / Company:

Brian Duryee w/Marathon Petroleum

Complainant Location:

Detroit, MI

Complainant Address: Complainant Phone:

1300 South Fort Street

Company Involved:

313-297-6364

Company Involved Address:

Brian Duryee w/Marathon Petroleum 1300 South Fort Street

Township Of Incident:

Name/Volume Of Contaminant:

Not reported

Surface Water Involved ?:

Sulfur dioxide/500 to 1,000 lbs.

Dispatched To District Staff: DEQ Division Involved:

None Jon Lamb

Date Dispatch:

AQD

09/09/2002

Incident Desc:

The cat unit went down. There was a release of 500 to 1,000 pounds ofof

sulfur dioxide.

PEAS Number:

681-02

Incident Date : Date Of PEAS Call: 09/28/2002 09/28/2002

Cindy Bain w/Marathon Shalin Petroleum

Complainant / Company:

Detroit, MI

Complainant Location: Complainant Address:

1300 South Fort Street

Complainant Phone:

Company Involved:

313-297-6309 Cindy Bain w/Marathon Shalin Petroleum

Company Involved Address:

1300 South Fort Street

Township Of Incident: Name/Volume Of Contaminant :

Not reported Sulfur dioxide/

Greater than 500 lbs.

Map ID Direction Distance Distance (ft.) Elevation Site

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

MARATHON PIPELINE CRYSTAL MINES (Continued)

S105144794

Surface Water Involved ?: Dispatched To District Staff: None Mike Gruber

DEQ Division Involved:

AQD 09/28/2002

Date Dispatch:

Incident Desc:

Lost the heater unit, gas testing unit, and potential. The duration of thevent was from 1:03 p.m. to 1:30 p.m. Lost greater than 500 poundsof

sulfur dioxide into the air.

PEAS Number:

Not reported 11/18/2002

Incident Date: Date Of PEAS Call:

11/18/2002

Complainant / Company:

Cindy Bain w/Marathon Ashland Petroleum

Complainant Location:

Detroit, MI

Complainant Address:

1300 South Fort Street

Complainant Phone:

313-297-6309

Company Involved:

Cindy Bain w/Marathon Ashland Petroleum

Approx. 150 gallons

Company Involved Address:

1300 South Fort Street

Township Of Incident: Name/Volume Of Contaminant: Not reported

Gas and oil/

Surface Water Involved ?:

None

Dispatched To District Staff:

Cheryl Wilson

DEQ Division Involved:

RRD

Date Dispatch:

11/18/2002

Incident Desc:

There was a leak coming from a gas oil line to the soil. It did not make it toany sewers or other waters. It was noticed immediately. Has

vac-trucks, booms, and pads on the scene. The leak has been contained.

PEAS Number:

773-02

Incident Date: Date Of PEAS Call: 11/20/2002 11/20/2002

Complainant / Company:

Ian Ladomer w/Marathon

Complainant Location:

Detroit, MI

Complainant Address:

1300 South Fort Street

Complainant Phone:

313-297-6336

Company Involved:

lan Ladomer w/Marathon 1300 South Fort Street

Company Involved Address: Township Of Incident:

Not reported

Name/Volume Of Contaminant:

Surface Water Involved ?:

SO2/Greater than 500 lbs.

None

Dispatched To District Staff: DEQ Division Involved:

Mike Gruber

AQD 11/20/2002

Date Dispatch: Incident Desc:

There is a high SO release in SRU incinerator to the air. They are attemptingto correct the problem. The volume is greater than 500 lbs.

PEAS Number:

786-02

Incident Date:

12/07/2002 12/07/2002

Date Of PEAS Call:

Honor w/Marathon Ashland Petroleum

Complainant / Company: Complainant Location:

Detroit, MI

1300 South Fort Street

Complainant Address:

248-408-3034

Complainant Phone: Company Involved:

Company Involved Address:

Honor w/Marathon Ashland Petroleum

Township Of Incident:

1300 South Fort Street

Name/Volume Of Contaminant:

Not reported

Oil or gas/Approx. 850 gallons

Surface Water Involved ?:

None

Map ID MAP FINDINGS

Direction Distance Distance (ft.) Elevation

Database(s)

EDR ID Number EPA ID Number

S105144794

MARATHON PIPELINE CRYSTAL MINES (Continued)

Dispatched To District Staff:

DEQ Division Involved: Date Dispatch:

12/07/2002

RRD

Ray Spaulding

Incident Desc:

Discovered oil or gas spill to the ground. It was coming from one of theirtanks. They have already called a cleanup contractor and the City ofDetroit Water and Sewer Company. Cleanup contractor to be on-site

withinone hour.

PEAS Number:

787-02

Incident Date: Date Of PEAS Call: 12/07/2002 12/07/2002

Complainant / Company:

Honor w/Marathon Ashland Petroleum

Complainant Location:

Detroit MI

Complainant Address: Complainant Phone:

1300 South Fort Street

248-408-3034

Company Involved:

Honor w/Marathon Ashland Petroleum

Company Involved Address:

1300 South Fort Street

Township Of Incident:

Not reported

Name/Volume Of Contaminant:

Oil or gas/25 gallons

Surface Water Involved ?:

None

Dispatched To District Staff:

Ray Spaulding

DEQ Division Involved:

RRD

Date Dispatch:

12/07/2002

Incident Desc:

Regarding Incident #787-02, called back to revise spill volume estimate

from850 gallons to 25 gallons.

PEAS Number:

Incident Date:

Not reported 05/27/2003

Date Of PEAS Call:

05/27/2003

Complainant / Company:

Marathon Ashland Petroleum

Complainant Location: Complainant Address:

Detroit, Michigan 1300 South Fort Street

Complainant Phone:

313-297-6336

Company Involved:

Marathon Ashland Petroleum

Company Involved Address: Township Of Incident:

1300 South Fort Street

Name/Volume Of Contaminant:

Not reported

Surface Water Involved ?:

S.0/2-500 pounds None

Dispatched To District Staff:

Not reported

Not reported

DEQ Division Involved:

Date Dispatch:

Incident Desc:

S.0/2 release due to flaring.

B27 ESE MARATHON REFINERY TANK FARM 1300 SOUTH FORT STREET

SHWS S105144803

1/2-1

MELVINDALE, MI 48217

DEL SHWS

N/A

4829 ft.

Site 2 of 2 in cluster B

Relative: Lower

SHWS:

Facility ID:

82000149

Actual: 585 ft.

Facility Status:

Delisted - no longer meets criteria specified in rules

Source: Pollutant(s): Petroleum Refining

SAM Score:

Crude oil

SAM Score Date:

23

Township:

09/06/1990

02S

Range:

11E

Section:

26

Map ID
Direction
Distance
Distance (ft.)
Elevation Site

MAP FINDINGS

Database(s)

EDR ID Number EPA ID Number

S105144803

MARATHON REFINERY TANK FARM (Continued)

Quarter:

null null

Quarter/Quarter:

DELETED HWS: Facility ID:

82000149

Status:

Delisted - no longer meets criteria specified in rules

Facility ID:

82000154

Status:

Delisted - no longer meets criteria specified in rules

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	
MELVINDALE MELVINDALE MELVINDALE MELVINDALE	U003320752 \$103594556	TACO BROTHERS TRUCKING NONFOLK SOUTHERN CORP NORFOLK AND WESTERN RAILROAD NORFOLK SOUTHERN CORP	333 DIX ST 1800 DIX 17670 N WABASH ST 17670 N WABASH	48122 48122	RCRIS-SQG UST SHWS LUST, UST	

AREA RADON INFORMATION

No records reported for ZIP:48122 MI

- Federal EPA Radon Zone for WAYNE County, MI: 3

Note

: Zone 1 indoor average level > 4 pCi/L. : Zone 2 indoor average level >= 2 pCi/L and <= 4 pCi/L. : Zone 3 indoor average level < 2 pCi/L.

- Federal Area Radon Information for WAYNE County, MI

Number of sites tested: 159

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
	V	2.702.2-00-00-00-	****	
Living Area - 1st Floor Living Area - 2nd Floor Basement	0.853 pCi/L Not Reported 1.398 pCi/L	100% Not Reported 97%	0% Not Reported 3%	0% Not Reported 0%

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Elapsed ASTM days: Provides confirmation that this EDR report meets or exceeds the 90-day updating requirement of the ASTM standard.

FEDERAL ASTM STANDARD RECORDS

NPL: National Priority List

Source: EPA Telephone: N/A

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 04/27/04 Date Made Active at EDR: 05/21/04

Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 05/04/04

Elapsed ASTM days: 17

Date of Last EDR Contact: 05/04/04

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)

Telephone: 202-564-7333

EPA Region 1

Telephone 617-918-1143

EPA Region 3

Telephone 215-814-5418

EPA Region 4

Telephone 404-562-8033

EPA Region 6

Telephone: 214-655-6659

EPA Region 8

Telephone: 303-312-6774

Proposed NPL: Proposed National Priority List Sites

Source: EPA Telephone: N/A

> Date of Government Version: 04/27/04 Date Made Active at EDR: 05/21/04

Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 05/04/04

Elapsed ASTM days: 17

Date of Last EDR Contact: 05/04/04

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

Source: EPA

Telephone: 703-413-0223

CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 05/17/04 Date Made Active at EDR: 08/10/04 Database Release Frequency: Quarterly

Date of Data Arrival at EDR: 06/23/04 Elapsed ASTM days: 48

Date of Last EDR Contact: 06/23/04

CERCLIS-NFRAP: CERCLIS No Further Remedial Action Planned

Source: EPA

Telephone: 703-413-0223

As of February 1995, CERCLIS sites designated "No Further Remedial Action Planned" (NFRAP) have been removed from CERCLIS. NFRAP sites may be sites where, following an initial investigation, no contamination was found, contamination was removed quickly without the need for the site to be placed on the NPL, or the contamination was not serious enough to require Federal Superfund action or NPL consideration. EPA has removed approximately 25,000 NFRAP sites to lift the unintended barriers to the redevelopment of these properties and has archived them as historical records so EPA does not needlessly repeat the investigations in the future. This policy change is part of the EPA's Brownfields Redevelopment Program to help cities, states, private investors and affected citizens to promote economic redevelopment of unproductive urban sites.

Date of Government Version: 05/17/04 Date Made Active at EDR: 08/10/04 Database Release Frequency: Quarterly Date of Data Arrival at EDR: 06/23/04 Elapsed ASTM days: 48 Date of Last EDR Contact: 06/23/04

CORRACTS: Corrective Action Report

Source: EPA

Telephone: 800-424-9346

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 06/15/04 Date Made Active at EDR: 08/10/04

Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 06/25/04

Elapsed ASTM days: 46

Date of Last EDR Contact: 06/07/04

RCRIS: Resource Conservation and Recovery Information System

Source: FPA

Telephone: 800-424-9346

Resource Conservation and Recovery Information System. RCRIS includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs): generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month. Small quantity generators (SQGs); generate between 100 kg and 1,000 kg of hazardous waste per month. Large quantity generators (LQGs): generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month. Transporters are individuals or entities that move hazardous waste from the generator off-site to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 06/15/04 Date Made Active at EDR: 07/20/04 Database Release Frequency: Varies

Date of Data Arrival at EDR: 06/23/04

Elapsed ASTM days: 27

Date of Last EDR Contact: 06/23/04

ERNS: Emergency Response Notification System

Source: National Response Center, United States Coast Guard

Telephone: 202-260-2342

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/03 Date Made Active at EDR: 03/12/04 Database Release Frequency: Annually

Date of Data Arrival at EDR: 01/26/04

Elapsed ASTM days: 46

Date of Last EDR Contact: 07/26/04

FEDERAL ASTM SUPPLEMENTAL RECORDS

BRS: Biennial Reporting System

Source: EPA/NTIS Telephone: 800-424-9346

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/01/01 Database Release Frequency: Biennially Date of Last EDR Contact: 06/22/04

Date of Next Scheduled EDR Contact: 09/13/04

DELISTED NPL: National Priority List Deletions

Source: EPA Telephone: N/A

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 04/27/04 Database Release Frequency: Quarterly

Date of Last EDR Contact: 05/04/04
Date of Next Scheduled EDR Contact: 08/02/04

FINDS: Facility Index System/Facility Identification Initiative Program Summary Report

Source: EPA Telephone: N/A

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 04/08/04 Database Release Frequency: Quarterly

Date of Last EDR Contact: 07/06/04 Date of Next Scheduled EDR Contact: 10/04/04

HMIRS: Hazardous Materials Information Reporting System

Source: U.S. Department of Transportation

Telephone: 202-366-4555

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 02/17/04 Database Release Frequency: Annually Date of Last EDR Contact: 04/20/04
Date of Next Scheduled EDR Contact: 07/19/04

MLTS: Material Licensing Tracking System Source: Nuclear Regulatory Commission

Telephone: 301-415-7169

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/19/04 Database Release Frequency: Quarterly

Date of Last EDR Contact: 07/06/04 Date of Next Scheduled EDR Contact: 10/04/04

MINES: Mines Master Index File

Source: Department of Labor, Mine Safety and Health Administration

Telephone: 303-231-5959

Date of Government Version: 03/05/04 Database Release Frequency: Semi-Annually Date of Last EDR Contact: 06/30/04 Date of Next Scheduled EDR Contact: 09/27/04

NPL LIENS: Federal Superfund Liens

Source: EPA

Telephone: 202-564-4267

Federal Superfund Liens. Under the authority granted the USEPA by the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner receives notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/91

Database Release Frequency: No Update Planned

Date of Last EDR Contact: 05/24/04 Date of Next Scheduled EDR Contact: 08/23/04

PADS: PCB Activity Database System

Source: EPA

Telephone: 202-564-3887

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 03/30/04 Database Release Frequency: Annually Date of Last EDR Contact: 05/12/04
Date of Next Scheduled EDR Contact: 08/09/04

DOD: Department of Defense Sites

Source: USGS

Telephone: 703-692-8801

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 10/01/03

Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 05/14/04

Date of Next Scheduled EDR Contact: 08/09/04

STORMWATER: Storm Water General Permits Source: Environmental Protection Agency

Telephone: 202 564-0746

A listing of all facilities with Storm Water General Permits.

Date of Government Version: N/A Database Release Frequency: Quarterly Date of Last EDR Contact: N/A

Date of Next Scheduled EDR Contact: N/A

INDIAN RESERV: Indian Reservations

Source: USGS

Telephone: 202-208-3710

This map layer portrays Indian administered lands of the United States that have any area equal to or greater

than 640 acres.

Date of Government Version: 10/01/03 Database Release Frequency: Semi-Annually Date of Last EDR Contact: 05/14/04

Date of Next Scheduled EDR Contact: 08/09/04

US BROWNFIELDS: A Listing of Brownfields Sites Source: Environmental Protection Agency

Telephone: 202-566-2777

Included in the listing are brownfields properties addresses by Cooperative Agreement Recipients and brownfields properties addressed by Targeted Brownfields Assessments. Targeted Brownfields Assessments-EPA's Targeted Brownfields Assessments (TBA) program is designed to help states, tribes, and municipalities—especially those without EPA Brownfields Assessment Demonstration Pilots—minimize the uncertainties of contamination often associated with brownfields. Under the TBA program, EPA provides funding and/or technical assistance for environmental assessments at brownfields sites throughout the country. Targeted Brownfields Assessments supplement and work with other efforts under EPA's Brownfields Initiative to promote cleanup and redevelopment of brownfields. Cooperative Agreement Recipients-States, political subdivisions, territories, and Indian tribes become BCRLF cooperative agreement recipients when they enter into BCRLF cooperative agreements with the U.S. EPA. EPA selects BCRLF cooperative agreement recipients based on a proposal and application process. BCRLF cooperative agreement recipients must use EPA funds provided through BCRLF cooperative agreement for specified brownfields-related cleanup activities.

Date of Government Version: 04/14/04 Database Release Frequency: Semi-Annually Date of Last EDR Contact: 06/14/04 Date of Next Scheduled EDR Contact: 09/13/04

RMP: Risk Management Plans

Source: Environmental Protection Agency

Telephone: 202-564-8600

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g. the fire department) should an accident occur.

Date of Government Version: N/A Database Release Frequency: N/A

Date of Last EDR Contact: N/A
Date of Next Scheduled EDR Contact: N/A

FUDS: Formerly Used Defense Sites Source: U.S. Army Corps of Engineers

Telephone: 202-528-4285

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers

is actively working or will take necessary cleanup actions.

Date of Government Version: 10/01/03 Database Release Frequency: Varies Date of Last EDR Contact: 07/06/04

Date of Next Scheduled EDR Contact: 10/04/04

UMTRA: Uranium Mill Tailings Sites Source: Department of Energy Telephone: 505-845-0011

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized. In 1978, 24 inactive uranium mill tailings sites in Oregon, Idaho, Wyoming, Utah, Colorado, New Mexico, Texas, North Dakota, South Dakota, Pennsylvania, and on Navajo and Hopi tribal lands, were targeted for cleanup by the Department of Energy.

Date of Government Version: 04/22/04 Database Release Frequency: Varies Date of Last EDR Contact: 06/21/04
Date of Next Scheduled EDR Contact: 09/20/04

RAATS: RCRA Administrative Action Tracking System

Source: EPA

Telephone: 202-564-4104

RCRA Administration Action Tracking System, RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/95

Database Release Frequency: No Update Planned

Date of Last EDR Contact: 06/07/04

Date of Next Scheduled EDR Contact: 09/06/04

TRIS: Toxic Chemical Release Inventory System

Source: EPA

Telephone: 202-566-0250

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/01 Database Release Frequency: Annually

Date of Last EDR Contact: 06/22/04

Date of Next Scheduled EDR Contact: 09/20/04

TSCA: Toxic Substances Control Act

Source: EPA

Telephone: 202-260-5521

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant

Date of Government Version: 12/31/02 Database Release Frequency: Every 4 Years Date of Last EDR Contact: 06/07/04

Date of Next Scheduled EDR Contact: 09/06/04

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

Source: EPA

Telephone: 202-564-2501

Date of Government Version: 04/13/04 Database Release Frequency: Quarterly Date of Last EDR Contact: 06/21/04

Date of Next Scheduled EDR Contact: 09/20/04

SSTS: Section 7 Tracking Systems

Source: EPA

Telephone: 202-564-5008

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/01 Database Release Frequency: Annually

Date of Last EDR Contact: 07/20/04 Date of Next Scheduled EDR Contact: 10/18/04

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

Source: EPA/Office of Prevention, Pesticides and Toxic Substances

Telephone: 202-564-2501

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/13/04 Database Release Frequency: Quarterly

Date of Last EDR Contact: 06/21/04 Date of Next Scheduled EDR Contact: 09/20/04

STATE OF MICHIGAN ASTM STANDARD RECORDS

SHWS: Contaminated Sites

Source: Department of Environmental Quality

Telephone: 517-373-9541

State Hazardous Waste Sites. State hazardous waste site records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. Available information varies by state.

Date of Government Version: 05/24/04 Date Made Active at EDR: 07/01/04 Database Release Frequency: Semi-Annually Date of Data Arrival at EDR: 05/25/04 Elapsed ASTM days: 37 Date of Last EDR Contact: 05/25/04

SWF/LF: Solid Waste Facilities Database Source: Department of Environmental Quality

Telephone: 517-335-4035

Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 05/25/04 Date Made Active at EDR: 07/09/04 Database Release Frequency: Semi-Annually Date of Data Arrival at EDR: 06/04/04 Elapsed ASTM days: 35 Date of Last EDR Contact: 07/26/04

LUST: Leaking Underground Storage Tank Sites Source: Department of Environmental Quality

Telephone: 517-373-8168

Leaking Underground Storage Tank Incident Reports, LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 06/12/04 Date Made Active at EDR: 07/27/04 Database Release Frequency: Annually

Date of Data Arrival at EDR: 06/16/04 Elapsed ASTM days: 41

Date of Last EDR Contact: 06/16/04

UST: Underground Storage Tank Facility List Source: Department of Environmental Quality

Telephone: 517-373-8168

Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 06/12/04 Date Made Active at EDR: 07/22/04 Database Release Frequency: Annually Date of Data Arrival at EDR: 06/16/04 Elapsed ASTM days: 36 Date of Last EDR Contact: 06/16/04

BEA: BASELINE ENVIRONMENTAL ASSESSMENT DATABASE

Source: DEPT. OF ENVIRONMENTAL QUALITY

Telephone: 517-373-9541

Date of Government Version: 06/16/04 Date Made Active at EDR: 07/27/04 Database Release Frequency: Semi-Annually Date of Data Arrival at EDR: 06/16/04 Elapsed ASTM days: 41 Date of Last EDR Contact: 06/14/04

INDIAN UST: Underground Storage Tanks on Indian Land

Source: EPA Region 5 Telephone: 312-886-6136

> Date of Government Version: 11/01/02 Date Made Active at EDR: 12/04/02 Database Release Frequency: Varies

Date of Data Arrival at EDR: 11/12/02 Elapsed ASTM days: 22 Date of Last EDR Contact: 06/15/04

HIST LF: Inactive Solid Waste Facilities Source: Department of Environmental Quality

Telephone: 517-335-4034

The database contains historical information and is no longer updated.

Date of Government Version: 03/01/97 Date Made Active at EDR: 03/06/03

Database Release Frequency: No Update Planned

Date of Data Arrival at EDR: 02/28/03 Elapsed ASTM days: 6

Date of Last EDR Contact: 02/28/03

STATE OF MICHIGAN ASTM SUPPLEMENTAL RECORDS

AST: Aboveground Tanks

Source: Department of Environmental Quality

Telephone: 517-373-8168

Registered Aboveground Storage Tanks.

Date of Government Version: 06/01/04

Database Release Frequency: No Update Planned

Date of Last EDR Contact: 06/14/04

Date of Next Scheduled EDR Contact: 09/13/04

DEL SHWS: Delisted List of Contaminated Sites Source: Department of Environmental Quality

Telephone: 517-373-9541

Sites that have been delisted or deleted from the List of Contaminated Sites. The available documentation for the site does not support it's listing or the site no longer meets criteria specified in rules.

Date of Government Version: 05/26/04 Database Release Frequency: Varies Date of Last EDR Contact: 05/24/04 Date of Next Scheduled EDR Contact: 08/23/04

PEAS: Pollution Emergency Alerting System Source: Department of Environmental Quality

Telephone: 517-373-8427

Environmental pollution emergencies reported to the Department of Environmental Quality such as tanker accidents, pipeline breaks, and release of reportable quantities of hazardous substances.

Date of Government Version: 07/02/04 Database Release Frequency: Quarterly Date of Last EDR Contact: 07/07/04 Date of Next Scheduled EDR Contact: 10/04/04

DRYCLEANERS: Drycleaning Establishments
Source: Department of Environmental Quality

Telephone: 517-335-4586

A listing of drycleaning facilities in Michigan.

Date of Government Version: 06/08/04 Database Release Frequency: Varies Date of Last EDR Contact: 05/21/04
Date of Next Scheduled EDR Contact: 08/16/04

EDR PROPRIETARY HISTORICAL DATABASES

Former Manufactured Gas (Coal Gas) Sites: The existence and location of Coal Gas sites is provided exclusively to EDR by Real Property Scan, Inc. ©Copyright 1993 Real Property Scan, Inc. For a technical description of the types of hazards which may be found at such sites, contact your EDR customer service representative.

Disclaimer Provided by Real Property Scan, Inc.

The information contained in this report has predominantly been obtained from publicly available sources produced by entities other than Real Property Scan. While reasonable steps have been taken to insure the accuracy of this report, Real Property Scan does not guarantee the accuracy of this report. Any liability on the part of Real Property Scan is strictly limited to a refund of the amount paid. No claim is made for the actual existence of toxins at any site. This report does not constitute a legal opinion.

BROWNFIELDS DATABASES

US BROWNFIELDS: A Listing of Brownfields Sites Source: Environmental Protection Agency

Telephone: 202-566-2777

Included in the listing are brownfields properties addresses by Cooperative Agreement Recipients and brownfields properties addressed by Targeted Brownfields Assessments. Targeted Brownfields Assessments-EPA's Targeted Brownfields Assessments (TBA) program is designed to help states, tribes, and municipalities—especially those without EPA Brownfields Assessment Demonstration Pilots—minimize the uncertainties of contamination often associated with brownfields. Under the TBA program, EPA provides funding and/or technical assistance for environmental assessments at brownfields sites throughout the country. Targeted Brownfields Assessments supplement and work with other efforts under EPA's Brownfields Initiative to promote cleanup and redevelopment of brownfields. Cooperative Agreement Recipients-States, political subdivisions, territories, and Indian tribes become BCRLF cooperative agreement recipients when they enter into BCRLF cooperative agreements with the U.S. EPA. EPA selects BCRLF cooperative agreement recipients based on a proposal and application process. BCRLF cooperative agreement recipients must use EPA funds provided through BCRLF cooperative agreement for specified brownfields-related cleanup activities.

Date of Government Version: N/A
Database Release Frequency: Semi-Annually

Date of Last EDR Contact: N/A
Date of Next Scheduled EDR Contact: N/A

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1999 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002 from the U.S. Fish and Wildlife Service.

STREET AND ADDRESS INFORMATION

© 2003 Geographic Data Technology, Inc., Rel. 07/2003. This product contains proprietary and confidential property of Geographic Data Technology, Inc. Unauthorized use, including copying for other than testing and standard backup procedures, of this product is expressly prohibited.



"Linking Technology with Tradition"

Sanborn® Map Report

Ship To: Sean McCuddy

Northern Environmental

647 Academy Drive

Northbrook, IL 60062

Customer Project:

05-3401-0381

1084233TWC

847-562-8577

Order Date: 8/25/2004 Completion Date: 8/27/2004

Inquiry #:

1257339.2s

P.O. #:

NA

Site Name: Motor City Motel

Address:

17355 Raupp Road

City/State: Melvindale, MI 48122

Cross Streets:

Based on client-supplied information, fire insurance maps for the following years were identified

1941 - 1 Map

1950 - 1 Map

1952 - 1 Map

1957 - 1 Map

1961 - 1 Map

1966 - 1 Map

Limited Permission to Photocopy

Total Maps: 6

Northern Environmental (the client) is permitted to make up to THREE photocopies of this Sanborn Map transmittal and each fire insurance map accompanying this report solely for the limited use of its customer. No one other than the client is authorized to make copies. Upon request made directly to an EDR Account Executive, the client may be permitted to make a limited number of additional photocopies. This permission is conditioned upon compliance by the client, its customer and their agents with EDR's copyright policy; a copy of which is available upon request.

This report contains information obtained from a variety of public and other sources. NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL EDR BE LIABLE TO ANYONE, WHETHER ASING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OR DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. It can not be concluded from this report that coverage information for the target and surrounding properties does not exist from other sources. Any analyses, estimates, ratings or risk codes provided in this report are provided for illustrative purposes only, and are not intended to provide, nor should they be naid for this report.

Any liability on the part of EDR is strictly limited to a refund of the amount naid for this report.

Copyright 2004 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc. or its affiliates, is prohibited without prior written permission. EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

Electronic Sanborn Map Images USER'S GUIDE

Thank you for your interest in electronic Sanborn Map images. The following are guidelines for accessing the images and for ransferring them to your system. If you have any questions about the use of electronic Sanborn Map images, contact your EDR account Executive at 1-800-352-0050.

Organization of Electronic Sanborn Image File

First Page

Sanborn Map Report, listing years of coverage

Second Page

Electronic Sanborn Map Images USER'S GUIDE

Third Page

Oldest Sanborn Map Image

Last Page

Most recent Sanborn Map Image

Navigating the Electronic Sanborn Image File

· Open file on screen.

Identify TP (Target Property) on the most recent map.

Find TP on older printed images.

Using Acrobat, zoom to 250% in order to view more clearly.

200-250% is the approximate equivalent scale of hardcopy Sanborn Maps.

Zooming in on an image:

- · On the menu bar, click "View" and then zoom.
- Use the magnifying tool and drag a box around the TP area.

Printing a Sanborn Map from the Electronic File

EDR recommends printing all images at 300 dpi (300 dpi prints faster than 600 dpi).

· To print only the TP area, cut and paste the area from Adobe Acrobat to your word processor.

Acrobat Version 4

- · Go to the Menu bar
- Press and hold the "T" button
- · Choose the Graphics Select Tool
- Draw a box around the area selected
- · Go to "Menu"
- · Hightlight "Edit"
- Hightlight "Copy"
- Go to a word processor such as Microsoft Word, paste and print.

Acrobat Version 5


- · Go to the Menu bar
- · Click the "Graphics Select Tool"
- · Draw a box around the area selected
- Go to "Menu"
- Highlight "Edit"
- Highlight "Copy"
- Go to a word processor such as Microsoft Word, paste and print.

mportant Information about Email Delivery of Electronic


Images are grouped intro one file, up to 2MB.

• In cases where in excess of 6-7 map years are available, the file size typically exceeds 2MB. In these cases, you will receive multiple files, labeled as 1 of 3, 2 of 3, etc. including all available map years.

Due to file size limitations, certain ISPs, including AOL, may occasionally delay or decline to deliver files. Please contact your ISP to identify their specific file size limitations.







The Sanborn Library, LLC


Copyrights 1941

The Sanborn Library, LLC

AMB

SOR Research or marke or in pilled the regard of the Sanborn Library, LLC may be prochanged unlined purer wringer.

Research or the first Sanborn Library, LLC may be prochanged unlined purer wringer.




Cog

The Sanborn Library, LLC

Year

EDR Research Associate

Serial any map of Try Sanctin Landy LLS may so perhapsed varying skip, junior





The Sanborn Library, LLC

Copyright 0,1952 The Sanborn Library, LLC AMB

ESH Research Associate

Reproduction on which is an pill of large 3 to 10 to to 10






The Sanborn Library, LLC

COpyright 1961
The Sanborn Library, LLC AMB
EER Reason Associate

Page declarate as what of an eart of any major of the Sanborn Lower, LLC may be strong us unrout place whether



- (1)


The Sanborn Library, LLC

Copyright® 1966 The Sanborn Library, LLC

EGR Resourch Assesses

Reproduction in white of in plin of any map of The Santoni Liotary, LLC may be provided written pronuncing permanent from the Santoni Library, LLC.

ATTACHMENT C
SITE PHOTOGRAPHS



north.

Picture 2. Office area of motel. Looking south.




Picture 3. Office area and motel front. Looking west.



Picture 7. Boiler room.



Picture 8. Cleaning chemicals in laundry room.



Picture 9. Dumpster at north end of parking lot.



Picture 10. Citgo gas station southeast of motel.



Picture 11. Pipe of unknown use located in grassy area between the west side of the motel and the gravel alley.



ATTACHMENT D

QUALIFICATIONS OF NORTHERN ENVIRONMENTAL PROFESSIONALS

Sean M. McCuddy

Geologist

Northern Environmental Technologies, Incorporated

EDUCATION

New Mexico Institute of Mining and Technology

Master of Science, Geology - 2003
 Albion College – Albion, Michigan

▲ Bachelor of Arts, Geological Sciences - 2000

Mr. McCuddy's college research and coursework includes:

- Microbiology and Molecular Biology
- ▲ Isotope Geochemistry
- ▲ Glacial Geology
- ▲ Geomorphology
- ▲ Structural Geology
- Sedimentation and Stratigraphy
- Environmental Science
- Mineralogy and Petrology

EXPERIENCE

2003 to Present:

Northern Environmental Technologies, Incorporated

2000 to 2003:

Microbiology Research Assistant, New Mexico

Summer 2001: 1999 to 2000:

Research Assistant, Dr. Thomas Kieft, South Africa Research Assistant, Geochemistry and Paleoclimatology,

Dr. Thomas Wilch, Albion College, Michigan

As a Geologist with Northern Environmental's Northbrook office, Mr. McCuddy's responsibilities include completing field assignments, data reduction and analysis, writing technical reports for clients and regulatory agencies, and correspondence and project coordination with clients, and regulatory agencies.

Mr. McCuddy's project experience includes:

- Leaking Underground Storage Tank (LUST) site investigation
- TACO analysis and Implementation
- Chlorinated solvent and petroleum contaminant characterization and remediation
- ASTM Phase I and transaction screen site assessments
- Analysis and interpretation of field data and laboratory results
- Performing field work including:
 - -Preparing site safety and health plans
 - -Borehole logging, screening and sampling
 - -Directing monitoring well installation
 - -Developing and sampling monitoring wells

CERTIFICATIONS A Health and Safety Training for Hazardous Waste Operations (40-Hour OSHA)

Bob C. Soni, PE

Director, Illinois Operations

Northern Environmental Technologies, Incorporated

EDUCATION

Roosevelt University, Chicago

Master of Business Administration (MBA) - 1977

Texas A & M University

Bachelor of Science, Chemical Engineering - 1971

Gujarat University, India

Bachelor of Science, Chemistry - 1968

EXPERIENCE

1998 to Present:

Northern Environmental Technologies, Incorporated

1994 to 1998:

Miller Engineers & Scientists

1990 to 1994:

Johnsonville Foods

1978 to 1990:

IBP, Incorporated

1971 to 1978:

Lindberg Heat Treating Company

As Northern Environmental's Director of Illinois Operations, Mr. Soni's responsibilities include overall technical and administrative direction of the Northbrook, Illinois office, as well as marketing and proposal preparation. He is responsible for managing the office and staff, as well as implementing and directing site investigations, interpretation of geologic and hydrogeologic data, design of remedial systems, and environmental projects for industries.

Mr. Soni's project experience includes:

- Preacquisition and Compliance auditing
- Industrial Environmental Compliance
- Process Design and modifications
- Planning, Development, Design and Installation of projects related to energy, environmental and processes
- Closure assessments and site investigations for numerous leaking underground storage tanks. Mr. Soni is experienced with gasoline, diesel, and waste oil remedial programs
- Site investigations and design of remedial systems, including soil excavation and disposal, and recovery and treatment of contaminated ground water and soil vapors
- Phase I and Phase II environmental site assessments. Responsibilities include data collection and interpretation of historical data

PROFESSIONAL

ORGANIZATIONS **m**

- American Institute of Chemical Engineers
- National Society of Professional Engineers
- Association of Facilities Engineering

CURRENT

REGISTRATION

- Registered Professional Engineer, State of Wisconsin, State of Illinois
- Certified Stormwater Manager, State of Wisconsin
- Certified Process Hazard Analysis (PHA) Leader Training